

NATIONAL ORGANIZATION
SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.
- Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial

☐ Monument *with* Sculpture ☐ Monument with *Cannon*
☐ Monument *without* Sculpture ☒ Historical Marker ☐ Plaque

Affiliation

☐ G.A.R. (Post Name & No. _____) ☐ M.O.L.L.U.S.
☐ W.R.C. (Corps Name & No. _____) ☐ Other Allied Order
☐ SUVCW (Camp Name & No. _____) (Please describe below)
☐ DUVCW (Tent Name & No. _____)
☒ Other: PEA RIDGE MEMORIAL ASSOCIATION

Original Dedication Date 1962 Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

Location

The Memorial is *currently* located at:

Street/Road address or site location Hwy DD at Arkansas State Line N36°29.921 W94°01.455
 City/Village Seligmann Township _____ County Barry

The front of the Memorial faces: ☐ North ☐ South ☐ East ☒ West

Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)...

Name Pea Ridge Memorial Association Dept./Div. _____
 Street Address Or Pea Ridge National Battlefield
 City _____ State _____ Zip Code _____
 Contact Person _____ Telephone () _____

If the Memorial has been moved, please list former location(s)...

N/A

Physical Details

Material of Monument or base under a Sculpture or Cannon = ☐ Stone ☐ Concrete ☒ Metal ☐ Undetermined
 If known, name specific material (color of granite, marble, etc.) _____

Material of the Sculpture = ☐ Stone ☐ Concrete ☐ Metal ☐ Undetermined
 If known, name specific material (color of granite, marble, etc.) _____
 If the Sculpture is of metal, is it solid cast or "hollow?" _____

Material of Plaque or Historical Marker / Tablet = _____

Material of Cannon = ☐ Bronze ☐ Iron - Consult known Ordnance Listing to confirm
 Markings on muzzle = _____
 Markings on Left Trunion _____ Right Trunion _____
 Is inert ammunition a part of the Memorial? ☐ If so, describe _____

Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points
 Monument or Base: Height ^{6 1/2 feet} _____ Width ^{30 inches} _____ Depth ^{6 inches} _____ or Diameter _____
 Sculpture: Height _____ Width _____ Depth _____ or Diameter _____

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture)
 Maker or Fabricator mark / name? If so, give name & location found _____

The "Dedication Text" is formed: ☐ cut into material ☒ raised up from material face

Record the text (indicate any separation if on different sides...) Please use additional sheet if necessary.
 Pea Ridge Memorial Association Logo with crossed US and Confederate Flags

POTTS' HILL

On the Arkansas - Missouri line where the Telegraph Road entered ten-mile long Cross Timber Hollow,
 on February 16, 1862, occurred the first skirmish on Benton County soil. Brig. Gen. Curtis' Federal army
 overtook the rear guard of Maj. Gen. Price as he retreated southward. This marked the beginning of the
 Pea Ridge Campaign.

T862 Centennial Observance 1962

Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

Type of Location

☐ Cemetery	☐ Park	☐ Plaza/Courtyard
☐ "Town Square"	☐ Post Office	☐ School
☐ Municipal Building	☐ State Capitol	Other: _____
☐ Courthouse	☐ College Campus	county road _____
☐ Traffic Circle	☐ Library	_____

General Vicinity

☒ Rural (low population, open land) ☐ Suburban (residential, near city)
☐ Town ☐ Urban / Metropolitan

Immediate Locale (check as many as may apply)

☐ Industrial ☐ Commercial
☒ Street/Roadside within 20 feet ☒ Tree Covered (overhanging branches)
☐ Protected from the elements (canopy or enclosure, indoors)
☐ Protected from the public (fence or other barrier)
 Any other significant environmental factor _____

Condition Information**Structural Condition** (check as many as may apply)

The following section applies to Monuments *with* Sculpture, and Monuments without _____ Sculpture - including the base for Monuments with Cannon. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

Sculpture**Base**

If hollow, is the internal support unstable/exposed?
 (look for signs of exterior rust)

Any evidence of structural instability?

(look for cracked joints, missing mortar or caulking or plant growth)

Any broken or missing parts?

(look for elements (i.e., sword, musket, hands, arms, etc. - missing due to vandalism, fluctuating weather conditions, etc.)

Any cracks, splits, breaks or holes?

(also look for signs of uneven stress & weakness in the material)

Surface Appearance (check as many as may apply)**Sculpture****Base**

Black crusting

White crusting

Etched, pitted, or otherwise corroded (on metal)

Metallic staining (run-off from copper, iron, etc.)

Organic growth (moss, algae, lichen or vines)

Chalky or powdery stone

Granular eroding of stone

Spalling of stone (surface splitting off)

Droppings (bird, animal, insect remains)

Other (e.g., spray paint graffiti) - Please describe...

good shape

Does water collect in recessed areas of the Memorial? ☐ Yes ☒ No ☐ Unable to tell

Surface CoatingDoes there appear to be a coating? ☐ Yes ☒ No ☐ Unable to determine

If known, identify type of coating.

☐ Gilded ☐ Painted ☐ Varnished ☐ Waxed ☐ Unable to determineIs the coating in good condition? ☐ Yes ☐ No ☐ Unable to determine**Basic Surface Condition Assessment** (check one)

In your opinion, what is the general appearance or condition of the Memorial?

☐ Well maintained ☐ Would benefit from treatment ☐ In urgent need of treatment ☐ Unable to determine**Overall Description**

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) .

Rustoleum paint would be a help, but overall in good shape

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector IdentificationDate of On-site Survey 03/10/2009Your Name Walt Busch US Grant Camp 68Address PO Box 381 City ArcadiaState MO Zip Code 63621 Telephone (314) 630-8407

Please send this completed form to:

Kevin P. Tucker, PDC, Chair

58 Forest Street

Wakefield, MA 01880

(617) 595-7721

Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR
National Civil War Memorials Committee





POTTS' HILL

On the Arkansas-Missouri line where the Telegraph Road entered ten-mile long Cross Timber Hollow, on February 16, 1862, occurred the first skirmish on Benton County soil. Brig. Gen. Curtis' Federal army overtook the rear guard of Maj. Gen. Price as he retreated southward. This marked the beginning of the Pea Ridge Campaign.

1862 CENTENNIAL OBSERVANCE 1962