NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

P	1	F	Δ	C	C	
	_		m	•		_

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.

 Include a photograph of each viewable side and label it with name & direction of view. Thank You.
Type of Memorial
Monument with SculptureMonument with Cannon Monument without Sculpture Mistorical Marker Plaque
Affiliation
Original Dedication Date November 5, 1989 Please consult any/all newspaper archives for a local paper's article that would have information on the first dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you. From records of the Williamson County Historical Society There was no newspaper Location. The Memorial is currently located at: Street/Road address or site location Pinkerton Park - Hwy. 96 East City/Village Franklin Township County Williamson, TN The front of the Memorial faces: X North X South East West
Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in) Name City of Franklin Dept./Div. Parks Dept. Street Address City Hall City Franklin State TN Zip Code 37064 Contact Person Lisa Clayton, Parks Director Telephone (615) 794-2103 If the Memorial has been moved, please list former location(s)
Physical Details Material of Monument or base under a Sculpture or Cannon =Stone Concrete Metal Undetermined If known, name specific material (color of granite, marble, etc.)

Material of the Sculpture =StoneConcreteMetalUndetermined If known, name specific material (color of granite, marble, etc.)If the Sculpture is of metal, is it solid cast or "hollow?"
Material of Plaque or Historical Marker / Tablet = <u>Aluminum</u>
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle =
Markings on muzzle =
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height Width Depth or Diameter Sculpture: Height Width Depth or Diameter
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!
Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found
The "Dedication Text" is formed: cut into material _X raised up from material face
Record the text (indicate any separation if on different sides) Please use additional sheet if necessary. FORT GRANGER
In the spring of 1863 (See attachment)
Environmental Setting (The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)
Type of Location Cemetery Park Post Office School Municipal Building Courthouse Traffic Circle Library Plaza/Courtyard Courtyard Cour

	uburban (residential, near rban / Metropolitan	city)
Condition Information)
Structural Condition (check as many as may apply) The following section applies to Monuments with Sculpture including the base for Monuments with Cannon. Instability in the by a number of factors. Indicators may be obvious or subtle. base.	sculpture and its base can be	detected
	Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	(Americana)	-
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth)		
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc missing due to vandalism, fluctuating weather conditions, etc.)		—
Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)		
Surface Appearance (check as many as may apply) Black crusting White crusting Etched, pitted, or otherwise corroded (on metal) Metallic staining (run-off from copper, iron, etc.) Organic growth (moss, algae, lichen or vines) Chalky or powdery stone	Sculpture	Base
Granular eroding of stone Spalling of stone (surface splitting off) Droppings (bird, animal, insect remains) Other (e.g., spray paint graffiti) - Please describe		_
Does water collect in recessed areas of the Memorial?	Yes No Unab	le to tell

Surface Coating Does there appear to be a coating? Yes No Unable to determine If known, identify type of coating. Gilded Painted Varnished Waxed Unable to determine Is the coating in good condition? Yes No Unable to determine
Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or condition of the Memorial? Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). Very good condition
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you. Inspector Identification Date of On-site Survey April 2, 2005 Your Name Sam Gant Address 580 Jordan Rd, City Frankling State TN Zip Code 37067 Telephone
Please send this completed form to:
Todd A. Shillington, PCC
Thank you for your help, and attention to detail.
Sons of Union Veterans of the Civil War National Civil War Memorials Committee

FORT GRANGER

In the spring of 1863, Federal forces commanded by Gen. Gordon Granger occupied Franklin. Construction of major Fortifications began under the direction of Capt. W.E. Merrill, U.S. Corps of Engineers, the largest of them being placed on Figuers Bluff, .2 of a mile north on the Harpeth River. Fort Granger commanded the southern and northern approaches to Franklin and was adjacent to the critically important Tenn. & Ala. Railroad bridge. The artillery within the fort saw action twice in 1863 against Confederate cavalry forces. During the Battle of Franklin, Nov. 30, 1864, the site served as Hqtrs. Of Maj. Gen. John M. Schofield (commander of U.S. forces) and as an active artillery position.

WILLIAMSON COUNTY HISTORICAL SOCIETY, 1989











