NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

 PLEASE: Type or print, using a ball-point pen, when filling out this form. Legibility is critical. Do not guess at the information. An answer of, "Unknown," is more helpful. Include a photograph of each viewable side and label it with name & direction of view. Thank You. 		
Type of Memorial		
Monument with Sculpture Monument with Cannon Historical Marker Plaque		
Affiliation		
_X G.A.R. (Post Name & No. Malvern Hill Post #131) M.O.L.L.U.S.		
W.R.C. (Corps Name & No)Other Allied Orde		
SUVCW (Camp Name & No) (Please describe below) X DUVCW (Tent Name & No. Julia Ward Howe Tent No. #7)		
Other:		
Original Dedication Date May 30, 1922 in the A.M. Please consult any/all newspaper archives for a local paper's article that would have information on the <i>first</i> dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you. Location The Memorial is <i>currently</i> located at: Anaheim Cemetery		
Street/Road address or site location 1400 E. Sycamore St.		
City/Village Anaheim 92805 Township California County Orange		
The front of the Memorial faces:X North South East West		
Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in) Name Orange County Cemetery District Dept./Div Street Address 25751 Trabuco Road		
City Lake Forest State CA Zip Code 92630-4348		
Contact Person Sam Randall Telephone (949) 951-9102		
If the Memorial has been moved, please list former location(s)		

Material of Monument or base under a Sculpture or Cannon = ___Stone____ Concrete ___ Metal __X Undetermined


If known, name specific material (color of granite, marble, etc.)

Physical Details

Material of the Sculpture =StoneConcreteMetalUndetermined If known, name specific material (color of granite, marble, etc.)If the Sculpture is of metal, is it solid cast or "hollow?"
Material of Plaque or Historical Marker / Tablet = None
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle = Right Trunion Right Trunion Is inert ammunition a part of the Memorial? If so, describe
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height Abt. 6' Width Abt. 18" Depth or Diameter Sculpture: Height Width Depth or Diameter
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!
Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found
The "Dedication Text" is formed: X cut into material raised up from material face Record the text (indicate any separation if on different sides) Please use additional sheet if necessary. North facing side: TO THE ABSENT AND UNKNOWN DEAD OF ALL WARS 1922 South facing side: ERECTED BY DAUGHTERS OF VETERANS TENT NO. 7 East facing side: U.S.A.
Environmental Setting (The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)
Type of Location X Cemetery

General Vicinity Rural (low population, open land) Town	Suburban (residential, nea X Urban / Metropolitan	ır city)	
Immediate Locale (check as many as may as Industrial Industrial Street/Roadside within 20 feet Protected from the elements (canopy or e Protected from the public (fence or other Any other significant environmental factor	Commercial Tree Covered (overhanging enclosure, indoors) barrier)		
Condition Information		-	
Structural Condition (check as many as may apply) The following section applies to Monuments with Sculpture, and Monuments without Sculpture - including the base for Monuments with Cannon. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.			
	Sculpture	Base	
If hollow, is the internal support unstable/exposed	?	No	
(look for signs of exterior rust) Any evidence of structural instability?	and reserve the N	No	
(look for cracked joints, missing mortar or caulking or pla Any broken or missing parts?		Maybe	
(look for elements (i.e., sword, musket, hands, arms, etc. due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the results)		No	
Surface Appearance (check as many as ma			
Black crusting	Sculpture	Base	
White crusting	_		
Etched, pitted, or otherwise corroded (on met Metallic staining (run-off from copper, iron, et			
Organic growth (moss, algae, lichen or vines)	200 O.T.)		
Chalky or powdery stone		8	
Granular eroding of stone Spalling of stone (surface splitting off)			
Droppings (bird, animal, insect remains)	ovile a	Yes	
Other (e.g., spray paint graffiti) - Please described top of the Monument appears that an otime. Now there is just a shallow hole may be and the sides of the monument.	bject may have been placed the		
Does water collect in recessed areas of the Memorial? Yes X No Unable to tell			

Surface Coating
Does there appear to be a coating? Yes NoX Unable to determine
If known, identify type of coating
Gilded Painted Varnished Waxed Unable to determine Is the coating in good condition? Yes No Unable to determine
Is the coating in good condition? Yes No Unable to determine
Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or condition of the Memorial? Well maintained X Would benefit from treatment In urgent need of treatment Unable to determine
TOURS SOCIONALIZATION OF THE PROPERTY SOCIETA OF THE PROPERTY SOCIETATION
Overall Description Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). Possible some type of drainage holes on the East and West sides of the monument. They are about 1 foot from the ground. Maybe to drain from the top? The top hole is 1-inch deep, maybe plugged up with trash? Also drain holes are plugged up with trash. The metal drain pipes have interior threads located at the ends of the pipe.
I am unable to get a copy of the newspaper article on microfilm for the time period that this monument was dedicated on May 30, 1922 in the A.M. The microfilm for that time period was unavailable at the Anaheim Public Library. I was able to get a copy of the adjacent city's newspaper (Fullerton News) article with a small note about the dedication.
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described
Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.
Inspector Identification
Date of On-site Survey April 14, 2001
Your Name Charles Beal
Sgt. William Pittenger Camp 21, Dept. of California & Pacific
Disease and this completed form to:
Please send this completed form to:
Thank you for your help, and attention to detail.
Sons of Union Veterans of the Civil War National Civil War Memorials Committee





Anaheim Cemetery Anaheim, California Looking Westerly at Monument