9CA5 PAGE 1 OF 5

NATIONAL ORGANIZATION

# SONS OF UNION VETERANS OF THE CIVIL WAR

# **CIVIL WAR MEMORIAL ASSESSMENT FORM**

#### PLEASE:

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful. .
- Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

## Type of Memorial

Monument with Sculpture	Monument with Cannon		
X Monument without Sculpture	Historical MarkerX Plaque		

## Affiliation

X G.A.R. (Post Name & No. Malvern Hill Post #131	) M.O.L.L.U.S.
X W.R.C. (Corps Name & No. #131	) _X Other Allied Order
SUVCW (Camp Name & No	) (Please describe below)
X DUVCW ( Julia Ward Howe Tent No. 7	) See attached Shee
Other:	.0

Original Dedication Date May 30, 1922 in the P.M. Please consult any/all newspaper archives for a local paper's article that would have information on the first dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

### Location

The Memorial is	currently located a	t: Loma Vista	a Memorial Pa	ark			
Street/Road add	ress or site location	n 701 E. Ba	stanchury Roa	ad			
City/Village Full	erton Township	California	County O	range			
The front of the	Memorial faces:	North	South	East	X West		
Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)							
Name Loma Vis	sta Memorial Park		Dept./Div				
Street Address	701 E. Bastanchur	y Road					
City Fullerton	State C	A Zip Co	de 92835				
Contact Person	Sharon Adams		Telephone (7	14) 525-1575			

If the Memorial has been moved, please list former location(s)...

Sharon Adams mentioned that the monument was near the old entrance to the cemetery, which was located on the East Side of the cemetery. The monument was moved to its present location about 1933, across from the Mausoleum that was built in 1933. The current entrance is from (North Side of cemetery) Bastanchury Road.

## Physical Details

Material of Monument or base under a Sculpture or Cannon = X Stone Concrete Metal Undetermined If known, name specific material (color of granite, marble, etc.)

#### **General Vicinity**

- Rural (low population, open land)
- Town

X Suburban (residential, near city) Urban / Metropolitan

#### Immediate Locale (check as many as may apply)

- Industrial Commercial Street/Roadside within 20 feet Tree Covered (overhanging branches)
- Protected from the elements (canopy or enclosure, indoors)
- Protected from the public (fence or other barrier) Any other significant environmental factor

# **Condition Information**

#### Structural Condition (check as many as may apply)

The following section applies to Monuments with Sculpture, and Monuments without Sculpture - including the base for Monuments with Cannon. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	No	No
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth)	No	No
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc missing due to vandalism, fluctuating weather conditions, etc.)	No	No
Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)	No	No
Surface Appearance (check as many as may apply)	Sculpture	Base
Black crusting		
White crusting		
Etched, pitted, or otherwise corroded (on metal)	<u></u>	· · · · · ·
Metallic staining (run-off from copper, iron, etc.)		
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone		
Granular eroding of stone		<u> </u>
Spalling of stone (surface splitting off)		
Droppings (bird, animal, insect remains) Other (e.g., spray paint graffiti) - Please describe	<u></u>	·
Does water collect in recessed areas of the Memorial?	YesX No	Unable to tell

SUVCW -- CIVIL WAR MEMORIAL ASSESSMENT FORM (CWM #61)

#### Surface Coating

Does there appear to be a coating? \_\_\_\_Yes \_\_\_No \_\_\_X Unable to determine If known, identify type of coating. \_\_\_\_Gilded \_\_\_Painted \_\_\_Varnished \_\_\_\_Waxed \_\_\_\_Unable to determine Is the coating in good condition? Yes \_\_\_\_No \_\_\_Unable to determine

#### Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?

\_\_\_\_ Well maintained X Would benefit from treatment \_\_\_\_ In urgent need of treatment \_\_\_\_ Unable to determine

### **Overall Description**

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) .

## Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

# Inspector Identification


Date of On-site Survey April 14, 2001 Your Name Charles Beal

Sgt. William Pittenger Camp 21, Dept. of California & Pacific


Please send this completed form to:

Thank you for your help, and attention to detail.


SONS OF UNION VETERANS OF THE CIVIL WAR National Civil War Memorials Committee



Loma Vista Cemetery Fullerton, California Looking Easterly at Monument



Loma Vista Cemetery Fullerton, California Looking Easterly at Monument



Loma Vista Cemetery Fullerton, California Looking Northerly at Monument