# NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL ASSESSMENT FORM

# Type of Memorial (check all applicable)

<u>V</u> Monument <u>V</u> with Sculpture without Sculpture with Cannon standalone Cannon Historical Marker <u>V</u> Plaque Other (flag pole, G.A.R. buildings, stained glass windows, etc.)

# Affiliation

GAR	MOLLUS	~	SUVCW	WRC	ASUVCW
LGAR	DUVCW		Other		

If known, record name and number of post, camp, corps, auxiliary, tent, circle or appropriate information of other groups:

**Original Dedication Date** September 25, 1908 Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

#### Location

The Memorial is *currently* located at:

Street/Road address or site location Mt. Hope Cemetery 1133 Mt. Hope Ave.

	GPS Coordinates 43 N -78 W	
City/Village &/or Township Rochester		
County Monroe	State NY	_ Zip Code <u>14620</u>
The front of the Memorial faces: 🖌 North _	South East West	
Government Body, Agency, or Individual	Owner	
Name City of Rochester, NY		
Dept./Div. Cemetery		
Street Address 1133 Mt. Hope Ave.		
City Rochester	_ State <u>NY</u> Z	ip Code 14620
Contact Person patricia Corcoran	Telephone (585) 704-4675	ext
Is Memorial on the National Register of Histo	ric PlacesYes _ <b>∽_</b> No ID	# if known
For Monuments with/without sculpture: Physical Details Material of Monument or base under a Sculpture or Ca If known, name specific material (color of granite, mar		_MetalOther
Material of the SculptureStone Concrete	eMetal <u>&lt;</u> Other Is it hollo	ow or solid? Hollow

If known, name specific material (color of granite, marble, etc.) Bronze

>This form may be photocopied.<

©2007-2015 Sons of Union Veterans of the Civil War, a Corporation

# For Historic Marker or Plaque:

Material of Plaque or Historical Marker / Tablet = <u>The Bivouac of the Dead on Monument</u>.

### For Cannons with/without monument:

Material of C	annon = Bronze	eIron Type of Ca	nnon (if known)			
Markings: M Left Trunion	uzzle	morial? Yes	Base Ring/Breech Right Trunion No	Rifled		
			 list of known ordnance]			
	-		stained glass windows, et			
	describes the memori	Denotes the Union Soldier	•	,		
Materials o	f the Memorial					
-	te for All Memor ate Dimensions (in		• taken from tallest / widest	points		
18'-4"	Height	Width <u>9'-10"</u>	Depth or	Diameter		
and attach to Markings/ Maker or Fa Please attac narrative she	this form. Please describe / <b>Inscriptions</b> (on sto bricator mark / name? I	e the "pose" of each statue separated from th ne-work / metal-work of f so, give name & locatio	tion on a separate sheet of pa and any weapons/implements is form). Thank you! monument, base, sculpture Sculpture name at eas Farnham. Fabriactor n BRONZE WORKS NY e text in the space below.	involved (in case ) st side base below fo name at south side/re	your photos ot: Sally Jame ar base: ROM	become es IAN
ON FAME'S E THEIR SILEN AND GLORY ( THE BIVOUA(	TERNAL CAMPING GRO T TENTS ARE SPREAD, GUARDS WITH SOLEMN C OF THE DEAD.		s marks.			

### Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

Type of Location └ Cemetery School Traffic Circle		Plaza/Courtyard State Capitol Other:	"Town Square" Courthouse	Post Office College Campus
General Vicinity	ation, open land)Su	burban (residential, nea	r city) Town 🔽 l	Jrban / Metropolitan
Industrial	<b>le</b> (check as many as may Commercial Str the elements (canopy or e	reet/Roadside within 20		
Any other significant	environmental factor			
To de	etail the condition of a mon	ument used the addend	um form for <i>Monument</i>	's Condition]

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment.

Addendums attached to this electronic file are the *Monument's Condition* and the *Narrative* forms. Only the *Monument's Condition* form is required if you are requesting grant money using form CWM-62 SUVCW Memorial Grant Application Form and Instructions.

Thank you.

No

Inspector Identification	Date of On-site Survey	March 2, 2021	
Your Name Peter Ellison			
Address 226 Mason Street			
City Canandaigua	State NY	Zip Code 14424	
Telephone			
Are you a member of the Allied C	Orders of the G.A.R.? If	so, which one?	

Please send this completed form to:

Walt Busch, PDC, Chair 1240 Konert Valley Dr. Fenton, MO 63026

Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War – Civil War Memorials Committee.

### SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL ASSESSMENT FORM ADDENDUM – MONUMENT'S CONDITION

Completion of this form is required when requesting grant money using form CWM-62 SUVCW Memorial Grant Application Form and Instructions.

### **Condition Information**

#### Structural Condition (check as many as may apply)

The following section applies to <u>Monuments with Sculpture</u>, and <u>Monuments without Sculpture</u> including the base for <u>Monuments with Cannon</u>. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If hollow, is the internal support unstable/exposed? (Look for signs of exterior rust)		
Any evidence of structural instability? (Look for cracked joints, missing mortar or caulking or plant growth)		
Any broken or missing parts? (Look for elements (i.e., sword, musket, hands, arms, etc missing		
due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes? (Also look for signs of uneven stress & weakness in the material)		
Surface Appearance (check as many as may apply)	0	Deer
Black crusting	Sculpture	Base
White crusting	<u> </u>	
Etched, pitted, or otherwise corroded (on metal)	<u> </u>	
Metallic staining (run-off from copper, iron, etc.)		<ul> <li>✓</li> </ul>
Organic growth (moss, algae, lichen or vines)		<u> </u>
Chalky or powdery stone		
Granular eroding of stone		
Spalling of stone (surface splitting off) Droppings (bird, animal, insect remains)		
Other (e.g., spray paint graffiti) - Please describe		

Does water collect in recessed areas of the Memorial? <u>Yes</u> No Unable to tell

## Surface Coating

Does there appear to be a coating? <u>Yes</u> No Unable If known, identify type of coating.	e to determine
Gilded Painted Varnished Yaxed Is the coating in good condition? Yes You No Duable to determ	
Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or condition of the Me Well maintained Would benefit from treatment In urg	
Briefly describe the Memorial (affiliation / overall condition & any conc Bronze has some patination (especially on weathering surfaces such as flag & shoulders) an attached report.	• •
Inspector's Name Peter Ellison	Date March 3, 2021

### SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL ASSESSMENT FORM ADDENDUM – NARRATIVE

[Generally used to record the text of monuments, but may be used for any other useful information, such as if the monument has been moved or if you have information about the day of dedication. May repeat use of page as often as necessary.]

The Memorial is *currently* located at: Street/Road address or site location Mt. Hope Cemetery 1133 Mt. Hope Ave.

GPS Coordinates 43 N -78 W

City/Village and/or Township Rochester County Monroe

State NY

Zip Code 14620

TEXT

Sally James Farnham was an American sculptor and the daughter of Colonel Edward C. James, a Civil War veteran who served with the NY 106th Infantry Regiment. Farnham produce a series of United States Civil War and cemetery monuments in New York and New Jersey. Farnham fabricated the Civil War monument, Defenders of the Flag,for Mt. Hope Cemetery in 1908.

FORM CWM #61

# **Physical Details**

Material of Monument or base under a Sculpture or Cannon = XX\_Stone \_\_\_ Concrete XX\_Metal \_\_\_ Undetermined If known, name specific material (color of granite, marble, etc.) Beige

#### SUVCW -- CIVIL WAR

Material of the Sculpture = <u>xx</u> Stone <u>Concrete</u> <u>xx</u> Metal <u>Undetermined</u> If known, name specific material (color of granite, marble, etc.) Bronze, granite base If the Sculpture is of metal, is it solid cast or "hollow?" Solid Cast

Material of Plaque or Historical Marker / Tablet = Bronze

Material of Cannon = \_\_\_Bronze \_\_\_Iron - Consult known Ordnance Listing to confirm 

 Markings on muzzle = \_\_\_\_\_\_
 Right Trunion \_\_\_\_\_\_

 Markings on Left Trunion \_\_\_\_\_\_
 Right Trunion \_\_\_\_\_\_

 Is inert ammunition a part of the Memorial? \_\_\_\_\_\_
 If so, describe \_\_\_\_\_\_

 Markings on muzzle =

Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height Six Ft Width Six Ft Depth \_\_\_\_\_ or Diameter \_\_\_\_\_ Sculpture: Height Seven Ft Width Four Feet Depth \_\_\_\_\_ or Diameter \_\_\_\_\_

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found The Music of Taps is on the bronze tablet.

The "Dedication Text" is formed: \_\_\_\_ cut into material x raised up from material face

Record the text (indicate any separation if on different sides) Please use additional sheet if necessary. Text is the musical notes of Taps

## Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.) Type of Location

- XX Cemeterv
- "Town Square"
- Municipal Building Courthouse
- - Traffic Circle

Park Post Office State Capitol College Campus Library

Plaza/Courtyard
School
Other:

>This form may be photocopied.<

©2007-2011 Sons of Union Veterans of the Civil War, a Corporation.

FORM CWM #61

#### **General Vicinity**

\_\_\_ Rural (low population, open land)

\_\_\_\_ Town

\_\_\_\_ Suburban (residential, near city) \_\_\_\_ Urban / Metropolitan

Immediate Locale (check as many as may apply)

\_\_ Industrial <u>××</u>\_ Commercial

<u>xx</u> Street/Roadside within 20 feet <u>xx</u> Tree Covered (overhanging branches) Protected from the elements (canopy or enclosure, indoors)

× Protected from the public (fence or other barrier)

Any other significant environmental factor Tree canopy over monument is badly in need of trimming.

### **Condition Information**

#### Structural Condition (check as many as may apply)

The following section applies to Monuments *with* Sculpture, and Monuments without Sculpture - including the base for Monuments with *Cannon*. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If hollow, is the internal support unstable/exposed? (Look for signs of exterior rust)		
Any evidence of structural instability? (Look for cracked joints, missing mortar or caulking or plant growth)		
Any broken or missing parts? (Look for elements (i.e., sword, musket, hands, arms, etc missing		
due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes? (Also look for signs of uneven stress & weakness in the material)		<u></u>

#### Surface Appearance (check as many as may apply)

	Sculpture	Base
Black crusting	XX	xx
White crusting	•	
Etched, pitted, or otherwise corroded (on metal)	XX	
Metallic staining (run-off from copper, iron, etc.)	XX	XX
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone		
Granular eroding of stone		XX
Spalling of stone (surface splitting off)		XX XX
Droppings (bird, animal, insect remains)	XX	
Other (e.g., spray paint graffiti) - Please describe		
The sculpture was restored some years ago by an unqualified craftsman. A coating of pulv	erized bronze powder was applied	d, and quickly

deteriorated. The craftsman cut notches in the top of the granite base to drain materials as they worked and the granite base is discolored.

Does water collect in recessed areas of the Memorial? \_\_\_ Yes XX\_ No \_\_\_ Unable to tell

Page 3 of 4

FORM CWM #61

#### Surface Coating

Does there appear to be a coating? <u>xx</u> Yes <u>No</u> Unable to determine If known, identify type of coating.

\_\_\_\_\_Gilded \_\_\_\_ Painted XXa Varnished \_\_\_\_ Waxed \_\_\_\_ Unable to determine Is the coating in good condition? Yes XX No Unable to determine

#### Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial? \_\_\_\_ Well maintained \_\_\_\_ Would benefit from treatment XX\_ In urgent need of treatment \_\_\_\_ Unable to determine

# **Overall Description**

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). The monument dates from 1908, designed by Sally James Farnham, daughter of a NY Hero Colonel Edward James Farnham. The piece portrays two soldiers defending the colors and a brass plaque in the granite base with the musical notes from Taps. The Bill of Sale for the cemetery section indicates the sale was made to the GAR. The City of Rochester owns and administers the cemetery. A coating of pulverized bronze powder was applied by an unqualified individual which quickly deteriorated and threatened not only the bronze statue but the granite base as well grooves were cut into the base to drain the discolored run off from the statue and has discolored the granite base.

# Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

### Inspector Identification

Date of On-site Survey 5 November 2015 Your Name William S. Poulton, PCC	- ughen
Address 31 Justinshire Drive	City Henrietta
State NY Zip Code 14467	Telephone (
What Order or Organization is submitter	a member of? Abraham Lincoln Camp #6, NY Dept, SUVCW

Please send this completed form to

Walt Busch, PDC, Chair



Thank you for your help, and attention to detail. SONS OF UNION V

CIVIL WAR VETERANS OF THE National Civil War Memorials Committee

>This form may be photocopied.<

#### SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL FUND REQUEST (FORM CWM #62)

#### REQUESTOR INFORMATION

(Please print or type)

CAMP AND DEPARTMENT NAME: Abraham Lincoln Camp #6 NY Department C/O 31 Justinshire Drive

ADDRESS:

CITY:	Henrietta		
STATE:	New York ZIP CODE: 14467		
NAME OF C	ONTACT PERSON: William S	. Poulton, PhD, PCC	
ADDRESS:			
	31 Justinshire Drive		
CITY:	Henrietta		
STATE:	New York	ZIP CODE: 14467	
PHONE(S):			

## MEMORIAL OR MONUMENT INFORMATION

NAME OF MEMORIAL: Defenders of the Flag

LOCATION: (Name and address of cemetery or other location description, such as, comer of 3<sup>rd</sup> and Lincoln Street)... Grand Army of the Republic section, Mount Hope Cemetery, 1133 Mount Hope Avenue, Rochester, NY 14620

WHEN WAS IT BUILT: 1908 by Sally Farnham

WHO OWNS IT: The Monument is a central part of the GAR section of Mount Hope.

According to information available to the Camp, the bill of sale of the section indicates GAR ownership.

CWM Form 62 - April 2011

Page 2

WHO IS FINANCIALLY RESPONSIBLE FOR IT: Mount Hope Cemetery, City of Rochester

ARE MATCHING FUNDS AVAILABLE? Yes FROM WHERE: Friends of Mount Hope Cemetery

ARE OTHER SOURCES OF FUNDS AVAILABLE? Yes FROM WHERE: Private Donations

AMOUNT BEING REQUESTED: \$1000.00

WAS A GRANT PREVIOUSLY RECEIVED FOR THIS PROJECT? NO

DATE RECEIVED

TOTAL COST OF RESTORATION PROJECT: \$15,000.000

DESCRIBE WORK THE FUNDS ARE NEEDED FOR (Be specific, use continuation sheet, if necessary)

At some time in the past, the surface of the monument (which sets upon a large block of coarse finished granite)

AMOUNT (\$)

and the plaque on the granite base were coated with pulverized bronze powder sometimes

referred to as "radiator paint". The coating was likely to have made the metal appear metalic-gold

but over the years has oxidized severely to brown-green. It will cause severe surface pitting to the bronze.

The scope of work includes the removal of the pulverized bronze powder and refinishing of the memorial

surface patination and with Incralac metal conservation lacquer

WHO EVALUATED THE NEED FOR THE WORK, AND WHAT ARE THEIR QUALIFICATIONS? Ellion Conservation, 226 Mason Street, Canandaigua, NY 14424

WHO WILL DO THE DESCRIBED WORK, AND WHAT ARE THEIR QUALIFICATIONS: Building Arts and Conservation, 206 South Ann Arbor St, Saline, MI 48176

WHO WILL RECEIVE THE FUNDS, IF GRANTED? (if other than requestor, provide complete mailing address)

FRIENDS OF MOUNT HUDE CEMETERY. 1133 MOUNT HOLE AVE. ROCHOITOR, NY 14620 William S. Poulton, PhD, PCC

FORM PREPARED BY:

ADDRESS:

31 Justinshire Drive

Henrietta, NY 14467

SIGNATURE:

CITY, STATE, ZIP:

Mynn

CWM Form 62 - April 2011

Page 3



Dr. William S. Poulton, Jr., PhD Past Camp Commander Abraham Lincoln Camp #6 Sons of Union Veterans of the Civil War 31 Justinshire Drive Henrietta, New York 14467



5 November 2015

Don Martin, PDC 6025 State Route 772 Chillicothe, Ohio 45601

Brother Martin,

The Members of Lincoln Camp request assistance from the Memorial/Monument Grant Fund for the restoration of the monument "Defenders of the Flag" in the GAR section (Section BB) of Rochester's Mount Hope Cemetery.

The Bill of sale of the section and plots indicates the sale of the section and the plots therein was made to the GAR. The City of Rochester owns, administers and maintains Mount Hope Cemetery.

The monument dates from 1908, designed by Sally James Farnham, the daughter of a New York Hero, Colonel Edward James. The piece Portrays two soldiers defending the colors and a plaque with the music from "Taps" on a granite base.

A few years ago, without consulting the Friends of mount Hope Cemetery of the heirs of the GAR (the SUVCW), the Mount Hope administration contracted for work on the monument by a local artist.

A coating of pulverized bronze powder was applied, which quickly deteriorated and threatened not only the bronze statue and plaque but the granite base as well. Grooves were cut into the base to drain the discolored run off from the statue. The granite base is discolored. Serious



Sally James Farnham

restoration efforts are needed to keep the monument from deteriorating.

After an exhausting search, Ellion Conservation of Canandaigua, New York and Building Arts and Conservation of Saline, Michigan was selected by the Friends of Mount Hope Cemetery to perform the conservation of the monument.

Lincoln Camp is a member of the Friends of Mount Hope.

The scope of work includes:

Examination and archival research for historical specifications and plans, photographs, correspondence.

Microanalysis to precisely determine the sculpture's original surface treatment;

Removal of debris, cleaning out cracks and voids.



Colonel Edward James 106<sup>th</sup> New York

Gentle overall surface cleaning of the monument's stone components with a very low concentration (3% - 6%) pH-neutral cleaner and deionized water.

Application of a nonreactive, liquid antimicrobial to remove surface mold, mildew, lichen and biological staining.

Masking and tarping of the monument's stone and surrounding plantings.

Paint removal with S-303, a non-toxic, hydrogen peroxide-based paint remover manufactured by Cathedral Stone Products in Hanover, Maryland.

Full clearance of all residue with deionized water.

Surface patination.

Surface finishing with Incralac, a metal conservation lacquer that contains a chelating agent to retard surface oxidation and UV degradation.

A fund raising effort is underway by the Friends of Mount Hope to raise the needed \$15,000.00 for the project.

Lincoln Camp has donated \$500.00, with Camp Members contributing more as individuals.

Work is scheduled for completion in 2016.



Defenders of the Flag

Your Obedient Servant,

With Spin 14

Dr. William S. (Sam) Poulton, Jr., PhD, PCC

# SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL FUND REQUEST

(FORM CWM #62)

<b>REQUESTOR INFORMATION</b> (Please print or the second	ype)					
CAMP AND DEPARTMENT NAME: Abraham Linc	oln Camp # 6 Roche	ster, New York				
NAME/ TITLE OF CONTACT PERSON: Edward O'E	Brien Camp Comma	nder				
ADDRESS: PO Box 69						
CITY:Honeoye Falls	STATE:NY	ZIP Co	DDE: 14472			
PHONE(S						
SIGNATURE:			_			
NAME OF MEMORIAL/MONUMENT Civil War	Nonument (Defender	rs of the Flag)				
NAME, NUMBER & STREET ADDRESS OF CEMETERY OR OTHER LOCATION Mt. Hope Cemetery 1133 Mt. Hope Ave. Rochester, NY 14620						
LOCATION DESCRIPTION (i.e. corner of 3 <sup>rd</sup> and Lincoln St) Monument is located at the intersection of Grove Avenue and Firemen's Avenue, Section BB, in						
the Civil War plot.						
GPS N <sup>43</sup> W <sup>-78</sup> City Honeoye F	alls	_State_NY	_ ZIP_14620			
WAS FORM CWM-61: GAR MONUMENTS/CIVIL WAR MEMORIALS ASSSESSMENT SUBMITTED? Y $\stackrel{ ext{Y}}{}$ N						
	ONUMENTL	AST SOLDIER PR	OJECT			
RESTORATION COST \$_3,500.00 AMOUN		REQUESTED \$	2,000.00			
CHECK PAYABLE TO: The Friends of Mount H	lope Cemetery					
ADDRESS: PO Box 69						
CITY: Honeoye Falls	State:NY	ZIP CODE:	14618			
Memorial Grant Committee Use Only						
Grant Request #	_ Amount Approved \$					
Approve Deny Table Name Committee Member	Signature		Date			
Check box, sign, date & return completed email to Com	nittee Chair, who will sen	d to National Treasu	rer for payment.			

#### MONUMENT/ MEMORIAL INFORMATION

WHEN WAS IT BUILT:	1908	WHO OWNS IT:	City of Rochester
WHO IS FINANCIALLY F	RESPONSIBLE?	Friends of Mo	unt Hope Cemetery
ARE MATCHING CONTI	RIBUTIONS AVA	ILABLE? yes	_FROM WHERE: Friends of Mt Hope Cemetery
ARE OTHER SOURCES	OF FUNDS AVA	AILABLE? none	FROM WHERE:
WAS A GRANT FROM T DATE: 2015			VED FOR THIS PROJECT?
			e specific, use continuation sheet if needed) SERVATION Building & Monument Restoration.
			AT ARE THEIR QUALIFICATIONS? ing in historic preservation of monuments.
WHO WILL DO THE DES Building and Monum			E THEIR QUALIFICATIONS? Ellison Conservation
WHO WILL RECEIVE FL Friends of Mount Ho		ED?	
			L DO TO ACCOMPLISH THE PROJECT Cemetery to raise funds for the restoration .

### ELLISON CONSERVATION

building & monument restoration, consulting & contracting

February 17, 2021

Patricia Corcoran The Friends of Mount Hope Cemetery 1133 Mount Hope Avenue Rochester, New York 14620

#### *Re:* Professional Services Proposal for the cleaning and waxing of the Civil War Monument, Mount Hope Cemetery, Rochester, N.Y.

Dear Friends of Mount Hope Cemetery:

As per your request, Ellison Conservation is pleased to submit this Proposal to the Friends of Mount Hope Cemetery for the Cleaning and Waxing of the Civil War Monument at Mount Hope Cemetery.

### General Description and Condition

The Civil War Monument is located in Mount Hope Cemetery in Rochester New York. The sculpture (Defenders of the Flag) by Sally Farnham and consists of bronze sculpture of a boy with a bugle and a soldier carrying a flag on a grey granite pedestal on a granite slab on grade.

### Conservation Treatment:

The definition of conservation is the preservation of cultural property for the future and in this project entails treating this monument as a historic artifact and implementing treatments that retain as much original material as possible while restoring it. The treatment will be sympathetic to the original materials and the original design intent, i.e. they will not cause harm to the stone. For example, some cleaning methods are too aggressive and remove original fabric and can accelerate deterioration of a monument.

Although bronze has excellent weathering properties, it requires a regular schedule of cleaning and coating to protect it from the elements. The National Park Service recommends outdoor bronze sculpture be recoated with wax at least once a year in normal environments, and twice a year in harsher environments.

The primary goal of treating the monument is to reinstate a physical wax barrier between its bronze surfaces and damaging oxygen, UV light, and acidic airborne hydrocarbons. It is also an opportunity to clean all its surfaces, remove any accumulation of bat and bird guano, and simply inspect the monument for problems not visible from the ground.

Treatment will take place as follows:

- 1) Erect scaffolding/lift to access all monument surfaces
- 2) Inspect & photodocument each of the memorial's quadrants before treatment
- 3) Mask around "Bivouac of The Dead" bonze tablet

- 4) Wipe any areas where bird or bat droppings have accumulated (full-face respirators will be worn during these procedures to protect against Histoplasmosis)
- 5) Dry-clean the memorial from top-to-bottom with soft brushes
- 6) Starting from the top of the flag, use soft cotton rags to clean the sculpture with a cleaning solution in deionized water
- 7) Rinse each area two (2) times with deionized water
- 8) Rub with cotton cloths to remove any aging wax
- 9) Apply new wax to surfaces, working down the flag, figures, base, and "Bivouac of The Dead" plaque
- 10) Buff with soft cotton cloths. Surfaces should be buffed after wax has set, but before morning dew has a chance to accumulate
- 11) Inspect and photograph finished memorial

### Guidelines

All work will conform to the American Institutes for Conservation's Code of Ethics.

### Qualifications

Ellison Conservation is a professional conservation firm specializing in historic preservation, and is experienced in the restoration and conservation of historic buildings and monuments. The firm is quite familiar with construction materials and techniques used in historic buildings and monuments, and has the expertise to investigate, analyze, and solve and treat problems associated with the restoration and rehabilitation of a resource's historic fabric.

### Availability and Schedule

We anticipate that a minimum of two (2) weeks will be required to complete the indicated scope of fieldwork.

## Fee

Ellison Conservation proposes to provide the Scope of Services described above for the below fees:

### CONSERVATION FIELDWORK

1.	Cleaning & Waxing of Monument- labor	\$ 2,650.00
2.	Materials & Access	\$ 850.00
	Total Cost	\$ 3,500.00

## TERMS

This proposal is incorporated into the attached Contract by reference. If you are in agreement with the Scope of Services, Terms, and Conditions of this proposal as presented herein, please sign and date where indicated and return a copy to me. When executed, the Proposal, together with the Contract, will constitute our Professional Services Agreement.

The Fees, Terms, and Conditions of this Proposal will remain valid for ninety (90) days.

Civil War Monument, Mount Hope Cemetery February 17, 2021 Page 3

\_\_\_\_\_

Ellison Conservation is delighted at the prospect of working with you on this project, and we appreciate your consideration of our firm. If you should have any questions regarding this proposal or our scope of work, please do not hesitate to contact me at 585-298-4487.

Respectfully submitted,

Peter T. Ellison Conservator, M.S. Civil War Monument, Mount Hope Cemetery February 17, 2021 Page 4

**Ellison Conservation Proposed Service** 

This agreement is hereby made and entered into this Proposed Service between The Friends of Mt. Hope Cemetery (Client) and Ellison Conservation (Contractor). The parties agree to the following:

The Contractor agrees to provide the material and labor required to perform the Conservation of the *Civil War Monument* located at the above address as outlined in the proposal dated February 17, 2021.

The Client hereby agrees to pay the Contractor, for the material and labor for the sum of up to \$3,500.00. The Contractor agrees to provide and pay for all materials, tools, and equipment required for the execution and timely completion of the work.

All changes in the work ordered by the Client must be in writing, the Proposed Service sum being increased or decreased accordingly by the Contractor. Any claims in writing and written approval of the Client shall be obtained by the Contractor before proceeding with the ordered change or revision.

The Client, Client's representative and public authorities shall have access to the work.

The Contractor agrees to re-execute any work which does not conform to the proposal, warrants the work performed, and agrees to correct resulting defects, from faulty materials or workmanship which shall become evident during a period of one year after completion of the work, except for abuse or acts of God and the resultant possible damages.

In the event the Contractor is delayed in the execution of the work by acts of God, fire, flood or any other unavoidable causalities by labor strikes, late delivery of materials; or by neglect of the Client; the time for completion the of the work shall be extended for the same period as the delay.

The Contractor has in place insurance to protect himself against claims for property damage, bodily injury or death due to his performance of this agreement.

\* Permission for storage of equipment/materials inside of Mount Hope Cemetery grounds will be obtained from the Friends of Mount Hope Cemetery (FOMH) prior to the beginning of work. Contractor assumes responsibility for any loss, damage, or liability resulting from on-site storage.

\* Delivery of materials or equipment and/or contractor's work will not interfere with normal operations at Mount Hope Cemetery. Contractor would like a minimum of 24 hours' notice if work must cease due to any activity taking place within an effected distance at cemetery during contractors scheduled work time.

\* The Contractor's Insurance Certificate will be on file at FOMH's office before commencing any work on the site. FOMH shall be listed as an additional insured on contractor's insurance certificate.

Contract valid upon receipt by Ellison Conservation of Signed copy of Contract.

By:	Peter T. Ellíson	Dated:	2/17/2021
Peter T. Elli	ison, Ellison Conservation		

By:

Dated:

The Friends of Mt. Hope Cemetery

Defenders of the Flag, Civil War Monument, Mt. Hope Cemetery, Rochester, NY



Sculptor Mark



Fabricator Mark

1861 R ON FAME'S ETERNAL CAMPING GROUND THEIR SILENT TENTS ARE SPREAD, AND GLORY GUARDS WITH SOLEMN ROUND THE BIVOUAC OF THE DEAD, MAND

Plaque on base



Oxidation/corrosion on sock.



Patina on arm/shoulder and flag.

# "THE DEFENDERS OF THE FLAG" A CIVIL WAR MEMORIAL BY SALLY JAMES-FARNHAM: CONSERVATION TREATMENT REPORT 2015

PREPARED BY RON KOENIG DECEMBER 10, 2015





Sally Farnham With "Simon Bolivar," 1921

# Overview

In October of 2015 Conservators Peter Ellison and Ron Koenig carried out the conservation of "Defender's Of The Flag," a bronze sculptural group executed in 1908 by Sally James-Farnham. The memorial is located in Mount Hope Cemetery, Rochester, NY. It depicts a contemplative moment shared by a Union soldier and bugle-boy, as they return home at the end of the Civil War.

# Condition

The sculpture is also sometimes titled "Civil War Soldier and Bugler." It is fifteen feet high and made of bronze. It was cast at Roman Bronze Works in New York City. The two figures stand upon a large block of coarse-finished granite, which in-turn is set on a flat, squared pedestal with rusticated edges. The monument's large massing makes it a central focus of Mount Hope Cemetery's Civil War burial-ground.

The City of Rochester has a naturally-occurring acidic environment, and this encouraged deterioration and pitting on the sculpture's bronze surface. At some time in its past, it appears that surfaces were also covered with bronze "radiator" paint, which had oxidized, turning the sculpture an uneven green-brown (Photo 1). By 2015, surface degradation had occurred to an extent that it was difficult to discern the carefully modelled clothing or subtle facial expressions of Sally Farnham's figures.

## **Treatment And Scope**

The goal in treating the sculpture was to improve its longevity, as well as to restore the look and feel intended by its artist Sally Farnham. The scope of the project included conservation of:

- 1) The "Defenders of The Flag" sculpture group
- 2) A bronze plaque below the sculpture containing verses from Theodore O'Hara's *Bivouac* of The Dead
- 3) Bronze "Carlo" sculpture

Treatment included:

- Documentation
- Microanalysis
- Scaffolding
- Masking and tarping
- Assessment and testing of surfaces
- Removal of debris, cleaning out cracks and voids
- Surface cleaning and finish removal

- Removal of biological growth
- Gentle abrasive cleaning
- Repair of areas of loss
- Surface patination
- Waxing

### Microanalysis

As noted in our report of September 17, 2012, very small representative samples were taken prior to treatment and analyzed under high magnification. Samples were examined at 100X with an Olympus SZ binocular microscope, under a 5200K light source. At high magnification, the samples were dark brown and had reflective and resinous qualities (Photo 2).

Solubility tests were also carried out under the microscope to determine the type of finish that was applied over the bronze. These were followed with simple reagent-based, wet chemical analysis for lead and copper to ascertain if the finish might be bronze powder in a spirit varnish.

The finish was partially soluble in acetone, but proved more fully miscible in methylene chloride. When a high-percentage methylene chloride solution was applied to part of the sample, it broke down into smaller, brown-green fragments, leaving a brown residue upon drying.

Tests for lead showed a mild reaction at the lower edge of the sample, suggesting lead may be a small component of the alloy used in casting the monument, or, more likely, that the finish applied to the monument contained lead.

Tests for copper were also positive, with the reagent turning color as soon as it came into contact with the material. The presence of copper in the finish was inconclusive, however, due to copper being present in the bronze alloy used for casting the sculptures (sculptural bronze is typically 83-88% copper).

Testing confirmed that the samples are likely pulverized bronze metal (an alloy of copper and tin) suspended in a nitocellulose spirit varnish. This type of paint was commonly used to paint cast iron radiators, so is often referred to as "Radiator Paint."

## Scaffolding

Access to conserve the monument was accomplished using standard 6' X 6' rigid scaffolding, erected over protective canvas tarps. Canvas tarps were chosen because they would cushion surfaces below, and their breathability meant they were less likely to cause damage to plantings, etc. than plastic sheeting. Scaffold sections were set up around the monument and levelled using screw-jacks; this allowed full access from all sides and all surfaces. Scaffolding was engineered to create safe work enclosures, while allowing full access to all surfaces.

### Documentation

Extensive photographic documentation was carried out through all aspects of the project. This included before and after pictures, as well as details of each step of treatment. Representative photos were presented to the client.

Research was carried out to determine how the sculpture was designed, and to better understand the materials used in its execution. Further, a working knowledge of Sally Farnham, her work, and her exposure to other artists such as Frederick Remington allowed for a more context-based approach to treatment.

A useful example can be found in an undated letter from Frederick Remington to Farnham; Remington wrote:

My dear Sally Missie [Eva, his wife, one might assume] was talking about your Sentinel on monument. First-his gun must not be on the ground if you want the sentinel idea.

The only good Civil War art material is *Forbes Etchings* and *Winslow Homer's* Illustrations in war numbers of Harpers Weekly. All else is misleading. Why don't you put him in marching order—blanket roll haversack, etc? Tuck his breaches in his socks, and don't make him slick. Give him long hair—curled forward over the ears. Don't have much in his haversack—pantaloons very full & wrinkled...and above all never mind what old soldiers tell you because this had that and this issue without end but the things they describe were not general—uniform or typical *ofttimes*. There were all kinds of things issued but which did not survive. The last of the war was fought with merely a poncho (rubber) and no blanket. Go to *Bravermans* on B'way for your stuff—and get a Civil War haversack—they were unlike the new ones in use now.

I enclose a rough sketch which may help you a little. If you don't have that soldier so he suits me I will slander your d\_\_\_\_ old monument.

Yours, Frederick\*

The letter's informality tells us volumes about the relationship between the sculptors; not only are Remington's words part of a dialogue between trusted friends, but the tongue-in-cheek use of a curse at the end tells us the Master is proud of his charge and expects only the highest quality work from her. Though undated, this remarkable communication almost certainly refers to "Defenders of The Flag." Within this context, the note makes it clear Remington played a very tangible part in its design, down to the figures' gear, hair, and how their clothes were portrayed.

While Sally Farnham is often described as "untrained," the truth is that her stunning attention to detail was clearly acquired--full or in-part--through the tutelage of her friend and mentor

<sup>\*</sup> George F. McFarland. "Sally James Farnham: The Remington Years." The Quarterly: Official Publication of The St. Lawrence County Historical Association: XXXVI. 3 (1991): 10-11. Print.

Frederick Remington. Understanding this relationship, and what it meant, gives great insight into how and why Farnham chose details for her composition. By extension, these insights can also be useful in determining how, for example, individual details might be presented during conservation.

### Treatment: "Defenders of The Flag"

Treatment began with a careful examination of all surfaces on the monument. Debris was removed from cracks and crevices, and several tiny pin-hole voids were noted.

The monument's surfaces were thoroughly wiped-down with acetone and soft rags. Biological growth such as moss, lichen, and mold were removed with an application of D/2, an antimicrobial manufactured by D/2 Biological Solutions, Inc, Westport, MA.

The monument's heavy accretion of black and blue-green vertigris made it difficult to see its details Cleaning tests were carried out to determine an appropriate method for mitigating this visual surface discontinuity. Further solvent wipes were found to have little effect. Testing was carried out using fine, compressed air-driven, abrasive media. Tests with pulverized walnut shells showed little to no change in the surfaces. Six to eight passes with very fine (500 Grit) ground glass, however, slowly removed the sculpture's heavy accumulation of bronze oxide, yet left an appropriate, visually integrated patina.

Beginning at the top, the figures were abrated in slow, horizontal passes. Protuberances such as limbs, hats, and military equipment were cleaned in an elongated pattern that followed the protuberance. Cleaning of the Verse Plaque, Base, and Flag followed. Throughout the cleaning great care was taken to gently play abrasive into crevices, back-cuts, and recesses, and not unduely effect edges and rims.

Small voids were carefully filled with a tinted, two-part epoxy manufactured by West System, Inc. Bay City, MI. Fills were applied in a manner that filled each tiny hole, yet did not extend beyond the margin.

To improve surface continuity, surfaces were patinated using *Brown: Brass, Bronze and Copper Darkener* made by Jax Chemical Company, Mount Vernon, NY.. Following patination, surfaces were rinsed repeatedly with deionized water; this was followed by two full rinses using potable tap water.

Surfaces were protected with two applications of Briwax, manufactured by Briwax Internation, Inc., Plano, Texas.

### **Treatment: Carlo**

In addition to the conservation of Sally Farnham's Monument, Building Arts & Conservation also restored a small bronze sculpture of a dog. The piece is ordinarily referred to as "Carlo" because this name is inscribed on its collar. The sculpture was cast at The Geo. Fischer & Bro. Bronze Foundry, NY. After being stolen from Mount Hope Cemetery, the piece was later found in poor condition in a field outside a local disreputable bar. After recovery, the sculpture was sandblasted, then painted with gold-colored radiator paint.

Treatment involved removing over-paint from its surfaces, and then touching-in weld-seams left visible from sand-blasting. After treatment Carlo looks much as he probably appeared when he ws installed as a watch-dog in front of a local family's tomb.

### **Future Treatment**

To ensure longevity, we recommend a close-up Condition Assessment be carried out on the "Defenders of The Flag" Monument at least one a year. This should entail:

- 1) Accessing all surfaces from a scaffold or man-lift
- 2) Photographing any areas of concern
- 3) Noting conditions in writing
- 4) Presenting findings to The Friends of Mount Hope Cemetery

To track changes over time, Condition Accessments should be placed in a binder, and reviewed—together--every five-to-six years.

Briwax should be reapplied to all of the monument's bronze surfaces at least three times a year. UV light will break the wax down over time, and needs to be recoated to continue to protect surfaces from acid rain, bird droppings, and general oxidation.

### Approach

All work followed the <u>Guidelines for Practice</u> of The American Institute for Conservation (AIC). These standards emphasize exercising an uncompromising respect for historic materials through:

- Research
- Full Documentation
- Retaining original architectural elements
- Using reversible treatments
- Flagging old work from new

All facets of the work on "Defenders of The Flag" were executed to conserve, preserve, and extend the life of its historic materials to the fullest extent possible. Treatments were photodocumented, and these photos have been uploaded to Dropbox® for download by the client.