SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL FUND REQUEST (FORM CWM #62)

Requester Information +
CAMPAND DEPARTMENT NAME: GEN. HENRY B. BANNING ZOT DEPT. of Ohio
ADDRESS: BMANSFielo Ave. (CAMP METS AT Memorial HAII-GAR off:
CITY: MT. Vernon Ohio ADDRESS) STATE: Ohio ZIPCODE: 43050
NAME OF CONTACT PERSON: Nicholas Ehlert Camp Commander
ADDRESS: 23 MANSfield Ave
CITY: MT. Vernon Oh.'s STATE: Ohio ZIPCODE: 430 50 PHONE(S):
THOREGO.
Memorial or Monument Information
NAME OF MEMORIAL: 4Th Ohio Vol. Infantry Monument.
LOCATION: (Name and address of cemetery or other location description, such as, corner of 3rd and Lincoln Streets) CemeTery 1.11. Getty/sburg NATioNA BAHLE Field PARK
Cemetery. Cemetery.
WHEN WAS IT BUILT: 1887 WHO OWNS IT: EITHER THE STATE OF Ohio OR The NATIONAL PARK
WHO IS FINANCIALLY RESPONSIBLE FOR IT: STATE of Ohio government SAI/3 The NATIONAL
PARK. PARK BAYS ITS STATE DESPERTY AND Ohio is Responsible. ARE MATCHING FUNDS AVAILABLE: FROM WHERE:
ARE OTHER SOURCES OF FUNDS AVAILABLE: 125 FROM WHERE: BRANTS TRUSTS DONATIONS GAL
AMOUNT BEING REQUESTED: MAXILLA
DESCRIBE WORK THAT THESE FUNDS ARE NEEDED FOR: (Be specific, use back if necessary) The 47h OVI MONUMENT WAS THE TAILEST OF COMMONWENT ON The
Gettysburg battlefiels from 1887 UNTIL The EARLY 1970'S. The NATIONAL PARK Removed The Top 2/3 RD AND DIACED
The column CADITAL & BOLDICK IN STORAGE. The MONUMENT WAS CONSTRUCTED ASITH MINE. The BASE COLD NOT
Support The weight of The 32 feet Above it. The base Developed CRACKS AND The column began To
LAN. All of PARTS ARE hollow. The PARK SERVICE
Delieves A STATINESS STEAL ARM CAN be Placed through Theseparts they All the weight will be on this ARM.
WHO EVALUATED THE NEED FOR THE WORK AND WHAT ARE THEIR QUALIFICATIONS: Vic GAVIN, Gettysburg NATIONAL VARK OFFICER OF CANNONS & MONGMENTS
1-717-334-5533
WHO WILL DO THE WORK DESCRIBED AND WHAT ARE THEIR QUALIFICATIONS: Vic GAUIN'S NATIONAL PARK CREW - They MAINTAIN ALL PARK MONAMENTS - UIC GAUIN'S Phone No. is 1-717-334 + 5533
WILL BUT I DECEMBER THE FUNDOUS CONTROL ALL CONTROL AND THE STATE OF T
MON UM ENT BANK ACCOUNT THAT IS NOW CHOSE TO 15,000.
of the \$20,000.00 Needed by The PARK To complete This
PRoject

Sons of Union Veterans of the Civil War Department of Ohio General Henry B. Banning Camp #207 Mt. Vernon, Ohio

October 5, 2001

Dear Brother Donald Darby:

Please find enclosed form CWM#62 made out in triplicate. You had advised me that I needed to send the forms to three different Council Administration members. Unfortunately, the website only lists you. Please forward to the other two administration members the enclosed copies.

As you are aware, our Camp has been struggling to raise the \$20,000 required by the Gettysburg National Military Park to restore the 4th OVI monument on Cemetery Hill. As of this date, we have raised nearly \$15,000. We are hoping to raise the additional \$5,000 needed by the end of 2001.

department, headed by Mr. Vic Gavin, will do all work on the monument restoration. His phone # is

Enclosed is the National Park's proposal for the restoration, photos of the monument as it now exists, a letter from Ms. Lisa Orendorff, showing that the Sons of Union Veterans has contributed \$4,000 as of November 1999.

Mary Zins from the First Cleveland Cavalry Association has not yet received

The Gettysburg National Park monument and cannon maintenance

the information that you said you would be sending to her. She can be reached at or E-mail:

This promise of \$1,000 is a much needed addition to our funds. Please follow up with her and provide the needed information.

Finally, if there are any questions on the enclosed form, please feel free to call me at as soon as possible.

I remain yours in Fraternity, Charity and Loyalty,

Nicholas J. Ehlert, Camp Commander

Proposal: General Conceptual Outline For Monument Restoration

Project: 4th Ohio Volunteer Infantry Monument

Location: East Cemetery Hill, GNMP


Background:

This monument, dedicated on 14 September, 1887, was designed by Peter B. Laird for the Monumental Bronze Company, Bridgeport, Conn. The components of the structure were cast in a zinc alloy that was advertised as "white bronze". This alloy of almost pure zinc, was alloyed with copper, tin, and sometimes nickel. White bronze was used for monument casting from about 1870 until the turn-of—the century. The alloy resists the effects of weathering quite well, but has poor structural strength. This creates problems with larger monuments (as in the case of the 4th Ohio Inf. Monument), when, because of this lack of strength, lower components eventually sag under the weight of upper parts of the structure. Cracks and distortions typically accompany this condition. It is notable that several small zinc monuments/markers, located at GNMP, remain in generally good condition.

Although this material was utilized for several decades, no doubt because it was inexpensive compared to bronze, the alloy presents a rather flat gray appearance, which lacks the aesthetic reflective qualities of bronze. The metal was recognized as inferior by the Board of Commissioners of Gettysburg Monuments. On October 7, 1887, shortly after the dedication of the 4th Ohio monument, specifications were written which stated that: "When designs call for bronze, real bronze only will be allowed".

The 4th Ohio was assembled (bolted joints) from seven major components. At present, only four of these remain in place. The upper three units were removed in 1976 when metal fatigue in the lower units created an out-of-plumb condition which threatened the upper units (column, capital, military figure). Since that time, the three upper units have remained in storage.

The GNMP Monument Section is proposing that the in-situ components be removed, and that the eld foundation be demolished. A stainless steel armature would then be fabricated on a new foundation. The hollow zinc castings would be supported by this internal framework. Non-conductive pads would be used at points of contact to inhibit electrolytic metal degradation. In theory this concept is basic, but detailed measurements and skilled fabrication would be essential. Intervention for cosmetic reasons (repairs of minor cracks, etc.) would be kept to a minimum. Some evidence of metal distortion would remain, but attempts to create a "new" appearance might well put historic fabric at risk.



Total Ht. 32' 3"

Note: Attached are field notes which illustrate the basic concept for an internal stainless steel armature. Estimates for this project vary considerably, based on the amount of work to be performed "in-house" vs. private sector contractors.

FORM D S C - 44

Fark	<i>A</i>			Shce:
Arca	G. N. M. P.		NATIONAL PARK SERVICE WILLIAMSPORT PRESERVATION TRAINING CENTER	cl
			. /(:	Pkg.
Footies	KTH. CHIO	MODUMENT	By Checked	Account
Leature	3.3. FRITATE	5.770M	Date 03/18/96 Date	Mocodill
		Composition of the control of the co	230 TO C.C.	



United States Department of the Interior

NATIONAL PARK SERVICE

GETTYSBURG NATIONAL MILITARY PARK GETTYSBURG, PENNSYLVANIA 17325 EISENHOWER NATIONAL HISTORIC SITE GETTYSBURG, PENNSYLVANIA 17325

IN REPLY REFER TO:

D66

March 14, 2001

Mr. Nick Elhert
Camp Commander
Henry Banning Camp #207
Sons of the Union Veterans of the Civil War
23 Mansfield Avenue
Mount Vernon, Ohio 43050

Dear Mr. Elhert:

This is in response to your phone inquiry regarding donations received for the restoration of the 4th Ohio monument located on East Cemetery Hill. To date we have received donations totaling \$4,300. These funds have been deposited into the park monument donation account where they will be held until enough money is available to complete the restoration of the monument.

The first donation in the amount of \$300 was received in December 1998 from the Columbiana County Park District. This money came from proceeds of a reenactment held at Scenic Vista Park, Lisbon, Ohio. The only other donation to this project was given generously by the National Organization of Sons of Union Veterans of the Civil War in November 1999.

Your group's interest and dedication in assisting in the restoration of this monument is appreciated. Sufficient funds are not always available to accomplish many vital projects, and it is only through these generous contributions that we are able to make these improvements.


Sincerely,


Lisa Orendorff


Acting Administrative Officer

cc: Maint: D.Grauel V. Gavin

4th OVI Statue as it appeared 1897













James W. Harl

mt Vernon Son

buried at G.N.B. Cem.

Brother also in 47h

OUT buried in Mound

View Com. MT. Vernon

