FORM CWM #61 Page 1 of 4

NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- 1. Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- 2. Do not guess at the information. An answer of, "Unknown," is more helpful. Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial Monument with Sculpture Monument with Cannon Monument without Sculpture Historical Marker Plaque Other (flag pole, G.A.R. buildings, stained glass windows, etc.)
Affiliation
Original Dedication Date April 12, 2015 Please consult any/all newspaper archives for a local paper's article that would have information on the <i>first</i> dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you. Location The Memorial is <i>currently</i> located at:
Street/Road address or site location Current River Conservation Area N37.200708 W90.988993 City/Village Ellington Township T29N, R1E,S6,18 County Reynolds State MO
The front of the Memorial faces: North South _xx _ East West Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in) Name _Missouri Department of Conservation Dept./Div Street Address PO Box 180 City
Jefferson City State MO Zip Code 65102 Current River Conservation Area Telephone () 573-751-4115 If the Memorial has been moved, please list former location(s). New Marker, 0.75 mi. S of Hwy J on Cty Rd. 814, Black vicinity

FORM CWM #61 Page 2 of 4

Physical Details

Material of Monument or base under a Sculp name specific material (color of gran		
Material of the Sculpture = Sto If known, name specific material (col If the Sculpture is of metal, is it soli	or of granite, marble, etc.)	
Material of Plaque or Historical Ma	rker / Tablet = Red Granite	
Material of Cannon =Bronze _ Markings on muzzle =		
Markings on Left Trunion Is inert ammunition a part of the Mo	Right Trunion	
Is inert ammunition a part of the Mo	emorial? If so, describe	
Approximate Dimensions (indica Monument or Base: Height 36 in Sculpture: Height Width		
For Memorials with multiple Sculpti for each statue and attach to this for weapons/implements involved (in contract)	orm. Please describe the "pose" of	of each statue and any
Markings/Inscriptions (on stone-Naker or Fabricator mark / name? If Not on marker, but made by Poplar Bluff Monument Co	so, give name & location found	
The "Dedication Text" is formed: \underline{x}	cut into material raised up	from material face
Record the text (indicate any separa Fort Barnesville - National Historic Site - Fort Barnesvil		
troop movement along the Belleview Trail. The Fort wa	as discovered by Dan Massie while hunting in the 19	50s. In 1995, Gerald
Angel, assisted by John Bradbury, Jerry Ponder and Jo	be Huett, researched and authenticated the Fort. It v	vas placed on the
national register of historic places on July 1, 1998. Marker provided by the Reynolds County Genealogy a	nd Historical Society, Inc. with a grant from the Taun	n Sauk Fund 2014
Environmental Setting (The general vicinity and immediate locale so Type of Location	urrounding a memorial can play a major ro	le in its overall condition.)
Cemetery	xx Park	Plaza/Courtyard
"Town Square"	Post Office	School
Municipal Building	State Capitol	Other:
Courthouse	College Campus	State Conservtion Area
Traffic Circle	Library	

FORM CWM #61 Page 3 of 4

General Vicinity XXX Rural (low population, open land) Town	Suburban (resident Urban / Metropolita	
Immediate Locale (check as many as may apply) Industrial Commercial Street/Roadside within 20 feet Tree Covered (composed from the elements (canopy or enclosure, incomposed from the public (fence or other barrier) Any other significant environmental factor	doors)	
Condition Information		
Structural Condition (check as many as may apply)		
The following section applies to Monuments with Sculpture, and including the base for Monuments with Cannon. Instability in the number of factors. Indicators may be obvious or subtle. Visually	sculpture and its base can be	e detected by a
	Sculpture	Base
If hollow, is the internal support unstable/exposed? (Look for signs of exterior rust)		
Any evidence of structural instability?		
(Look for cracked joints, missing mortar or caulking or plant gr Any broken or missing parts?	rowth)	
(Look for elements (i.e., sword, musket, hands, arms, etc mi	issing ——	
due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes?		
(Also look for signs of uneven stress & weakness in the mater	ial)	
Surface Appearance (check as many as may apply)		
	Sculpture	Base
Black crusting White crusting		
White crusting Etched, pitted, or otherwise corroded (on metal)		
Metallic staining (run-off from copper, iron, etc.)		
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone Granular eroding of stone		
Spalling of stone (surface splitting off)		
Droppings (bird, animal, insect remains)		
Other (e.g., spray paint graffiti) - Please describe		
		
		
Does water collect in recessed areas of the Memorial?	_ Yes No Unable	to tell

FORM CWM #61 Page 4 of 4

Surface Coating
Does there appear to be a coating? Yes <u>×</u> No Unable to determine If known, identify type of coating Gilded Painted Varnished Waxed <u>×</u> Unable to determine Is the coating in good condition? <u>×</u> Yes No Unable to determine
Basic Surface Condition Assessment (check one)
In your opinion, what is the general appearance or condition of the Memorial? XX Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). WORKMEN FROM Poplar Bluff Monument Company installed this marker at the entrance to Fort Barnesville Monday, Nov. 24. 2014
Submitter was on the archaeological survey of this fort. The results were totally inconclusive. No period artifacts found. The "fort"
needs to have considerable research done before it can be called a Fort, a redoubt, or even a cavalry picket post, which at best it could
have been. Active time for this according to telegrams between Barnesville (Ellington and Pilot Knob) would have been Spring 1863.
Complemental Deckmand Information


Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-site Survey 04/09/2015 Your Name Walt Busch	
What Order or Organization is submitter a member of? SUVCW - MO - US GRANT 68	
Please send this completed form to	

Walt Busch, PDC, Chair



Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR National Civil War Memorials Committee



