

NATIONAL ORGANIZATION
SONS OF UNION VETERANS OF THE CIVIL WAR
 CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.
- Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial

Monument *with* Sculpture Monument with *Cannon*
 Monument *without* Sculpture Historical Marker Plaque

Affiliation

G.A.R. (Post Name & No. _____) M.O.L.L.U.S.
 W.R.C. (Corps Name & No. _____) Other Allied Order
 SUVCW (Camp Name & No. _____) (Please describe below)
 DUVCW (Tent Name & No. _____)
 Other: Subscribed Community Members _____

Original Dedication Date August 12, 1911 Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

Location

The Memorial is *currently* located at:

Street/Road address or site location N39°13.504 W92°50.715 Third & Howard streets
 City/Village Glasgow Township _____ County Howard

The front of the Memorial faces: North South East West

Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)...

Name City of Glasgow Dept./Div. _____
 Street Address _____
 City _____ State _____ Zip Code _____
 Contact Person _____ Telephone () _____

If the Memorial has been moved, please list former location(s)...

Physical Details

Material of Monument or base under a Sculpture or Cannon = Stone Concrete Metal Undetermined
 If known, name specific material (color of granite, marble, etc.) _____

Material of the Sculpture = Stone Concrete Metal Undetermined
If known, name specific material (color of granite, marble, etc.) _____
If the Sculpture is of metal, is it solid cast or "hollow?" _____

Material of Plaque or Historical Marker / Tablet = _____

Material of Cannon = Bronze Iron - Consult known Ordnance Listing to confirm
Markings on muzzle = _____

Markings on Left Trunion _____ Right Trunion _____

Is inert ammunition a part of the Memorial? If so, describe _____

Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points
Monument or Base: Height ^{5 1/2 ft} _____ Width ^{5 ft} _____ Depth ^{5 ft} _____ or Diameter _____
Sculpture: Height _____ Width _____ Depth _____ or Diameter _____

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture)

Maker or Fabricator mark / name? If so, give name & location found Could have a name
but some of cuts are very faded _____

The "Dedication Text" is formed: cut into material raised up from material face

Record the text (indicate any separation if on different sides...) Please use additional sheet if necessary.
See separate pages

Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

Type of Location

- | | | |
|---|---|--|
| <input type="checkbox"/> Cemetery | <input type="checkbox"/> Park | <input type="checkbox"/> Plaza/Courtyard |
| <input type="checkbox"/> "Town Square" | <input type="checkbox"/> Post Office | <input type="checkbox"/> School |
| <input type="checkbox"/> Municipal Building | <input type="checkbox"/> State Capitol | Other: _____ |
| <input type="checkbox"/> Courthouse | <input type="checkbox"/> College Campus | Street Side _____ |
| <input type="checkbox"/> Traffic Circle | <input type="checkbox"/> Library | _____ |

General Vicinity

Rural (low population, open land) Suburban (residential, near city)
 Town Urban / Metropolitan

Immediate Locale (check as many as may apply)

Industrial Commercial
 Street/Roadside within 20 feet Tree Covered (overhanging branches)
 Protected from the elements (canopy or enclosure, indoors)
 Protected from the public (fence or other barrier)
 Any other significant environmental factor _____

Condition Information

Structural Condition (check as many as may apply)

The following section applies to Monuments *with* Sculpture, and Monuments without _____ Sculpture - including the base for Monuments with *Cannon*. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

Sculpture		Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	_____	_____
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth)	No _____	No _____
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc. - missing due to vandalism, fluctuating weather conditions, etc.)	No _____	No _____
Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)	Minor _____	Minor _____

Surface Appearance (check as many as may apply)

	Sculpture	Base
Black crusting	_____	_____
White crusting	_____	_____
Etched, pitted, or otherwise corroded (on metal)	_____	_____
Metallic staining (run-off from copper, iron, etc.)	_____	_____
Organic growth (moss, algae, lichen or vines)	_____	_____
Chalky or powdery stone	_____	_____
Granular eroding of stone	X _____	_____
Spalling of stone (surface splitting off)	_____	_____
Droppings (bird, animal, insect remains)	_____	_____
Other (e.g., spray paint graffiti) - Please describe...	_____	_____
Could use some cleaning		

Does water collect in recessed areas of the Memorial? Yes No Unable to tell

Surface Coating

Does there appear to be a coating? Yes No Unable to determine
If known, identify type of coating.

Gilded Painted Varnished Waxed Unable to determine

Is the coating in good condition? Yes No Unable to determine

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?

Well maintained Would benefit from treatment In urgent need of treatment Unable to determine

Overall Description

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) .

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification


Date of On-site Survey 06/16/2009

Walt Busch

US Grant #68

Please send this completed form to:

Kevin P. Tucker, PDC, Chair



Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR
National Civil War Memorials Committee

[West Face]

Glasgow Surveyed 1836
Incorporated 1845
Named for James Glasgow - A FDH
First City Govt -
Mayor - H W Smith
Council -
J S Thomson - Pres
DRIP Vaughan
R P Hanenkamp
Jesse Arnot
E Billingsley
J Zimmerman
G P Dameron
C D Simpson - Sec

Present Govt -
Mayor- W L Hannaca
Council -
E A Wengler - Pres
J T Hughes
Andrew Blocher
W B Nivert
Robert Amick
B F Stuckey
J H Scott
R E Turner - Sec
Percival Birch - Atty
Edw Gannon - M
[??} R L Wengler - Treas
H J Borges - Assr
R L Bacet - Elec Eng
C B Mc Atee - Depy Mar
J. K. [??????] C Y Eng.

St. Mary's Catholic Church Founded
[????????]
Rev. Father Henry Meur - First Pastor
Rev. Father John Waeltermann - Present
Pastor
New Church To Be Completed
[????????]

[East Face]

Lat of Mnt 33 D 13 M N
Long W from Greenw 92D 50M
From Washington - 15 D 47 M
[MAG VAY 5015 M E O ? N]
Top Above St L OR CT X-
330.20 Ft

Glasgow CRCTX -
126.50 Ft

Below Morrison Obs
1.80 FT
Fall In MO R -
.80 Ft Per M

Top 152.70 Ft Above
Stand Low W in MO. R

High W 1844
Highest on Record

High W 1903
2.90 Ft Below 1844

High W 1909
5.23 Ft Below 1844

Geodetic Distances -
From Washington - 849.10 M
St Louis - 143.40 M
Kansas C - 84.00
San Fran I [????] .90 M

1n 181[6?] Howard Co Contained 2[????
?? ?] and extended into Iowa.
In 1825 reduced to present area - 450 sq.
m.

The first large all-steel bridge in the
world built across Mo R
At Glasgow for the Alton RR - 1879 -
Gen Wm Sooey Smith Ch Eng.

The present bridge was built in 1900 -
WM D Taylor CH Eng

NORTH FACE





North Face



East Face



South Face



West Face



West Face



TOP