NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.
- Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial

Monument <i>with</i> Sculpture	Monument with Cannon	
Monument without Sculpture	X Historical Marker Plaque	Э

Affiliation

G.A.R. (Post Name & No) M.O.L.L.U.S.
W.R.C. (Corps Name & No)Other Allied Order
SUVCW (Camp Name & No) (Please describe below)
DUVCW (Tent Name & No)
Original Dedication Date	Please consult any/all newspaper archives for a
local paper's article that would have information on the first dedi	ication ceremony and/or other facts on the memorial.
Please submit a copy of your findings with full identification of th	ne paper & date of publication. Thank you.

Location

The Memorial is currently	v located at:		
Street/Road address or s	ite location Hwy DD at	Arkansas State Line N3	6°29.921 W94°01.455
City/Village Seligmann	ounty Barry		
The front of the Memoria	faces: North	South	East X West
			y that Memorial is located in)
Name Pea Ridge Memorial Asso			
Street Address Or Pea Ridg	e National Battlefield		
City		State	Zip Code
Contact Person		Telephone(_ Zip Code)
If the Memorial has been	moved, please list	former location(s)

Physical Details

Material of Monument or base under a Scu	ulpture or Cannon = 🔜	_Stone	Concrete	Metal _	Undetermined
If known, name specific material (co	olor of granite, mar	ble, etc.)			

11

Material of the Sculpture =StoneConcreteMetalUndetermined If known, name specific material (color of granite, marble, etc.) If the Sculpture is of metal, is it solid cast or "hollow?"
Material of Plaque or Historical Marker / Tablet =
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle = Markings on Left Trunion Right Trunion Is inert ammunition a part of the Memorial?
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height 6 1/2 feet Width 30 inches Depth 6 inches or Diameter Sculpture: Height Width Width Depth 0 or Diameter
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you! Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found
The "Dedication Text" is formed: cut into material raised up from material face Record the text (indicate any separation if on different sides) Please use additional sheet if necessary. Pea Ridge Memorial Association Logo with crossed US and Confederate Flags
POTTS' HILL
On the Arkansas - Missouri line where the Telegraph Road entered ten-mile long Cross Timber Hollow,
on February 16, 1862, occurred the first skirmish on Benton County soil. Brig. Gen. Curtis' Federal army
overtook the rear guard of Maj. Gen. Price as he retreated southward. This marked the beginning of the
Pea Ridge Campaign.
1862 Centennial Observance 1962
Environmental Setting
(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.) Type of Location
Cemetery Park Plaza/Courtyard "Town Square" Post Office School Municipal Building State Capitol Other: Courthouse College Campus county road Traffic Circle Library

Suburban (residential, near city)

General Vicinity

- × Rural (low population, open land)
 - Town Urban / Metropolitan

Immediate Locale (check as many as may apply)

- Industrial Commercial
- × Street/Roadside within 20 feet × Tree Covered (overhanging branches)
- Protected from the elements (canopy or enclosure, indoors)
- Protected from the public (fence or other barrier)
- Any other significant environmental factor

Condition Information

Structural Condition (check as many as may apply)

Sculpture -The following section applies to Monuments *with* Sculpture, and Monuments without ______ Sculpture - Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth)	
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc missing due to vandalism, fluctuating weather conditions, etc.)	
Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)	
Surface Appearance (check as many as may apply)	

	Sculpture	Base
Black crusting		
White crusting		
Etched, pitted, or otherwise corroded (on metal)		
Metallic staining (run-off from copper, iron, etc.)		
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone		
Granular eroding of stone		
Spalling of stone (surface splitting off)		
Droppings (bird, animal, insect remains)		
Other (e.g., spray paint graffiti) - Please describe		
good shape		

Does water collect in recessed areas of the Memorial? Yes X No Unable to tell

Surface Coating

Does	there	appear	to be	e a	coating?		Yes	<u>×</u>	No		Unable	to	determine
lf kno	wn, ide	ntify type	e of co	batin	g.								
G	ilded	Paint	ted	_ Va	arn <mark>ish</mark> ed _	V	Vaxed	_	Unab	le to	determi	ne	
Is the	coating	in good	conditi	on?	Yes		No			Una	ble to def	term	nine

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial? ____Well maintained _____Would benefit from treatment _____In urgent need of treatment _____Jnable to determine

Overall Description

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). Rustoleum paint would be a help, but overall in good shape

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-site Survey 03/10/2009 Your Name Walt Busch US Grant Camp 68

State MO Zip Code 63621 Telephone


Please send this completed form to:

Kevin P. Tucker, PDC, Chair



Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR National Civil War Memorials Committee



reated with TOPO!® ©2002 National Geographic (www.nationalgeographic.cor





HITT

Missouri line

On the Arkansas-Missouri line where the Telegraph Road emered ten-mile long Cross Timber Hollow, on February 16, 1862, occurred the tirst skirmish on Benton County soil. Brig, Gen. Curtis' Federal army overtook the rear quard of Maj. Gen. Price as he retreated southward. This marked the beginning of the Pea Ridge Campaign.