

**NATIONAL ORGANIZATION  
SONS OF UNION VETERANS OF THE CIVIL WAR  
CIVIL WAR MEMORIAL ASSESSMENT FORM**

**Type of Memorial (check all applicable)**

Monument  with Sculpture  without Sculpture  with Cannon  standalone Cannon  
 Historical Marker  Plaque  Other ( flag pole, G.A.R. buildings, stained glass windows, etc.)

**Affiliation**

GAR  MOLLUS  SUVCW  WRC  ASUVCW  
 LGAR  DUVCW  Other

If known, record name and number of post, camp, corps, auxiliary, tent, circle or appropriate information of other groups:

GAR John A. Hayn Post 240 Boonville

**Original Dedication Date** 1928 Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

**Location**

The Memorial is *currently* located at:

Street/Road address or site location Union Pacific Railroad Property next to the Overton Bottoms Conservation Area, off of Rochport Road. GPS Coordinates close to N38°58.006' W92°38.314

City/Village &/or Township Saline Township / Woodridge  
 County Cooper State MO Zip Code 65287

The front of the Memorial faces:  North  South  East  West

**Government Body, Agency, or Individual Owner**

Name Union Pacific Railroad  
 Dept./Div. \_\_\_\_\_  
 Street Address 1400 Douglas Street  
 City Omaha State NE Zip Code 68179  
 Contact Person \_\_\_\_\_ Telephone ( 888 ) 870-8777 ext \_\_\_\_\_

Is Memorial on the National Register of Historic Places  Yes  No ID # if known \_\_\_\_\_

**For Monuments with/without sculpture:**

**Physical Details**

Material of Monument or base under a Sculpture or Cannon =  Stone  Concrete  Metal  Other

If known, name specific material (color of granite, marble, etc.) \_\_\_\_\_

Material of the Sculpture  Stone  Concrete  Metal  Other Is it hollow or solid? \_\_\_\_\_

If known, name specific material (color of granite, marble, etc.) \_\_\_\_\_

**For Historic Marker or Plaque:**

Material of Plaque or Historical Marker / Tablet = Stone

**For Cannons with/without monument:**

Material of Cannon =  Bronze  Iron Type of Cannon (if known) \_\_\_\_\_

Rifled  YES  NO

Markings: Muzzle \_\_\_\_\_ Base Ring/Breech \_\_\_\_\_

Left Trunion \_\_\_\_\_ Right Trunion \_\_\_\_\_

Is inert ammunition a part of the Memorial?  Yes  No

[For camp/department monuments officer's use: Cannon on list of known ordnance]  Yes  No

**For Other Memorials:** (flag pole, G.A.R. buildings, stained glass windows, etc.)

What best describes the memorial

Materials of the Memorial

**Complete for All Memorials**

**Approximate Dimensions** (indicate unit of measure) - taken from tallest / widest points

35" Height 27" Width 13.5" Depth or \_\_\_\_\_ Diameter

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue (service, pose, etc) and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

**Markings/Inscriptions** (on stone-work / metal-work of monument, base, sculpture)

Maker or Fabricator mark / name? If so, give name & location found

Please attach legible photographs of all text &/or Record the text in the space below. Please use the addendum – narrative sheet if necessary.

Front (in large and small capital letters): "The Battle Of Boonville / Began Here June 17, 1861 / GENL LYON COMMANDER / Of The Union Forces"

Back (in capital letters): "Erected by the / G.A.R. / Post of Boonville / 1928"

**Environmental Setting**

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

**Type of Location**

Cemetery     Park     Plaza/Courtyard     "Town Square"     Post Office  
 School     Municipal Building     State Capitol     Courthouse     College Campus  
 Traffic Circle     Library    Other: Conservation Area

**General Vicinity**

Rural (low population, open land)     Suburban (residential, near city)     Town     Urban / Metropolitan

**Immediate Locale** (check as many as may apply)

Industrial     Commercial     Street/Roadside within 20 feet     Tree Covered (overhanging branches)  
 Protected from the elements (canopy or enclosure, indoors)     Protected from the public (fence or other barrier)

Any other significant environmental factor Should be protected from the Missouri River flooding by the raised bed of the railroad tracks

[To detail the condition of a monument used the addendum form for *Monument's Condition*]

**Supplemental Background Information**


In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment.

Addendums attached to this electronic file are the *Monument's Condition* and the *Narrative* forms. Only the *Monument's Condition* form is required if you are requesting grant money using form CWM-62 *SUVCW Memorial Grant Application Form and Instructions*.

Thank you.

Inspector Identification    Date of On-site Survey 5 September A. D. 2021

Your Name Sumner Gary Hunnewell




Are you a member of the Allied Orders of the G.A.R.? If so, which one?

SUVCW

Please send this completed form to:

Walt Busch, PDC, Chair



Thank you for your help, and attention to detail.

**SONS OF UNION VETERANS OF THE CIVIL WAR – CIVIL WAR MEMORIALS COMMITTEE.**

SONS OF UNION VETERANS OF THE CIVIL WAR
CIVIL WAR MEMORIAL ASSESSMENT FORM
ADDENDUM – MONUMENT’S CONDITION

Completion of this form is required when requesting grant money using form CWM-62 SUVCW Memorial Grant Application Form and Instructions.

Condition Information

Structural Condition (check as many as may apply)

The following section applies to Monuments with Sculpture, and Monuments without Sculpture including the base for Monuments with Cannon. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

Table with 3 columns: Question, Sculpture, Base. Rows include: If hollow, is the internal support unstable/exposed?; Any evidence of structural instability?; Any broken or missing parts?; Any cracks, splits, breaks or holes?.

Surface Appearance (check as many as may apply)

Table with 3 columns: Question, Sculpture, Base. Rows include: Black crusting; White crusting; Etched, pitted, or otherwise corroded (on metal); Metallic staining (run-off from copper, iron, etc.); Organic growth (moss, algae, lichen or vines); Chalky or powdery stone; Granular eroding of stone; Spalling of stone (surface splitting off); Droppings (bird, animal, insect remains); Other (e.g., spray paint graffiti) - Please describe...

Does water collect in recessed areas of the Memorial? \_\_\_ Yes \_\_\_ No \_\_\_ Unable to tell

Surface Coating

Does there appear to be a coating? \_\_\_ Yes \_\_\_ No \_\_\_ Unable to determine

If known, identify type of coating.

\_\_\_ Gilded \_\_\_ Painted \_\_\_ Varnished \_\_\_ Waxed \_\_\_ Unable to determine

Is the coating in good condition? \_\_\_ Yes \_\_\_ No \_\_\_ Unable to determine

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?

\_\_\_ Well maintained \_\_\_ Would benefit from treatment \_\_\_ In urgent need of treatment \_\_\_ Unable to determine

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) .

The monument was moved from near the Union Pacific Railroad tracks and a new base was created for it.

Inspector’s Name Sumner Gary Hunnewell

Date 10 December A. D. 2021

SONS OF UNION VETERANS OF THE CIVIL WAR  
CIVIL WAR MEMORIAL ASSESSMENT FORM  
ADDENDUM – NARRATIVE

[Generally used to record the text of monuments, but may be used for any other useful information, such as if the monument has been moved or if you have information about the day of dedication. May repeat use of page as often as necessary.]

The Memorial is *currently* located at:

Street/Road address or site location Union Pacific Railroad Property next to the Overton Bottoms Conservation Area, off of Rochport Road. GPS Coordinates close to N38°58.006' W92°38.314

City/Village and/or Township Saline Township / Woodridge

County Cooper State MO Zip Code 65287

TEXT

NO RESPASSÉ  
Property of  
Union Pacific Railroad

THE BATTLE OF BODINVILLE  
BEGAN HERE JUNE 17 1861  
GEN. LYON COMMANDER  
OF THE UNION FORCES



THE BATTLE OF BUNNELL  
BUNNELL WAS THE BATTLE  
GENERAL BUNNELL COMMANDER  
OF THE BATTLE OF BUNNELL

UNDEVELOPED  
PROPERTY

# BOONVILLE

WEDNESDAY, SEPTEMBER 15, 2021 | BOONVILLEDAILYNEWS.COM

## DAILY NEWS

PART OF THE USA TODAY NETWORK

### BOONVILLE MONUMENT DEDICATION



Bryan Bradford, CC , Robert Aubuchon, PCC , Martin Aubuchon, PDC , Charles Strastmann in front. James Dixon, PCC and Larry Dietzel, PDC to the back. SUBMITTED PHOTO

### Honoring a forgotten past

On Sunday afternoon while many families were enjoying their Labor Day holiday, there were a select few who were honoring a forgotten past along the Cliffside Southeast of Boonville.

"Ann Hawkins Gentry Tent #21, Daughters of Union Veterans of the Civil War and Tiger Camp, Sons of Union Veterans of the Civil War sponsored moving the monument commemorating the 1st Battle of Boonville away from the railroad track to a more suitable location while still on the historic property. Bryan Bradford, commander of Tiger Camp and Mary Ellen McVicker, President of Daughters of Union Veterans, conducted a joint dedication ceremony of the monument being moved. It was originally erected in 1928 by the Grand Army of the Republic which is no longer in existence in Missouri due to the death of all Civil War veterans. The monument was cleaned and restored before it was moved."

In June 1861, the forces of Gov. Claiborne Fox Jackson, The Missouri State Guard, were encamped upon

See DEDICATION, Page 3A

### Dedication

Continued from Page 1A

the bluff just to the East of Boonville in what was called Camp Bacon. After the affair at Camp Jackson near St. Louis, the Governor and the Guard fled Jefferson City and were using this camp as a rendezvous to mass forces and defend the state against the invading Union troops of Gen. Nathaniel Lyon. When Gen. Lyon arrived at Jefferson City he took two steamboats up river towards Boonville, when they arrived to the south of town they had spotted what they believed to be cannons on the bluff below the city. Lyon ordered the boats go back down to the landing where the Rocheport Rd came down to the river. From this point, Lyon's troops marched

up the steep road to the point where skirmishers were making contact 2 miles up the road.

The Battle of Boonville was very quickly decided and with a Union victory, secured the Missouri River Valley for the Union. 93 years ago in 1928, the Grand Army of the Republic, John A. Hayn Post #240 set a stone marker along the Union Pacific tracks at the point where the Rocheport Rd starts up to the bluffs. This marker reads, "The Battle of Boonville began here June 17, 1861 Genl. Lyon Commander of the Union Forces" and "Erected by the G.A.R. Post of Boonville 1928".

The marker had been in a state of disrepair, and with the help of the Sons and Daughters of the Missouri River Monument Company it is now on a new base and moved away from the tracks to more safer ground.



NATIONAL ORGANIZATION  
SONS OF UNION VETERANS OF THE CIVIL WAR  
CIVIL WAR MEMORIAL ASSESSMENT FORM

Type of Memorial (check all applicable)

\_\_\_ Monument \_\_\_ with Sculpture \_\_\_ without Sculpture \_\_\_ with Cannon \_\_\_ standalone Cannon  
\_\_\_ Historical Marker \_\_\_ Plaque \_\_\_ Other ( flag pole, G.A.R. buildings, stained glass windows, etc.)

Affiliation

\_\_\_ GAR \_\_\_ MOLLUS \_\_\_ SUVCW \_\_\_ WRC \_\_\_ ASUVCW  
\_\_\_ LGAR \_\_\_ DUVCW \_\_\_ Other

If known, record name and number of post, camp, corps, auxiliary, tent, circle or appropriate information of other groups:  
GAR John A. Hayn Post 240 Boonville

Original Dedication Date 1928 Please consult any/all newspaper archives for a local paper's article that would have information on the first dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

Location

The Memorial is currently located at:

Street/Road address or site location Union Pacific Railroad Property next to the Overton Bottoms Conservation Area, off of Rochport Road. GPS Coordinates close to N38°58.006' W92°38.314

City/Village &/or Township Saline Township / Woodridge

County Cooper State MO Zip Code 65287

The front of the Memorial faces: \_\_\_ North \_\_\_ South \_\_\_ East \_\_\_ West

Government Body, Agency, or Individual Owner

Name Union Pacific Railroad

Dept./Div. \_\_\_\_\_

Street Address 1400 Douglas Street

City Omaha State NE Zip Code 68179

Contact Person \_\_\_\_\_ Telephone (888 ) 870-8777 ext \_\_\_\_\_

Is Memorial on the National Register of Historic Places \_\_\_ Yes \_\_\_ No ID # if known \_\_\_\_\_

For Monuments with/without sculpture:

Physical Details

Material of Monument or base under a Sculpture or Cannon = \_\_\_ Stone \_\_\_ Concrete \_\_\_ Metal \_\_\_ Other

If known, name specific material (color of granite, marble, etc.) \_\_\_\_\_

Material of the Sculpture \_\_\_ Stone \_\_\_ Concrete \_\_\_ Metal \_\_\_ Other Is it hollow or solid? \_\_\_\_\_

If known, name specific material (color of granite, marble, etc.) \_\_\_\_\_



**Environmental Setting**

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

**Type of Location**

Cemetery       Park       Plaza/Courtyard       "Town Square"       Post Office  
 School       Municipal Building       State Capitol       Courthouse       College Campus  
 Traffic Circle       Library      Other: Conservation Area

**General Vicinity**

Rural (low population, open land)       Suburban (residential, near city)       Town       Urban / Metropolitan

**Immediate Locale** (check as many as may apply)

Industrial       Commercial       Street/Roadside within 20 feet       Tree Covered (overhanging branches)  
 Protected from the elements (canopy or enclosure, indoors)       Protected from the public (fence or other barrier)

Any other significant environmental factor Should be protected from the Missouri River flooding by the raised bed of the railroad tracks.

[To detail the condition of a monument used the addendum form for *Monument's Condition*]

**Supplemental Background Information**

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment.

Addendums attached to this electronic file are the *Monument's Condition* and the *Narrative* forms. Only the *Monument's Condition* form is required if you are requesting grant money using form CWM-62 *SUVCW Memorial Grant Form and Instructions*.

Thank you.

Inspector Identification \_\_\_\_\_ Date of On-site Survey 5 September A. D. 2021  
 Your Name Sumner Gary Hunnewell  
 Address 2030 San Pedro Drive  
 City Arnold State MO Zip Code 63010  
 Telephone (636 ) 464-3856 E-Mail HildifonsTook@prodigy.net

Are you a member of the Allied Orders of the G.A.R.? If so, which one?

SUVCW

Please send this completed form to:

Walt Busch, PDC, Chair  
 1240 Konert Valley Dr.  
 Fenton, MO 63026  
 (314) 630-8407  
 webusch@hotmail.com

Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War - Civil War Memorials Committee.

**SONS OF UNION VETERANS OF THE CIVIL WAR  
CIVIL WAR MEMORIAL ASSESSMENT FORM  
ADDENDUM – MONUMENT’S CONDITION**

Completion of this form is required when requesting grant money using form CWM-62 *SUVCW Memorial Grant Application Form and Instructions.*

**Condition Information**

**Structural Condition** (check as many as may apply)

The following section applies to Monuments with Sculpture, and Monuments without Sculpture including the base for Monuments with Cannon. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	<b>Sculpture</b>	<b>Base</b>
If hollow, is the internal support unstable/exposed? <small>(Look for signs of exterior rust)</small>	_____	_____
Any evidence of structural instability? <small>(Look for cracked joints, missing mortar or caulking or plant growth)</small>	_____	_____
Any broken or missing parts? <small>(Look for elements (i.e., sword, musket, hands, arms, etc. - missing due to vandalism, fluctuating weather conditions, etc.)</small>	_____	_____
Any cracks, splits, breaks or holes? <small>(Also look for signs of uneven stress &amp; weakness in the material)</small>	_____	_____

**Surface Appearance** (check as many as may apply)

	<b>Sculpture</b>	<b>Base</b>
Black crusting	_____	_____
White crusting	_____	_____
Etched, pitted, or otherwise corroded (on metal)	_____	_____
Metallic staining (run-off from copper, iron, etc.)	_____	_____
Organic growth (moss, algae, lichen or vines)	_____	_____
Chalky or powdery stone	_____	_____
Granular eroding of stone	_____	_____
Spalling of stone (surface splitting off)	_____	_____
Droppings (bird, animal, insect remains)	_____	_____
Other (e.g., spray paint graffiti) - Please describe...	_____	_____

Does water collect in recessed areas of the Memorial?  Yes  No  Unable to tell

**Surface Coating**

Does there appear to be a coating?  Yes  No  Unable to determine

If known, identify type of coating.

Gilded  Painted  Varnished  Waxed  Unable to determine

Is the coating in good condition?  Yes  No  Unable to determine

**Basic Surface Condition Assessment** (check one)

In your opinion, what is the general appearance or condition of the Memorial?

Well maintained  Would benefit from treatment  In urgent need of treatment  Unable to determine

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) .

*The monument was moved from near the Union Pacific Railroad tracks and a new base was created for it.*

Inspector’s Name Sumner Gary Hunnewell

Date 10 December A. D. 2021

SONS OF UNION VETERANS OF THE CIVIL WAR  
CIVIL WAR MEMORIAL ASSESSMENT FORM  
ADDENDUM – NARRATIVE

[Generally used to record the text of monuments, but may be used for any other useful information, such as if the monument has been moved or if you have information about the day of dedication. May repeat use of page as often as necessary.]

The Memorial is *currently* located at:

Street/Road address or site location Union Pacific Railroad Property next to the Overton Bottoms Conservation Area, off of Rochport Road. GPS Coordinates close to N38°58.006' W92°38.314

City/Village and/or Township Saline Township / Woodridge

County Cooper State MO Zip Code 65287

TEXT



Material of the Sculpture = \_\_\_ Stone \_\_\_ Concrete \_\_\_ Metal \_\_\_ Undetermined

If known, name specific material (color of granite, marble, etc.) \_\_\_\_\_

If the Sculpture is of metal, is it solid cast or "hollow?" \_\_\_\_\_

Material of Plaque or Historical Marker / Tablet ± Limestone? \_\_\_\_\_

Material of Cannon = \_\_\_ Bronze \_\_\_ Iron - Consult known Ordnance Listing to confirm

Markings on muzzle = \_\_\_\_\_

Markings on Left Trunion \_\_\_\_\_ Right Trunion \_\_\_\_\_

Is inert ammunition a part of the Memorial? \_\_\_ If so, describe \_\_\_\_\_

\_\_\_\_\_

**Approximate Dimensions** (indicate unit of measure) - taken from tallest / widest points

Monument or Base: Height 35" Width 27" Depth 13.5" or Diameter \_\_\_\_\_

Sculpture: Height \_\_\_\_\_ Width \_\_\_\_\_ Depth \_\_\_\_\_ or Diameter \_\_\_\_\_

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

**Markings/Inscriptions** (on stone-work / metal-work of monument, base, sculpture)

Maker or Fabricator mark / name? If so, give name & location found \_\_\_\_\_

\_\_\_\_\_

The "Dedication Text" is formed: X cut into material \_\_\_ raised up from material face

Record the text (indicate any separation if on different sides...) Please use additional sheet if necessary.

Front of Marker: "The Battle of Boonville began here June 17, 1861 Genl. Lyon Commander of the Union Forces"

Back of Marker: "Erected by the G.A.R. Post of Boonville 1928"

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Environmental Setting**

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

**Type of Location**

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Cemetery           | <input type="checkbox"/> Park           | <input type="checkbox"/> Plaza/Courtyard |
| <input type="checkbox"/> "Town Square"      | <input type="checkbox"/> Post Office    | <input type="checkbox"/> School          |
| <input type="checkbox"/> Municipal Building | <input type="checkbox"/> State Capitol  | Other: <u>Field</u>                      |
| <input type="checkbox"/> Courthouse         | <input type="checkbox"/> College Campus | <u>Railroad right of way</u>             |
| <input type="checkbox"/> Traffic Circle     | <input type="checkbox"/> Library        | _____                                    |

**General Vicinity**

- Rural (low population, open land)                       Suburban (residential, near city)  
 Town     Urban / Metropolitan

**Immediate Locale** (check as many as may apply)

- Industrial     Commercial  
 Street/Roadside within 20 feet     Tree Covered (overhanging branches)  
 Protected from the elements (canopy or enclosure, indoors)  
 Protected from the public (fence or other barrier)  
 Any other significant environmental factor \_\_\_\_\_

**Condition Information**

**Structural Condition** (check as many as may apply)

The following section applies to Monuments *with* Sculpture, and Monuments without Sculpture - including the base for Monuments with *Cannon*. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	<b>Sculpture</b>	<b>Base</b>
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	_____	_____
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth)	_____	_____
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc. - missing due to vandalism, fluctuating weather conditions, etc.)	_____	_____
Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)	_____	_____

**Surface Appearance** (check as many as may apply)

	<b>Sculpture</b>	<b>Base</b>
Black crusting	_____	_____
White crusting	_____	_____
Etched, pitted, or otherwise corroded (on metal)	_____	_____
Metallic staining (run-off from copper, iron, etc.)	_____	_____
Organic growth (moss, algae, lichen or vines)	_____	<input checked="" type="checkbox"/>
Chalky or powdery stone	_____	_____
Granular eroding of stone	_____	<input checked="" type="checkbox"/>
Spalling of stone (surface splitting off)	_____	_____
Droppings (bird, animal, insect remains)	_____	_____
Other (e.g., spray paint graffiti) - Please describe...	_____	_____

The back of monument has 6 to 8 impact areas of missing stone in the area of inscription.

Damage likely caused by firearm bullet impacts. Lower left rear corner of monument missing 4" x 6" area.

Back of monument is cracked in the middle running horizontally across but did not appear to penetrate.

Does water collect in recessed areas of the Memorial?     Yes     No     Unable to tell



**Surface Coating**

Does there appear to be a coating? \_\_\_ Yes  No \_\_\_ Unable to determine  
 If known, identify type of coating.

\_\_\_ Gilded \_\_\_ Painted \_\_\_ Varnished \_\_\_ Waxed \_\_\_ Unable to determine

Is the coating in good condition? \_\_\_ Yes \_\_\_ No \_\_\_ Unable to determine

**Basic Surface Condition Assessment** (check one)

In your opinion, what is the general appearance or condition of the Memorial?

\_\_\_ Well maintained \_\_\_ Would benefit from treatment  In urgent need of treatment \_\_\_ Unable to determine

**Overall Description**

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).  
 The marker is out of level due to foundation missing and broken. Damage and crack should be repaired along  
 with an area clean up

Photos 6/3/2011 by Walt Busch

**Supplemental Background Information**

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

**Inspector Identification**

Date of On-site Survey March 13, 2011

Your Name Larry Dietzel TIGER CAMP 432

Address 920 West Broadway City Columbia

State MO Zip Code 65203 Telephone ( 573 ) 449-6443

Please send this completed form to:

Bruce B. Butgereit, PDC, Chair  
 1691 Summerfield Street, SE  
 Grand Rapids, MI 49508-6499  
 (616) 827-3369  
 civil-war@comcast.net

Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR  
 National Civil War Memorials Committee









RECTED BY THE  
G. I.  
OF EMMVILLE  
1826

ERECTED BY THE  
G. L. S.  
POINT OF BURNVILLE  
1922









NO RESPAKIE  
Property of  
Union Pacific Railroad

THE BATTLE OF BODENVILLE  
BEGAN HERE JUNE 17 1861  
GEN. LYON COMMANDER  
OF THE UNION FORCES

