

Material of the Sculpture = ___ Stone ___ Concrete Metal ___ Undetermined
 If known, name specific material (color of granite, marble, etc.) _____
 If the Sculpture is of metal, is it solid cast or "hollow?" Brass

Material of Plaque or Historical Marker / Tablet = _____

Material of Cannon = ___ Bronze ___ Iron - Consult known Ordnance Listing to confirm
 Markings on muzzle = _____
 Markings on Left Trunion _____ Right Trunion _____
 Is inert ammunition a part of the Memorial? ___ If so, describe _____

Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points

Monument or Base: Height 4 ft Width 3 1/2 ft Depth 3 1/2 ft or Diameter _____
 Sculpture: Height 10 ft Width 18 inches Depth 16 inches or Diameter _____

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture)

Maker or Fabricator mark / name? If so, give name & location found North side base of sculpture

"Manufactured by "The W.H. Mullins Co., Salem, Ohio, USA" on riveted plate

The "Dedication Text" is formed: ___ cut into material raised up from material face

Record the text (indicate any separation if on different sides...) Please use additional sheet if necessary.

East side: Base has brass plate with GAH Medal on it.

South Side: Erected by Post and People of Laclede 1915

West Side: Blank

North Side: Musterd 1882 In Memory of Phil Kearny Post No. 19 Dept of Mo. GAR

Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

Type of Location

<input checked="" type="checkbox"/> Cemetery	___ Park	___ Plaza/Courtyard
___ "Town Square"	___ Post Office	<input checked="" type="checkbox"/> School
___ Municipal Building	___ State Capitol	Other: _____
___ Courthouse	___ College Campus	_____
___ Traffic Circle	___ Library	_____

General Vicinity

- Rural (low population, open land) ___ Suburban (residential, near city)
 ___ Town ___ Urban / Metropolitan

Immediate Locale (check as many as may apply)

- ___ Industrial ___ Commercial
 ___ Street/Roadside within 20 feet ___ Tree Covered (overhanging branches)
 ___ Protected from the elements (canopy or enclosure, indoors)
 ___ Protected from the public (fence or other barrier)
 Any other significant environmental factor _____

Condition Information

Structural Condition (check as many as may apply)

The following section applies to Monuments *with* Sculpture, and Monuments without Sculpture - including the base for Monuments with *Cannon*. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	___	___
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth)	___	___
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc. - missing due to vandalism, fluctuating weather conditions, etc.)	Sword ___	___
Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)	Sword ___	___

Surface Appearance (check as many as may apply)

	Sculpture	Base
Black crusting	___	___
White crusting	___	___
Etched, pitted, or otherwise corroded (on metal)	___	___
Metallic staining (run-off from copper, iron, etc.)	___	___
Organic growth (moss, algae, lichen or vines)	___	___
Chalky or powdery stone	___	___
Granular eroding of stone	___	___
Spalling of stone (surface splitting off)	___	___
Droppings (bird, animal, insect remains)	___	___
Other (e.g., spray paint graffiti) - Please describe...	___	___

Sword appears to be an original militia type plated over. Plate on the blade is missing causing blade to rust. Otherwise in good condition.

Does water collect in recessed areas of the Memorial? ___ Yes ___ No Unable to tell

Surface Coating

Does there appear to be a coating? Yes No Unable to determine

If known, identify type of coating.

Gilded Painted Varnished Waxed Unable to determine

Is the coating in good condition? Yes No Unable to determine

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?

Well maintained Would benefit from treatment In urgent need of treatment Unable to determine

Overall Description

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) .

In right had is a copper or brass clad (real) sword. The clading is peeling from the sword blade which is pitted and very rusty.

There is some splitting and cracking on flag pole.

Flower pot in front of Monument

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification


Date of On-site Survey 3 July 2008

Your Name Walter E Busch, US Grant Camp 68



Please send this completed form to:

Todd A. Shillington, PDC



Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR
National Civil War Memorials Committee





ERECTED
BY
POST
AND
PEOPLE
OF
LAUREL
1915







MUSTERED 1882

IN
MEMORY
OF PHIL
KEARNY
POST
NO. 19
DEPT. OF
WAR







**VANDALISM DONE
IN SUMMER 2021
APPARENTLY TRUCK
USING TOW STRAP**







ERECTED BY
POST
AND
PEOPLE
OF
LAFAYETTE
1911











ERECTED
BY
POST
AND
PEOPLE
OF
LACLSDE
1915






MUSTERED 1862

IN
MEMORY
OF PHIL
KEARNEY
CAPT
NO 10
DEPT OF
MD & A





**IN STORAGE 2022
AT LOCAL WELDING
SCHOOL
AWAITING REPAIRS**

















The following pictures
recieved from Pete
Oetting on
01/22/2025



MUSTERED 1882

IN
MEMORY
OF PHIL
KEARNEY
POST
NO. 19
DEPT. OF
MUNICIPAL









MANUFACTURED BY
THE W. H. MULLINS CO.
SALEM, OHIO, U. S. A.

2025 Updated Pictures of Soldier in Storage













