FORM CWM #61 Page 1 of 4

NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- 1. Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- 2. Do not guess at the information. An answer of, "Unknown," is more helpful. .Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial Monument with Sculpture Monument without Sculpture Other (flag pole, G.A.R. buildings, stained glass windows, etc.) Type of Memorial Monument with Cannon Historical Marker Plaque Other (flag pole, G.A.R. buildings, stained glass windows, etc.)			
Affiliation			
Original Dedication Date July 4, 1902 Please consult any/all newspaper archives for a local paper's article that would have information on the <i>first</i> dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you. Location			
The Memorial is currently located at: Street/Road address or site location Sunrise Highway & Madison Avenue City/Village Freeport Township County Nassau State New York			
The front of the Memorial faces: North South E East West Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in) Name Don't /Div			
Dept./DivStreet AddressCity StateZip CodeContact Person Telephone () If the Memorial has been moved, please list former location(s).			
ii tile Memoriai rias beeri moveu, piease list former location(s).			

FORM CWM #61 Page 2 of 4

Physical Details

Material of Monument or base under a Sculpture or Cannon =Stone Concrete _xxx Metal Undetermined If know name specific material (color of granite, marble, etc.)						
SUVCW CIVIL WAR						
Material of the Sculpture = St If known, name specific material (could be sculpture is of metal, is it so	olor of granite, marble, etc.)					
Material of Plaque or Historical Ma	Material of Plaque or Historical Marker / Tablet = Metal					
Material of Cannon =Bronze _ Markings on muzzle =Unable to read. F Markings on Left Trunion P RBH Is inert ammunition a part of the M	××× Iron - Consult known Ordnan	ce Listing to confirm				
Markings on Left Trunion P RBH	Right Trunion 18	63 30 PDR				
Is inert ammunition a part of the M	Memorial? <u>№</u> If so, describe _					
Approximate Dimensions (indicated) Monument or Base: Height 30" Sculpture: Height Width	ate unit of measure) - taken from _ Width 22" Depth 49" Depth 9' long or Diame	tallest / widest points or Diameter ter _ ^{18"}				
For Memorials with multiple Sculp for each statue and attach to this weapons/implements involved (in	form. Please describe the "pose'	' of each statue and any				
Markings/Inscriptions (on stone- Maker or Fabricator mark / name? I						
The "Dedication Text" is formed: _	cut into material <u>×××</u> raised ι	up from material face				
Record the text (indicate any separativity was trophy gun 30 PDR. PARROTT R	IFLE 240 FROM USS HARTFORD PRESENTED	•				
VILLAGE OF FREEPORT BY THE UNITED STA MOUNTED JULY 4TH 1902	ATES NAVY DEPARTMENT					
Environmental Setting (The general vicinity and immediate locale stype of Location	surrounding a memorial can play a major	role in its overall condition.)				
Comotony	Park	Plaza/Courtyard				
Cemetery "Town Square"	Post Office	Plaza/Courtyard School				
Municipal Building	State Capitol	Other: Traffic Triangle				
Courthouse	College Campus	<u> </u>				
Traffic Circle	Library					

FORM CWM #61 Page 3 of 4

General Vicinity Rural (low population, open land) Town	Suburban (residen Urban / Metropolita	• ,
Immediate Locale (check as many as may apply) Industrial xxx Commercial xxx Street/Roadside within 20 feet xxx Tree Covered (compressed from the elements (canopy or enclosure, incompressed from the public (fence or other barrier) Any other significant environmental factor	loors)	
Condition Information		
Structural Condition (check as many as may apply)		
The following section applies to Monuments with Sculpture, and including the base for Monuments with Cannon. Instability in the number of factors. Indicators may be obvious or subtle. Visually	sculpture and its base can	be detected by a
If hollow, is the internal support unstable/exposed? (Look for signs of exterior rust) Any evidence of structural instability? (Look for cracked joints, missing mortar or caulking or plant greater and problem or missing parts? (Look for elements (i.e., sword, musket, hands, arms, etc midue to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes? (Also look for signs of uneven stress & weakness in the material	ssing	Base
Surface Appearance (check as many as may apply)		
Black crusting White crusting Etched, pitted, or otherwise corroded (on metal) Metallic staining (run-off from copper, iron, etc.) Organic growth (moss, algae, lichen or vines) Chalky or powdery stone Granular eroding of stone Spalling of stone (surface splitting off) Droppings (bird, animal, insect remains) Other (e.g., spray paint graffiti) - Please describe Some rust showing where paint is wearing away. Debris is inside of the base. Unable to the base has split open.	Sculpture XXX	Base ast corner of
Does water collect in recessed areas of the Memorial?	Yes XXX No Unable	e to tell

FORM CWM #61 Page 4 of 4

Surface	Coating
---------	---------

Does there appear to be a coating? <u>xxx</u> Yes No Unable to determine If known, identify type of coating.					
Gilded XXX Painted Varnished Waxed Unable to determine					
Is the coating in good condition? Yes xxx No Unable to determine					
Basic Surface Condition Assessment (check one)					
In your opinion, what is the general appearance or condition of the Memorial? Well maintainedXXX Would benefit from treatment In urgent need of treatment Unable to determine					
Overall Description					
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). The cannon and its base is in need of a fresh coat of paint. The weld should be repaired. However, the base seems structurally sound.					
Repair is needed, but not urgent. A tool would be needed to clean out the debris and leaves from the base underneath the cannon.					

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-site Survey April 30, 2018	
Your Name Christopher Shand	•
Address 1854 Old Mill Road	City Merrick
State NY Zip Code 11566 Telepho	one (
What Order or Organization is submitter a member	r of? Moses A. Baldwin Camp #544, SUVCW

Please send this completed form to

Walt Busch, PDC, Chair



Thank you for your help, and attention to detail. Sons of Union V

CIVIL WAR VETERANS OF THE National Civil War Memorials Committee





















