FORM CWM #61

Page 1 of 4

### NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

## CIVIL WAR MEMORIAL ASSESSMENT FORM

#### PLEASE:

1. Type or print, using a ball-point pen, when filling out this form. Legibility is critical.

 Do not guess at the information. An answer of, "Unknown," is more helpful. .Include a photograph of each viewable side and label it with name & direction of view.

- Thank You. Type of Memorial \_\_\_ Monument with Sculpture Monument with Cannon Monument without Sculpture \_\_ Historical Marker \_\_ Plaque Other ( flag pole, G.A.R. buildings, stained glass windows, etc.) Affiliation G.A.R. (Post Name & No.\_\_\_\_ M.O.L.L.U.S \_\_ SUVCW (Camp Name & No.\_\_\_\_ (Please describe below) WRC (Corps Name & No.\_\_\_\_ \_\_ ASUVCW (Aux Name & No.\_\_\_\_ DUVCW (Tent Name & No.\_\_\_\_ LGAR (Circle Name & No. Other \_\_\_\_ Original Dedication Date Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you. Location The Memorial is currently located at: N34° 47 13.63N / W.91° 27' 22.49 Street/Road address or site location PARKING ARER - BOAT RAND City/Village DECIALS BLUE Township County PRAIRE State AR. The front of the Memorial faces: \_\_\_ North \_\_\_ South \_\_ East \_\_ West unknown Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in) Name Dept./Div. Street Address Contact Person Telephone ( ) \_\_\_ If the Memorial has been moved, please list former location(s).

## **Physical Details**

>This form may be photocopied.<

Material of Monument or base under a Sculpture or Cannon =StoneConcreteMetalUndetermined If known, name specific material (color of granite, marble, etc.)			
SUVCW CIVIL WAR			
Material of the Sculpture =StoneConcreteMetalUndetermined If known, name specific material (color of granite, marble, etc.)  If the Sculpture is of metal, is it solid cast or "hollow?"			
Material of Plaque or Historical Marker / Tablet =			
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle =			
Markings on muzzle =			
Is inert ammunition a part of the Memorial? If so, describe			
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points  Monument or Base: Height Width Depth or Diameter  Sculpture: Height Width Depth or Diameter			
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!			
Markings/inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found			
The "Dedication Text" is formed: cut into material raised up from material face			
Record the text (indicate any separation if on different sides) Please use additional sheet if necessary.			
SEE ATTACHED PHOTOS.			
Environmental Setting (The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)  Type of Location			
Cemetery  "Town Square"  Municipal Building  Courthouse  Traffic Circle  Park  Post Office  School  Other:  College Campus  BOAT PAND  Library			

©2007-2011 Sons of Union Veterans of the Civil War, a Corporation.

Company 1 to 1				
General Vicinity				
Rural (low population, open land)				
Town	Suburban (residentia	l near city		
	Urban / Metropolitan	, . roar city)		
Immediate Locale (-b	modopontari			
Immediate Locale (check as many as may apply)				
Industrial Commercial				
Street/Roadside within 20 foot				
Protected from the elements (canopy or enclosure, indo	erhanging branches)			
Protected from the elements (canopy or enclosure, indo	ors)			
Protected from the public (fence or other barrier)	,			
Any other significant environmental factor with				
WITH IN	J PARKING LOT			
		Contract of the Contract of th		
		Minima con additional and a second		
Condition		The second secon		
Condition Information				
Structural Condition (check as many as may apply)				
The following and apply)				
	Milmonto salda			
including the base for Monuments with Cannon, Instability in the po	ridinents without Sculpture -			
including the base for Monuments with Sculpture, and Monuments with Cannon. Instability in the sc number of factors. Indicators may be obvious or subtle. Visually ex-	ulpture and its base can be d	etected by a		
number of factors. Indicators may be obvious or subtle. Visually exa	amine the sculpture and its bi	ase.		
If hollow, is the internal support unstable/exposed?	Sculpture	Base		
(Look for signs of exterior rust)				
Any evidence of structural instability?	T	Addressance		
(Look for cracked joints, mission				
(Look for cracked joints, missing mortar or caulking or plant growth Any broken or missing parts?	7)	Muselmaniphilipsyde		
(Look for elements (i.e. august				
(Look for elements (i.e., sword, musket, hands, arms, etc missin due to vandalism, fluctuating weather conditions, etc.)  Any cracks splite breaks	9	***************************************		
Any cracks, splits, breaks or holes?				
(Also look for nigers of Holes /				
(Also look for signs of uneven stress & weakness in the material)	dering processed abuses.	APPROXIMATION .		
Surface Appearance (-1-1				
Surface Appearance (check as many as may apply)				
Di	0-1-1			
Black crusting	Sculpture	Base		
White crusting	- Ampliment and applications of the Control of the			
Etched, pitted, or otherwise corroded (on metal)	***************************************	1403400000000000		
Metallic staining (are of female)		Militaria de la compansión de la compans		
Metallic staining (run-off from copper, iron, etc.)	- Control of Control o	Managhan.		
Organic growth (moss, algae, lichen or vines)	*MATISTAN REPORT OF THE PROPERTY OF THE PROPER	Characteristic		
Chairy of powdery stone	Additional acceptance			
Granular eroding of stone	Финосоположения			
Spalling of stone (surface splitting off)				
Propriess (hind surface splitting off)		NAME OF THE PARTY		
Oroppings (bird, animal, insect remains)	#Minophila (unique magine	AND PROPERTY.		
Other (e.g., spray paint graffiti) - Please describe	With block works.	APPENDING CONTRACTOR OF THE PERSON OF THE PE		
,				
		MARING COMMANDED.		
		SAMMA SA		
		CONTRACTOR OF THE PROPERTY OF		
Does water collect in recessed areas of the Memorial?	No.	2		
Does water collect in recessed areas of the Memorial?Yes No Unable to tell				

	Page 4 of 4
Surface Coating	
Does there appear to be a coating?Yes No Unable to determine If known, identify type of coating Gilded Painted Varnished Waxed Unable to determine Is the coating in good condition? Yes No Unable to determine	
Basic Surface Condition Assessment (check one)	
In your opinion, what is the general appearance or condition of the Memorial? Well would benefit from treatment In urgent need of treatment Unable to determine	l maintained
Overall Description	
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on)	
	MONROPERSON
	Jamesongulga,
	Microscope
Supplemental Background Information	GSSubmuggs
In addition to your on-site survey, any additional information you can provide on the described will be welcomed. Please label each account with its source (author, title, publisher, date, include any reference to the points listed on this questionnaire, plus any previous conserver treatments - or efforts to raise money for treatment. Thank you.	ibed Memorial pages). Topics
Inspector Identification	
Date of On-site Survey 8-22-7 22  Your Name ELIC GIASER  Address 813A BECCHOOD) City LOTTE BOW  State All Zip Code 1220 Telephone ()  What Order or Organization is submitter a member of?	<b>Mac</b>
Please send this completed form to Jagac Muhalty (A	140 122
Walt Busch PDC Chair	

Thank you for your help, and attention to detail. Sons of Union V

CIVIL WAR VETERANS OF THE National Civil War Memorials Committee



# DeValls Bluff: A Major Union Riverport

Rising from the Boston Mountains, the White River meanders 720 miles to its junction with the Arkansas River in the southeastern part of the state. The fast-moving water kept the White River from suffering the build-up of silt that made such rivers as the Arkansas difficult to traverse for much of the year. The White River could accommodate deeper-draft vessels than most other rivers in the state.

With its tall bluffs towering over the White River, DeValls Bluff was easily defendable and became the most important port on the river during the Civil War. Union gunboats could easily travel to the town, providing security for the steamboats carrying supplies that would then be transferred for railroad transport to Little Rock.



The U.S.S. Signal, U.S.S. Romeo, U.S.S. Fawn and U.S.S. Marmora were some of the Union gunboats that piled the waters of the White River, seeking Confederate targets and protecting cargo and troop transports. Signal, courtesy Arkansas History Commission.



The steamboat Des Arc was moored at DeValls Bluff when cotton in her hold caught fire on March 22, 1864. The U.S.S. Signal towed her across the river to protect other vessels docked nearby and, when the flames grew out of control, sank her with cannon fire. The Des Arc was later raised and continued serving as a White River packet until 1871. Courtesy, Arkansas History Commission.



Steamboats carried cargo to DeValls Bluff, where it was shifted to the railroad. Here, the *Pocahontas*, Ella and Emma No. 2 are docked at DeValls Bluff. Courtesy, Arkansas History Commission.

This project is supported in part by a grant from the Arkansas Humanities Counand the Department of Arkansas Heritage. Other sponsors are the Arkansas Cival War Sesquicentermail Commission, the City of DeValls Bluff and the Bill & Sharen Araold Family Poundation.



Latitude

34° 47′ 13.63″ N

Longitude

91° 27′ 22.49″ W

0

o'" UTM MGRS



Accuracy: 53 ft

Last location age: 00:01





