East Cannon

National Organization

24MI2

Sons of Union Veterans of the Civil War Civil War Memorial Assessment Form

Please:

Type or print, using a ball-point pen, when filling out this form. Legibility is critical.

Do not guess at the information. An answer of, "Unknown", is more helpful.

Include a photograph of each viewable side and label it with name direction of view.

Type of Memorial:	- Thank You.
 ■ Monument with Sculpture ■ Monument without Sculpture ■ Historical Marker 	non Plaque
Affiliation:	
	mp or Tent information: Tent 30
Original Dedication Date Please consult any	/all newspaper archives for a
local paper's article that would have information on the first dedication memorial. Please submit a copy of your findings with full identification you.	
Location:	
The Memorial is currently located at:	
Street/Road address or site location Main St.	
City/Village: Sunfield Township: Sunfield	
The front of the memorial faces: North South E	
Government Body, Agency or Individual Owner (of private ceme Owner Name: Son's & Daughters UV.CW Dept or E Address: Mai) St.	
	Zip Code
	phone: 517-627-2777
Owner E-Mail: Imaves @netscape.net	
If the Memorial has moved, please list formaer location(s)	
Physical Details:	
Material of Monument or base under a Sculpture or Cannon	Stone 🔀 Concrete 🏻 Metal 🔻 Undetermined
If known, name the specific material (color of granite, marble, etc.):	Varity

Gen	OFO	11	lici	nit	,,
Gen	Cla	I V	161	1116	

■ Rural (low population, open land) ▼ Town	Suburban (residential, near city Urban/Metropolitan
Immediate Locale (check as many as may apply)	
■ Industrial	
Street/Roadside within 20 feet ■ Street/Roadside within 20 feet ■ ■ Street/Roadside within 20 feet ■	Tree covered (overhanging branches)
Protected from the elements (canopy or enclose	sure, indoors Other
Protected from the public (fence or other barrie	er
Any other significant environmental factor	

Condition Information

Structural Condition

(check as many as may apply)

The following section applies to Monuments with Sculpture, and Monuments without sculpture - including the base for monuments with cannon. Instability in the structure and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If Hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	8	₩
Any evidence of structural instability? (look for cracked joints, missing mortar or calking or plant growth)		
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc missing due to vandalism, fluctuating weather conditions, etc.)	₩	
Any cracks, splits, breaks or holes? (Also look for signs of uneven stress weakness in the material)	8	
Surface Appearance (check as many boxes as may	apply) Sculpture	Base
Black crusting	※	***
White crusting		
Etched, pitted, or otherwise corroded (on metal)	*	*
Metallic staining (run-off from copper, iron, etc.)	(%)	**
Organic growth (moss, algie, lichen or vines)	**	**
Chalky or powdery stone	(8)	
Granular eroding of stone	(8)	×
Spalling of stone (surface splitting off)	**	×
Droppings (bird, animal, insect remains)	**	×
Other (e.g., spray paint graffiti) - Please describe		
Sculpture:	Base:	
Does water collect in recessed areas of the Memorial	Yes 🔀 No 🗟 Unable to	o determine
This forms was the whaterenied	0.1007.0	

Surface Coating:

Does there appear to be a coating?

Yes No 🖾

If known, identify the type of coating.

☐ Gilded ☐ Painted ☐ Varnished ☐ Waxed ☐ Unable to determine

Is the coating in good condition?

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?

🖾 Well maintained 🗷 Would benefit from treatment 🖾 In urgent need of treatment 🖾 Unable to determine

Overall Description:

Briefly describe the Memorial (affiliation/overall condition any concern not already touched on).

Cannon Mounted on a stone sill, Supported by individual stone Tablets Identifing GAR members at time of prection of monument

Dedicated 30 Oct. 1900

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date pages). Topics include any reference to the points listed on this questionaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification:

Date of on-site survey: 9-27-99

Your Name:

LaVerne L. Aves

Street:

11740 Broadbent

City:

Lansing

State: Mi

zip code: 48917

home phone:

Please send the completed Civil War Memorial Record to :

Doug Armstrong

236 Frederick Ave

Lansing, MI 48906-3226

Thank you for your help, and attention to detail.

THE SUNFIELD CENTINEL DEC. 10, 1990

Here is a portion of the article as taken from the Ionia Sentinel of Oct. 25, 1899 as printed in the Portland Observer.

"The Grand Army Post at Sunfield thought it would be nice to have a couple of cannon which Dewey captured at Manila in their village. As they could have them by paying freight from San Francisco, to which point the government delivered them, they ordered them sent on. They received notice the other day that they were at Lansing—and they were glad. But when they knew the amount of freight charges they were sad—the figure was \$303. The guns weight 17,000 pounds."

The freight bill was more than one-third the cost of the hall itself. And the cannon may have languished in a freight yard for some months. But the post wanted the cannon and raised \$173, although how quickly is not indicated. Perhaps the railroad would wait only so long for its money. At any rate, Clark Richards, instrumental in building the hall, lent the post \$130 for the rest of freight charges and took a note. Bases for the cannon cost another \$80.

With the freight costs and installation costs, the cannon were not installed and dedicated until Oct. 30, 1900 - a full year after the dedication of the hall. Regrettably, how the cannon were moved into place is not recorded.

A claim against the railroad was entered for the three missing cannon ball-but the post minute book indicates the cannon balls were never located and the claim was never settled. Perhaps railroad officials were heartily tired of Sunfield's cannons. In due time the Post paid the note and burned it."

The cannons are Spanish in origin.

One cannon weighs 8,465 pounds and fired a 42 pound shot. The other cannon weights 7,200 pounds and fired a 32 pound shot. The government also agreed to send nine cannon balls with the cannon but only six were received.

