NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.

 Include a photograph of each viewable side and label it with name & direction of view. - Thank You. Type of Memorial × Monument with Sculpture Monument with Cannon Monument without Sculpture Historical Marker Plaque Affiliation X G.A.R. (Post Name & No. Major James Wilson Post 20 M.O.L.L.U.S. W.R.C. (Corps Name & No.____ Other Allied Order SUVCW (Camp Name & No._____ (Please describe below) DUVCW (Tent Name & No. Other: Original Dedication Date 1884 Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you. Location The Memorial is currently located at: Street/Road address or site location Riverview Cemetery W91°03'20" N39°27'26". City/Village Louisiana Township County Pike The front of the Memorial faces: North X South East West Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)... Name City of Louisiana Dept./Div. Cemetery Street Address N B St. (City Hall at 410 No 6th) City Louisiana State MO Zip Code 63353 Contact Person Bill Shade Telephone (573) 754-4176 If the Memorial has been moved, please list former location(s)... Not applicable Physical Details Material of Monument or base under a Sculpture or Cannon = ___Stone ___ Concrete X Metal Undetermined If known, name specific material (color of granite, marble, etc.) possibly zinc


Material of the Sculpture =StoneConcrete _X_MetalUndetermined If known, name specific material (color of granite, marble, etc.) possibly zincUndetermined If the Sculpture is of metal, is it solid cast or "hollow?" hollow							
Material of Plaque or Historical Marker / Tablet = n/a							
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle = n/a							
Markings on Left Trunion Right Trunion							
Markings on muzzle = _n/a Markings on Left Trunion Right Trunion Is inert ammunition a part of the Memorial? If so, describe							
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height 6 1/2 feet Width 7 feet Depth 7 feet or Diameter Sculpture: Height 5 1/2 feet Width 18 inch Depth 18 inch or Diameter							
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!							
Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found south face: Detroit Bronze Co. Detroit, Mich.							
The "Dedication Text" is formed: cut into material _X raised up from material face Record the text (indicate any separation if on different sides) Please use additional sheet if necessary.							
(South) Erected 1884, by Major James Wilson, Post No. 20 G.A.R. Department of Missouri. To all the brave defenders of the							
Union in 1861-1865. From the County of Pike, Mo. On fame's eternal camping ground, their silent tents are spread; and glory guards with							
solemn round, the bivouac of our dead. [Maker\ Detroit Bronze Co., Detroit Mich							
West Face: [Pic of Cav Soldier on Horse] William W. Scaggs Co. K 3rd Regt. M.S.M. Hollow Oley Co. K, 3rd Regt. M.S.M. Eternal Vigilance is the Eternal Price of Liberty.							
North Face: [Pic Drum & Flag] Walker W. Gourley Co. I 3rd Regt. M.S.M. William F. Evans Co. I 3rd Reg't M.S.M. One Country and One Flag.							
East Face [Pic of GAR Ribbon] John W. Shew Co I 3rd Reg't M.S.M. William C. Grotts Co. I 3rd Regt M.S.M. Fraternity - Charity - Loyalty							
[NOTE: Many think the soldiers named are buried there. They are not. Scaggs, Gourley, Shew and Grotts were murdered 3 Oct							
1864 with Major James Wilson. Evans died in fall from horse in 1862. Hollow Oley is probably known as John Holabaugh who was							
also murdered with Wilson.]							
Environmental Setting (The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)							
Type of Location							
X Cemetery Park Plaza/Courtyard							
"Town Square" Post Office School							
Municipal Building State Capitol Other:							
Courthouse College Campus							
Traffic Circle Library							

General Vicinity						
Rural (low population, open land) X Town	Suburban (residential, near city) Urban / Metropolitan					
	_ Orban / Wetropolitan					
Immediate Locale (check as many as may apply)	executeristati would					
Industrial Commercial						
X Street/Roadside within 20 feet	Tree Covered (overhang	ging branches)				
Protected from the elements (canopy or enclosed)	[4] [5] [6] [6] [6] [6] [6] [6] [6] [6] [6] [6					
Protected from the public (fence or other barrie						
Any other significant environmental factor						
Condition Information	4					
	200					
Structural Condition (check as many as may app	oly)					
The following section applies to Monuments with Sculp including the base for Monuments with Cannon. Instability in by a number of factors. Indicators may be obvious or subbase.	n the sculpture and its base ca	an be detected				
50	Sculpture	Base				
If hollow, is the internal support unstable/exposed?	no	no				
(look for signs of exterior rust)	137					
Any evidence of structural instability?	no no	no				
(look for cracked joints, missing mortar or caulking or plant grow	no no	Vec				
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc missi		yes				
due to vandalism, fluctuating weather conditions, etc.)	···g					
Any cracks, splits, breaks or holes?		repaired				
(also look for signs of uneven stress & weakness in the material)					
Surface Appearance (check as many as may app						
	Sculpture	Base				
Black crusting						
White crusting	-					
Etched, pitted, or otherwise corroded (on metal)						
Metallic staining (run-off from copper, iron, etc.)						
Organic growth (moss, algae, lichen or vines)						
Chalky or powdery stone						
Granular eroding of stone	-	-				
Spalling of stone (surface splitting off)						
Droppings (bird, animal, insect remains)	\$ 	With the same of t				
Other (e.g., spray paint graffiti) - Please describe. some wear on left hand and on front edge of frock coat. GAR Emblem b	 roken but repaired. Some bolts mis	sing				
Does water collect in recessed areas of the Memorial?	Yes _X_Nol	Jnable to tell				

Surface Co					
if known, ide	appear to be a coating? entify type of coating. Painted Varn		× No	Unable to det	ermine
Gilded Is the coating	X Unable to dete X Unable to dete				
In your opini	ce Condition Assessment on, what is the general applied X Would benefit from treat	nearance or	condition	of the Memorial?	etermine
Overall De	escription				
Generally well maint	e the Memorial (affiliation / over lained, but could use some clean up (replac	rall condition & a e a few missing bolts;	any concer	n not already touched or	ו) .
			- 4		
0.000					
In addition to y Memorial will I date, pages).	ntal Background Info your on-site survey, any add be welcomed. Please label Topics include any reference ervation treatments - or effor	ditional inform each account ce to the point	with its s	ource (author, title, pu	hlishas
	dentification				
Date of On-si	te Survey 17 August 2006				
Your Name _v	Valter E. Busch, Commander US Grant Car	np 68			
Please send t	this completed form to:				
Todd A. Shi	llington, PDC				

Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR National Civil War Memorials Committee




Postcard *Tichnor Quality Views* by Tichnor Bros, Inc, Boston, MA circa 1915-1950 [before showing zipcodes on the back of postcards]













This very old, very large cemetery is located in

Louisiana, MO in the eastern portion of Pike County, just 1 block off of Highway 79. It is still active.

Also see Riverview Burials.

Top Inscription: (Front) Erected 1884, by Major James Wilson, Post No. 20 G.A.R. Department of Missouri.

Middle Inscription:

(Front) To all the brave defenders of the Union in 1861-1865. From the County of Pike, Mo.

Around the sides: WILLIAM W. SCAGGS, Co. K 3rd, Regt. M. S. M. HOLLOW OLEY, Co. K 3rd Regt. M. S. M. JOHN W. SHEW, Co. 1 3rd Regt. M. S. M. WILLIAM C. GROTTS,

Co. 1 3rd Regt. M. S. M. WALKER W. GOURLEY Co. 1 3rd Regt. M. S. M. WILLIAM F. EVANS Co. 1 3rd Regt. M. S. M. Lower Inscription: (Front) On fame's eternal camping ground, their silent tents are spread; and glory guards with solemn round, the bivouac of our dead. Around the sides: Eternal

Around the sides:
Eternal
Vigilance is the Eternal Price of Liberty.
Fraternity,
Charity,
Loyalty
One Country
and One Flag.

Rívervíew Cemetery Louisiana, MO

If you have pictures you would like to share, forward them to <u>Rhonda Stolte Darnell</u>. Please include a transcription of the writing on the stone, where the stone is located, your name and a valid email address, in case she needs