## NATIONAL ORGANIZATION

## SONS OF UNION VETERANS OF THE CIVIL WAR

## CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:		
<ul> <li>Type or print, using a ball-point pen, whe</li> <li>Do not guess at the information. An answ</li> <li>Include a photograph of each viewable side</li> </ul>	n filling out this form. Lever of, "Unknown," is me and label it with name & d	egibility is critical. ore helpful. lirection of view.
Type of Memorial	à.	- Thank You.
Monument with Sculpture  Monument without Sculpture	Monument with (  Historical Marker	Cannon Plaque
<u>Affiliation</u>		
G.A.R. (Post Name & No	) ) ) ) ) )	Other Allied Order (Please describe below)
Original Dedication Date May 1996 local paper's article that would have information on the first de Please submit a copy of your findings with full identification of	Please consult any/all r	newspaper archives for a er facts on the memorial.
Location The Memorial is currently located at: W 90° 3 Street/Road address or site location 200 800 City/Village PLOT KNOS Township	127.07	112011
The front of the Memorial faces: North	SouthX Eas	tWest
Name IRON County HISTORICAL Society Street Address	private cemetery that Memo	orial is located in)
Contact Person	State <u>Ho</u> Zip Code	e 63650
NIA	Telephone (573)54	7 - 3512

## Physical Details

Material of Monument or base under a Sculpture or Cannon = \(\sum \) Stone \_\_\_ Concrete \_\_\_ Metal \_\_\_ Undetermined If known, name specific material (color of granite, marble, etc.) A -----

If the Memorial has been moved, please list former location(s)...

Telephone (573)546-3513

Material of the Sculpture = "/A If known, name specific material (c) If the Sculpture is of metal, is it s	olor of granite marble atc	1		(
Material of Plaque or Historical I				
Material of Cannon =Bronze  Markings on muzzle =  Markings on Left Trunion  Is inert ammunition a part of the	Iron Consult In	our Ourte	1	
	11 SO,	describe		
Approximate Dimensions (indice Monument or Base: Height 3 F Sculpture: Height Height From Hot: 2 FEET G	value Debu	or i	Diameter	
For Memorials with multiple Scusheet of paper for each statue as each statue and any weapons separated from this form). Thank	and attach to this form. Jimplements involved (i	Please dosc	ribo the "none" of	
Markings/Inscriptions (on stone Maker or Fabricator mark / name	IT SO GIVE name & loc	ation found 🗸	NOT SHOWN ON MONU	IMENT <sup>3</sup> .
The "Dedication Text" is formed face				
Record the text (indicate any separation	if on different sides) Please	e use additional	sheet if necessary.	
*T-0-1		,		
"THE BATTLE OF PLOT KNOR"	FACT			
				,
Environmental Setting				
The general vicinity and immediate locale su	arrounding a memorial can play a	a major role in its	overall condition.)	
Type of Location Cemetery "Town Square" Municipal Building Courthouse	Park Post Office State Capitol College Campus	S	Plaza/Courtyard School T: Residentia	
Traffic Circle	Library	-		

1/ -	Suburban (residential, i Urban / Metropolitan	near city)
Immediate Locale (check as many as may apply)  Industrial  Street/Roadside within 20 feet  Protected from the elements (canopy or enclosus Protected from the public (fence or other barrier)  Any other significant environmental factor		
	2	
Condition Information	:	
Structural Condition (check as many as may apply The following section applies to Monuments with Sculpture, an the base for Monuments with Cannon. Instability in the scul number of factors. Indicators may be obvious or subtle. Visually	d Monuments without Sculp pture and its base can be	detected by a
	Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)  Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth Any broken or missing parts?	) — <u> </u>	<u>No</u> <u>No</u> No
(look for elements (i.e., sword, musket, hands, arms, etc missing due to vandalism, fluctuating weather conditions, etc.)  Any cracks, splits, breaks or holes?  (also look for signs of uneven stress & weakness in the material)	<del> </del>	No
Surface Appearance (check as many as may apply	Sculpture	Base
Black crusting White crusting Etched, pitted, or otherwise corroded (on metal) Metallic staining (run-off from copper, iron, etc.) Organic growth (moss, algae, lichen or vines) Chalky or powdery stone Granular eroding of stone Spalling of stone (surface splitting off)		No No No No No
Droppings (bird, animal, insect remains) Other (e.g., spray paint graffiti) - Please describe		<i>No</i>
Does water collect in recessed areas of the Memorial?	Yes <u></u> No	Unable to tell

Surface Coating  Does there appear to be a coating? YesX_ No Unable to determine If known, identify type of coating.
Gilded Painted Varnished Waxed Unable to determined ls the coating in good condition? Yes No N/A Unable to determined
Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or condition of the Memorial?  X Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description  Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).  UERY (SOOD SNAPE. REINSPECTION EVERY 5 YEARS SNOWN BE  SUFFICIENT.
Supplemental Dealessand Lafe
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, published date, pages). Topics include any reference to the points listed on this questionnaire, plus are previous conservation treatments - or efforts to raise money for treatment. Thank you.  US Grant 68 MO SUVCW
Inspector Identification
Date of On-site Survey 05-03-2005
Your Name WALTER E. BUSCH
Places and the second s
Please send this completed form to:
PAUL LEISTRITZ

Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War National Civil War Memorials Committee Marker No. 12 -- Railroad Depot

Front of marker:

BATTLE OF PILOT KNOB RAILROAD DEPOT

Text:

From 1857 to 1871, Pilot Knob was the terminus of the St. Louis & Iron Mt. Railroad. During the war the supply depot located here supplied Union outposts at Patterson, Centerville, Farmington, and Fredericktown. The road to Middlebrook ran alongside the railroad between Cedar and Oak mountains. Slayback's Regiment camped near the road on the night of the 27th to guard against any attempts by the Union army to evacuate the fort and escape by this route.15

<sup>&</sup>lt;sup>15</sup>Iron County Historical Society, A History of Iron County, Missouri, 1857-1994 1, 36-37; Thompson, " The Great-Little Battle of Pilot Knob [Part I], 150; Suderow, Thunder in Arcadia Valley, 125







