NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- 1. Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- 2. Do not guess at the information. An answer of, "Unknown," is more helpful. Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial

Monument with Sculpture	nent with Sculpture N	
Monument without Sculpture	xx	Historical Marker Plaque
Other (flag pole, G.A.R. buildings, stained glass windo	ws,	etc.)

Affiliation

G.A.R. (Post Name & No)	M.O.L.L.U.S
SUVCW (Camp Name & No)	(Please describe below)
WRC (Corps Name & No)
ASUVCW (Aux Name & No)	
DUVCW (Tent Name & No)
LGAR (Circle Name & No)
Other Wilson's Creek National Battlefield	_

Original Dedication Date Unknown

Please consult any/all newspaper archives for a local paper's article that would have information on the first dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

Location

The Memorial is <i>currently</i> lo Street/Road address or site	Judieu al. Wilcon's	7.11163 W93.40226 Creek National Battlefie	d	
City/Village Springfield		County	Greene	•
State Missouri	 	·		
The front of the Memorial fa	aces: North	South East	_West	
Government Body, Agency, on Name Wilson's Creek N.B.	or Individual Owner	(of private cemetery that	Memorial is located in)	
Dept./Div. National Park Service				
	100			0.1

Street Address	6424 W Farm Rd 182	City
Republic	State MO Zip Code 65738	Contact Person
Superintendent	Telephone () 417-732-2662	

If the Memorial has been moved, please list former location(s).

N/A

Material of Monument or base under a Sculpture or Cannon =	_Stone	Concrete	Metal	Undetermined If known,
name specific material (color of granite, marble, etc.)				

SUVCW -- CIVIL WAR

Material of the Sculpture = ____ Stone ____Concrete ____ Metal ____ Undetermined If known, name specific material (color of granite, marble, etc.) _____ If the Sculpture is of metal, is it solid cast or "hollow?" ______

Material of Plaque or Historical Marker / Tablet = Metal and polymers

Material of Cannon =B	BronzeIron - Con	sult known Ordnance	e Listing to confirm
Markings on muzzle =			-
Markings on Left Trunion_		Right Trunion	
Is inert ammunition a part of	of the Memorial?	If so, describe	

Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height 4 ft Width 3 ft Depth 3 ft or Diameter _____ Sculpture: Height _____ Width ____ Depth ____ or Diameter _____

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found ______

The "Dedication Text" is formed: ____ cut into material ____ raised up from material face

Record the text (indicate any separation if on different sides) Please use additional sheet if necessary.

Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.) **Type of Location**

- Cemetery
- ____ "Town Square"
- ____ Municipal Building
- ____ Courthouse
 - Traffic Circle

<u>××</u> Park
Post Office
State Capitol
College Campus
Library

Plaza/Courtyard
School
Other:

>This form may be photocopied.<

©2007-2011 Sons of Union Veterans of the Civil War, a Corporation.

General Vicinity XX Rural (low population, open land) Town	Suburban (residential, near city) Urban / Metropolitan
Immediate Locale (check as many as Industrial Commercial Street/Roadside within 20 feet Protected from the elements (canop Protected from the public (fence o Any other significant environmental)	_ Tree Covered (overhanging branches) y or enclosure, indoors) r other barrier)

Condition Information

Structural Condition (check as many as may apply)

The following section applies to Monuments *with* Sculpture, and Monuments without Sculpture - including the base for Monuments with *Cannon*. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

_

Sculpture	Base
Sculpture	Base
	Sculpture

Does water collect in recessed areas of the Memorial? ____ Yes xx__ No ____ Unable to tell

Surface Coating

Does there appear to be a coating? ___ Yes <u>××</u> No ___ Unable to determine If known, identify type of coating. ___ Gilded ___ Painted ___ Varnished ___ Waxed ___ Unable to determine Is the coating in good condition? <u>××</u> Yes ___ No ___ Unable to determine

Basic Surface Condition Assessment (check one)

Overall Description

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) . $^{n/a} \ \ \,$

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-site Survey 03/25/2014 Your Name Walt Busch, PDC US Grant Camp #68

SUVCW

Please send this completed form to

Walt Busch, PDC, Chair

Thank you for your help, and attention to detail. SONS OF UNION V

CIVIL WAR VETERANS OF THE National Civil War Memorials Committee

>This form may be photocopied.<

signs from the past n37.11163 w93.40226

WILSON'S CREEK Signs From The Past

The surrounding young forest can tell us much. Agriculture has long dominated the landscape. Nearby, John Gibson's horsedrawn plow broke ground for an oat field. Later, tractors would shape and alter the countryside. In the course of this evolution roads and buildings emerged and later would disappear from view. Yet, subtle clues from the past remain to be discovered.

Directly in front of you is the trace of an old ditch. This is the millrace that carried water to the Gibson Mill. As it flowed downstream the millrace's water slowly gained elevation over the creek itself. At the mill the millrace was nine feet above the creek. The falling water provided the power to turn the mill's water-wheel. The entire millrace can be followed 3,862 feet upstream from the mill itself! Imagine ... in an age before bulldozers and backhoes completing such a project assisted only by a shovel, your neighbors, and perhaps a mule or two.

[Graphic of millrace labeled "Over ½ mile upstream from here water from Wilson Creek was diverted by a dam into the millrace. It flowed downstream several hundred yards, crossed the creek on a 45 foot raised trestle and continued past this spot to the mill. Artwork by Ken Cowan"]

Signs From The Past

The surrounding young forest can tell us much. Agriculture has long dominated the landscape. Nearby, John Gibson's horsedrawn plow broke ground for an oat field. Later, tractors would shape and alter the countryside. In the course of this evolution roads and buildings emerged and later would disappear from view. Yet, subtle clues from the past remain to be discovered.

Directly in front of you is the trace of an old ditch. This is the millrace that carried water to the Gibson Mill. As it flowed downstream the millrace's water slowly gained elevation over the creek itself. At the mill the millrace was nine feet above the creek. The falling water provided the power to turn the mill's waterwheel. The entire millrace can be followed 3,862 feet upstream from the mill itself Imágine . . . in an age before bulldozers and backhoes completing such a project assisted only by a shovel, your neighbors, and perhaps a mule or two.

SNOST

Over 1/2 mile upstream from here water from Wilson Creek was diverted by a dam into the millrace. It flowed downstream several hundred yards, crossed the creek on a 45 foot raised trestle and continued past this spot to the mill.

N-t

