NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

 Do not gu 	rint, using a t	formation. A	n answer of	"Unkno	wn" is more	e helpful.		
• include a	photograph o	or each view	able side and	label	it with name	e & directio	n of vie	w. - Thank You
Type of M	lemorial							
	nt with Sculpt nt without Scu			_	nument with orical Mark			Plaque
Affiliation								
GAR	Post Name	& No.						MOLLUS
WRC	Corps Nam	e & No.					_	□ MOLLOS
SUVCW	Camp Nam						_	
DUVCW	Tent Name	3 - 2 - 1 V					-	
Other	Description	2nd Colorac	lo Cavalry sole	diers an	d officers		_	
Original Dedi	cation Date	31 Jul 1864			2012/2014/2014/2014/2		_	
Location The Memoria Street/Road	l is <i>currently</i>	located at:						& date of publication.
City/Village			Townsh				unty Jac	
The front of the	ne Memorial	faces: O	_	South	○ East	OWest		
Government	Body, Agen	cy, or Indiv	idual Owne	r (of pr	operty that	Memorial is	locate	d in)
Name Woodl	awn Cemeter	y			Dept./Div.			7.11.2119
Street Addres	s 710 S. Nola	nd Rd.			- S			
City Independ	lence				State M	0	Zip Co	ode 64050
Contact Person				Telephone 816-325-7365				
If the Memoria	al has been r	noved, pleas	se list former	locatio	n(s):			
Physical D	etails							

Material of Monument or base under a Sculpture or Cannon is: X Stone Concrete Metal Undetermined

If known, name specific material (color of granite, marble, etc.) White Vermont marble

Material of the Sculp	oture is: Stone	Concrete	☐ Metal ☐ Un	determined
If known, name spec	cific material (color	of granite, marble,	etc.)	
If the Sculpture is of	metal, is it solid ca	st or "hollow?"	Solid Cast O Ho	llow Undetermined
Material of Plaque o	r Historical Marker	/ Tablet is:		
Material of the Cann	on is: Bron	ze 🗌 Iron - Co	nsult known Ordnan	ce Listing to confirm
Markings on muzzle	are:			**
Markings on Left Tru	union:		Right Trunion:	
Is inert ammunition	a part of the Memo	rial? O Yes O	No If so, describe:	
Approximate Dime Monument or Base:		nit of measure) - tak Width 2' 3/8"	en from tallest / wide Depth 2' 3/8"	est points or Diameter
Sculpture:	Height	Width	Depth	or Diameter
implements involved Markings/Inscription	d (in case your photons (on stonework	tos become separat	the "pose" of each led from this form). The ument, base, sculptu	
Maker or Fabricator	~	Yes No		
If so, give name & lo	and constitution of the co			
The "Dedication Tex	(1997) 1997 (1998) (1998) (1997) (1997) (1997)			n material face
Record the text (ind		n if on different side	s):	
[slashes indicate line West: In memory and Aged 33 yrs.	400 (100 (100 (100 (100 (100 (100 (100 (Wagoner / Co. C 2d (Col. Vol. Cav. / Died at	Ind. Mo. / July 6, 1864 /
Laffer / .E. 35 yrs. / Ro	bt Stackhouse / .E. 3	6 yrs. / Owen McFade		unn / .E. 30 yrs. / John / Whatson / .E. 24 yrs. / Co. ights.
East: Theo. Lamming	ger / Private / Co. C 2	d Col. Vol. Cav. / died	at Ind. Mo. / July 9, 18	364 / Aged 33 yrs.
	a cruel foe - / And t	hus, this tribute to / t	heir memory stands /	y murderous hands. / They Our country's honor, and /
Environmental (surrounding a memori	al can play a major role	in its overall condition.)
Type of Location				
		☐ Traffic Circle		College Campus
☐ "Town Square"		State Capito	E	☐ School
Municipal Buildin	g	Post Office		☐ Plaza/Courtyard
Courthouse		Park		Library
Other:				

General Vicinity						
Rural (low population, open land)	O Suburban (residential, ne	ear city)				
○ Town	Urban / Metropolitan					
Immediate Locale (check as many as may apply)						
☐ Industrial	▼ Commercial					
Street/Roadside within 20 feet						
Protected from the elements (canopy or enclosure, indoor		ing branches)				
Protected from the public (fence or other barrier)	5)					
Any other significant environmental factor:						
TALLAND HANDLES FOR A STREET AND THE	*					
Condition Information	2					
Structural Condition (check as many as may apply)						
The following section applies to Monuments with Sculpture, a	nd Monuments without Soulat					
the base for Monuments with Cannon. Instability in the	sculpture and its base car	ure - including				
by a number of factors. Indicators may be obvious or subt	le. Visually examine the sci	ulpture and its				
base.	•	12. 1 . (2.10) (2.10) (2.10) (2.10)				
M .	S1-4	2				
If hallow in the later of the second	Sculpture	Base				
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)						
Any evidence of structural instability?		_				
(look for cracked joiints, missing mortar or caulking or plant growth)	يكان					
Any broken or missing parts? (look for elements - sword, musket, hands, arms, etc missing due		10				
vandalism fluctuating weather conditions, etc.)	to 🔀					
Any cracks, splits, breaks, or holes?		_				
(also look for signs of uneven stress & weakness in the material)	X					
Surface Appearance (check as many as may apply)						
	Sculpture	Base				
Black crusting	×					
White crusting	ñ	H				
Etched, pitted, or otherwise corroded (on metal)	H	님				
Metallic staining (run-off from copper, iron, etc.)	H	H				
Organic growth (moss, algae, lichen or vines)	H	H				
Chalky or powdery stone	H	님				
Granular eroding of stone	$\overline{\mathbf{x}}$	H				
Spalling of stone (surface splitting off)	Ä	H				
Droppings (bird, animal, insect remains)	Ħ	H				
Other (e.g., spray paint graffiti) - please describe:						
Does water collect in recessed areas of the Memorial?	Yes ○ No ● U	Inable to tell				

Surface Coating							
Does there appear to be a coating? Yes No Unable to determine							
If known, identify type of coating:							
○ Gilded ○ Painted ○ Varnished ○ Waxed ○ Unable to determine							
Is the coating in good condition? Yes ONO Ounable to determine							
Basic Surface Condition Assessment							
In your opinion, what is the general appearance or condition of the Memorial? (a) Would benefit from treatment (b) In urgent need of treatment (c) Unable to determine							
O Vien manned O Vien a Seriem ver a Seriem of the Seriem o							
Overall Description							
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).							
Recorded as the oldest Civil War monument west of the Mississippi River, this monument is in surprisingly							
good shape except for the discolored white Vermont marble and illegible, weather-worn inscriptions. There							
are small pieces broken from the edges, too, which sometimes also removed a letter of the inscription. The inscriptions are very difficult to read even with shadows cast across the words. In fact, without knowing what							
the south face says, it would be impossible to figure it out. (see attached document)							
Supplemental Background Information							
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described							
Memorial will be welcomed. Please label each account with its source (author, title, publisher,							
date, pages). Topics include any reference to the points listed on this questionnaire, plus any							
previous conservation treatments - or efforts to raise money for treatment. Thank you.							
Inspector Identification							
Date of On-site Survey 17 Jun 2006 Westport 64 MO SUVCW							
Your Name Brian Smarker							
Print Form							
Please send this completed form to:							
T 11 A 01 W 1 D00							
Todd A. Shillington, PCC							
62							

SONS OF UNION VETERANS OF THE CIVIL WAR National Civil War Memorials Committee

The 2d Col. Vol. Cav. Memorial

Woodlawn Cemetery Independence, Missouri

By Brian V. Smarker Sons of Union Veterans of the Civil War Department of Missouri Westport Camp #64

In Woodlawn Cemetery stands a monument sculpted from white Vermont marble atop a concrete base. It has stood the test of time at that spot most certainly since its dedication on 31 July 1864, presumably the oldest Civil War memorial west of the Mississippi River. It was dedicated to nine soldiers of Company C 2nd Colorado Cavalry who died in or near Independence, Missouri.

All four faces of the monument bear weather-beaten inscriptions which have become difficult to read. Even after a stone rubbing the words appear incomprehensible. The least invasive method of deciphering the text is using a mirror to reflect sunlight across the engravings or, perchance the time of day is right, have the sun cast shadows across the surfaces enhancing their text.

According to Ellen Williams in her book, <u>Three Years and a Half in the Army; or History of the Second Colorados</u>, she "was requested to write an inscription" (Williams 60) which she did. The engravings on this surface are next to impossible to read, but knowing the inscription the words can be detected with careful studying. The inscription she wrote is on the southern face of the monument and it reads:

Brave heroes rest beneath this sculptured stone; In unfair contest slain by murderous hands. They knew no yielding to a cruel foe – And thus, this tribute to their memory stands Our country's honor, and a nation's pride 'Twas thus they nobly lived and bravely died.

Ellen Williams and her two children traveled with the Second Colorado since its inception when her husband, bugler Charles Williams, enlisted into Co. A under Capt. James Ford in the fall of 1861. She wrote about her travels and became acquainted with many of the soldiers. Her book was originally copyrighted in 1885.

The western face of the monument bore an inscription of the highest ranking officer killed in a skirmish with George Todd's guerillas. Ironically, Todd is buried in the same cemetery after being shot through the throat and killed by a sniper on 23 October 1864. The first and fourth lines are the most difficult to read and are interpreted along with the others as follows:

In memory and honor Capt. S. W. Wagoner Co. C 2d Col. Vol. Cav. Died at Ind. Mo. July 6, 1864 Aged 33 yrs.

Notice the spelling of Capt. Seymour W. Waggoner's last name. His headstone which is just as difficult to read definitely shows his last name spelled with two g's as does other documentation.

12/29/2006 1 of 2

The 2d Col. Vol. Cav. Memorial

Woodlawn Cemetery Independence, Missouri

The northern face of the monument continues with other soldiers killed in action in the skirmish with Todd's guerillas. It reads:

Corp. Eli Bear Aged 32 yrs. Privates Andrew Eaves .E. 18 vrs. Michael Gunn .E. 30 yrs. John Laffer .E. 35 yrs. Robt. Stackhouse .E. 36 yrs. Owen McFadden .E. 31 yrs. Henry Whatson .E. 24 yrs. Co. C 2d Col. Vol. Cav. who fell July 6, 1864 near Ind. Mo. defending their country's rights.

The most difficult part of this surface was deciphering the ages. The ".E." was apparently used to denote repetition of the "Aged" text beneath Corp. Eli Baer's name. Also notice the misspelling of Corp. Baer's and Pvt. Henry Watson's last names. Their headstones are also difficult to read, but bear the correct spellings.

Finally, the eastern face of the monument records the name of one individual who died from disease three days following the aforementioned skirmish:

Theo. Lamminger Private Co. C 2d Col. Vol. Cav. died at Ind. Mo. July 9, 1864 Aged 33 yrs.

All nine men have government-issued headstones marking their burial locations around the memorial. The majority of them, like the monument, prove difficult to read even with a trained eye. Knowing the names of the fallen helps, along with the aid of a mirror to reflect the sunlight across the faces of the stones casting shadows of what is left of the engraved characters.

There are those who believe the 2d Col. Vol. Cav. monument should be restored, yet in its current state, it would seem more feasible to leave it alone for history's sake and, possibly, erect a modern replica to perpetuate the memory of the Second Colorado Cavalry buried at Woodlawn Cemetery in Independence, Missouri.

12/29/2006 2 of 2







