## NATIONAL ORGANIZATION

## SONS OF UNION VETERANS OF THE CIVIL WAR

## CIVIL WAR MEMORIAL ASSESSMENT FORM

D	8	=	Δ	9	E	
	_	_	т.	•	_	•

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.

Include a photograph of each viewable	side and label it with name & direction of view.  - Thank You.
Type of Memorial	
× Monument with Sculpture	Monument with Cannon
Monument without Sculpture	Historical Marker Plagu
	I localities market I local
<u>Affiliation</u>	
G.A.R. (Post Name & No	) M.O.L.L.U.S.
W.R.C. (Corps Name & No	) Other Allied Ord
SUVCW (Camp Name & No.	) (Please describe be
DUVCW (Tent Name & No.	
X Other: Camp Jackson Union Soldier's Monument	Association
Original Dedication Date 1929	Please consult any/all newspaper archives f
	the first dedication ceremony and/or other facts on the memo
Please submit a copy of your findings with full identifie	cation of the paper & date of publication. Thank you.
	on Park, Arsenal & Broadway W90°12'37" N38°35'42"  County St. Louis City
The front of the Memorial faces: N	lorth South East _X West
Government Body, Agency, or Individual O	owner (of private cemetery that Memorial is located in)
Name city of st. Louis	Dept./Div. FACILITIES MANAGEMENT
Street Address 1200 MARKET	
City st Louis	State MO Zip Code 63103
Contact Person FACILITIES MANAGEMENT	State MO Zip Code 63103 Telephone ( 314 ) 613-7280
If the Memorial has been moved, please	
Originally at St. Louis University on original site of Cam	p Jackson, moved to this location 1960
Physical Details	
Material of Monument or base under a Sculpture or Ca	annon = X Stone Concrete Metal Undetermine
If known, name specific material (color of gra	anite, marble, etc.) White Stone & Bronze

If known, name specific material	StoneConcrete X Metal Undetermined (color of granite, marble, etc.)color - Browle
	t solid cast or "hollow?" LENKNOWN (PROBABLY HOLLOW)
Material of Plaque or Historica	Marker / Tablet = BRONZE
Markings on Muzzie = w#  Markings on Left Trunion N/A	zelron - Consult known Ordnance Listing to confirm Right Trunion
Is ment ammunition a part of th	e Memorial?   If so, describe
Wonument or Base: Height 2	dicate unit of measure) - taken from tallest / widest points  4 f+ Width 4 f+ Depth 5 f+ or Diameter  2 f+ Width 8 f+ Depth 4 f+ or Diameter
sneet of paper for each statue	culptures, please record this information on a separate and attach to this form. Please describe the "pose" of ns/implements involved (in case your photos become ank you!
Maker or Fabricator mark / nan	ne-work / metal-work of monument, base, sculpture) ne? If so, give name & location found
The "Dedication Text" is forme	ed: cut into material X raised up from material
ING STRENGTH OF OUR A	on if on different sides) Please use additional sheet if necessary.  VATION IS THE UNION OF STATES TO COMMEMORATE  VACUE OF STATES TO COMMEMORATE  VACUE OF STATES TO COMMEMORATE
AND THE MISSOURI VOLUNTEE	TACKSON MAY 10 1861 BY GENERAL NATHANEL LYON
FIRST REGIMENT INFANTRY COLON	
SECOND " " + "	HENRY BERNSTEIN
THIRD " "	FRANZ SIGEL
OURTH " "	NICHOLAS SCHLIETTNER
IRST REG US RESERVE CORP	S COL. HENRY ALMSTEDT
SECOND " " "	" HENRY KALLMAN
(SEE BACK) Environmental Setting	
(The general vicinity and immediate locale	e surrounding a memorial can play a major role in its overall condition.)
	a major fold in its overall continuon.)
Type of Location	
Cemetery	X Park Plaza/Courtyard
"Town Square"	Post Office School
Municipal Building	State Capitol Other:
Courthouse	College Campus
Traffic Circle	Library

## TEXT CONTINUED

JOHN MCNEIL THIRD B. GRATZ BROWN FOURTH CHARLES G. STIFEL 11 11 FIFTH

ERECTED 1929 By THE CAMP JACKSON UNION SOLDIERS MONUMENT ASSOCIATION

REV FRANK G. BEARDSLEY PHD-STD PRESIDENT

ALBERT VON HOFFMAN

THEO H. MOHR

MAJOR LEO RASSIEUR

MRS. JESSIE SHERMAN

MRS. MARY E. CONRATH MRS. ANNA MENIKHEIM

MRS. NELLIE BECKTOLD

JOHN W. LANLEY

MRS. M. NEUBAUER

TREASURER

SECRETARY

HONDRARY PRESIDENT

FIRST VICE PRESIDENT

SECOND " "

THIRD "

FOUNTH "

FIFTH " "

ASST. TREASURER

General Vicinity  Rural (low population, open land) Town	Suburban (residential, near city) Urban / Metropolitan					
Immediate Locale (check as many as may apply)  X Industrial  Street/Roadside within 20 feet Protected from the elements (canopy or enclosure, indoors) Protected from the public (fence or other barrier) Any other significant environmental factor  ST Louis Policities						
Condition Information						
Structural Condition (check as many as may the following section applies to Monuments with Sculp the base for Monuments with Cannon. Instability in number of factors. Indicators may be obvious or subtle.	ture, and Monuments without Sculptu the sculpture and its base can be d	etected by a				
	Sculpture	Base				
If hollow, is the internal support unstable/exposed' (look for signs of exterior rust)  Any evidence of structural instability? No (look for cracked joints, missing mortar or caulking or pla Any broken or missing parts? No (look for elements (i.e., sword, musket, hands, arms, etc due to vandalism, fluctuating weather conditions, etc.)  Any cracks, splits, breaks or holes? CHIPS ON (also look for signs of uneven stress & weakness in the results of the stress of	nt growth)					
White crusting No Etched, pitted, or otherwise corroded (on me Metallic staining (run-off from copper, iron, et Organic growth (moss, algae, lichen or vines Chalky or powdery stone No Granular eroding of stone No Spalling of stone (surface splitting off) No Droppings (bird, animal, insect remains) No Other (e.g., spray paint graffiti) - Please des  Some Light Green 9 Brown Pair GREEN STAINING From METAL	c.) Yes					

Surface Coating  Does there appear to be a coating? Yes X_ No Unable to determine If known, identify type of coating Gilded Painted Varnished Waxed VA Unable to determine Is the coating in good condition? Yes No Unable to determine
Basic Surface Condition Assessment (check one)  In your opinion, what is the general appearance or condition of the Memorial?  Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).  OVERALL GOOD CONDITION. REINSPECTION ON A 2 YR CYCLE
NEEDS TREATMENT TO REMOVE GREEN STAIN FROM METAL
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.
Date of On-site Survey
Your Name WALTER E. Buscut
Please send this completed form to:
PAUL LEISTRITZ

Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War National Civil War Memorials Committee Title: General Nathanial Lyon, 1929

Artist: Erhardt Siebert

Artist Bio: born: Switzerland; 1895-1959

Medium: Bronze and limestone Dimensions: 22' H, 8' W, 6' D

Location: Lyon Park - Arsenal and Broadway

Owner: City of St. Louis

Donor: Lyon Monument Association and private donors

Purchase Price: \$15,000

General Lyon had an easier time keeping St. Louis from falling into Confederate hands than the statue honoring him has had keeping its rightful place in the public arena. One newspaper article even stated that the general would be better honored by the absence of the sculpture. The monument was poorly conceived and badly executed. It was originally planned for a \$50,000 budget and had to be revised to fit the \$15,000 that was raised; the artist was selected, sight-unseen, on the basis of a magazine article praising his work; and then St. Louis University took both the site for which the sculpture was designed for their development of Mill Creek Valley, as well as the private bequest designated for the site acquisition.

The artist, whose father was a St. Louis physician, studied art at Washington University, then in Chicago. He opened a studio for awhile in New York City, returned to St. Louis, and finally gave up art to become the supervisory photographer for Aeronautical Chart Plant. He repeatedly denied that the sculpture was bad, saying that it was along new lines that old-style advocates would not appreciate. Artistic criticism ranged from calling the work "unaesthetic" to "a crime" to one description referring to the familiar comedy of two people in a horse outfit moving in different directions.

The work was moved in 1960 to its current location in Lyon Park, where it joined the earlier monument to Lyon executed by Adolphus Druiding.







