

Material of the Sculpture = Stone Concrete Metal Undetermined
 If known, name specific material (color of granite, marble, etc.) not applicable _____
 If the Sculpture is of metal, is it solid cast or "hollow?" _____

Material of Plaque or Historical Marker / Tablet = bronze

Material of Cannon = Bronze Iron - Consult known Ordnance Listing to confirm
 Markings on muzzle = N/a

Markings on Left Trunion _____ Right Trunion _____

Is inert ammunition a part of the Memorial? If so, describe _____

Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points

Monument or Base: Height 2 1/2 ft Width 2 1/2 feet Depth 2 1/2 feet or Diameter _____
 Sculpture: Height _____ Width _____ Depth _____ or Diameter _____

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture)

Maker or Fabricator mark / name? If so, give name & location found _____

The "Dedication Text" is formed: cut into material raised up from material face

Record the text (indicate any separation if on different sides...) Please use additional sheet if necessary.

1863 THE BATTLE OF CAPE GIRARDEAU This homestead was the center; Bloomfield Road the left flank; and Perryville Road the right flank; of the Union forces commanded by Brig. Gen. John H. McNeil. A sharp, bloody attack by Confederates led by Gen. Joe Shelby from the command of Gen. John S. Marmaduke was repulsed on April 26, 1863. This engagement came to be known as the Battle of Cape Girardeau.

Profile of Indian Chief atop plaque.

Rotary International symbol at bottom.

Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

Type of Location

- | | | |
|---------------------------------------------|-----------------------------------------|------------------------------------------|
| <input type="checkbox"/> Cemetery | <input type="checkbox"/> Park | <input type="checkbox"/> Plaza/Courtyard |
| <input type="checkbox"/> "Town Square" | <input type="checkbox"/> Post Office | <input type="checkbox"/> School |
| <input type="checkbox"/> Municipal Building | <input type="checkbox"/> State Capitol | Other: <u>Streetside</u> |
| <input type="checkbox"/> Courthouse | <input type="checkbox"/> College Campus | _____ |
| <input type="checkbox"/> Traffic Circle | <input type="checkbox"/> Library | _____ |

Surface Coating

Does there appear to be a coating? ___ Yes X No ___ Unable to determine

If known, identify type of coating.

___ Gilded ___ Painted ___ Varnished ___ Waxed ___ Unable to determine

Is the coating in good condition? ___ Yes ___ No ___ Unable to determine

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?

X Well maintained ___ Would benefit from treatment ___ In urgent need of treatment ___ Unable to determine

Overall Description

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) .

Good Condition.


Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification


Date of On-site Survey 19 June 2006

Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri



Please send this completed form to:

Todd A. Shillington, PDC



Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR
National Civil War Memorials Committee



18

63

THE BATTLE OF CAPE GIRARDEAU

THIS HOMESTEAD WAS THE CENTER, BLOOMFIELD ROAD THE LEFT FLANK, AND PERRYVILLE ROAD THE RIGHT FLANK, OF THE UNION FORCES COMMANDED BY BRIG. GEN. JOHN H. MCNEIL. A SHARP, BLOODY ATTACK BY CONFEDERATES LED BY GEN. JOE SHELBY FROM THE COMMAND OF GEN. JOHN S. MARMADUCE WAS REPULED ON APRIL 26, 1862. THIS ENGAGEMENT CAME TO BE KNOWN AS THE BATTLE OF CAPE GIRARDEAU.

