

2IN3

NATIONAL ORGANIZATION
SONS OF UNION VETERANS OF THE CIVIL WAR
CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.
- Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial

Monument *with* Sculpture Monument with *Cannon*
 Monument *without* Sculpture Historical Marker Plaque

Affiliation

G.A.R. (Post Name & No. B.J. Crosswait Post of the GAR, Angola, Indiana) M.O.L.L.U.S.
 W.R.C. (Corps Name & No. _____) Other Allied Order
 SUCVW (Camp Name & No. _____) (Please describe below)
 DUVCW (Tent Name & No. _____)
 Other: _____

Original Dedication Date September 17, 1917 Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

Location

The Memorial is *currently* located at:
 Street/Road address or site location US 20 AND WAYNE STREET, THE BIG TRAFFIC CIRCLE DOWNTOWN
 City/Village ANGOLA Township _____ County STEBEN CO, INDIANA

The front of the Memorial faces: North South East West

Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)...

Name _____ Dept./Div. CITY HALL

Street Address _____

City ANGOLA State INDIANA Zip Code _____

Contact Person _____ Telephone () _____

If the Memorial has been moved, please list former location(s)...

Physical Details

Material of Monument or base under a Sculpture or Cannon = Stone Concrete Metal Undetermined
 If known, name specific material (color of granite, marble, etc.) BARRE GRANITE

Material of the Sculpture = Stone Concrete Metal Undetermined
 If known, name specific material (color of granite, marble, etc.) _____
 If the Sculpture is of metal, is it solid cast or "hollow?" UNKNOWN

Material of Plaque or Historical Marker / Tablet = BRONZE

Material of Cannon = Bronze Iron - Consult known Ordnance Listing to confirm
 Markings on muzzle = _____
 Markings on Left Trunion _____ Right Trunion _____
 Is inert ammunition a part of the Memorial? If so, describe _____

Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points
 Monument or Base: Height _____ Width 19' 6" Depth 19' 6" or Diameter _____
 Sculpture: Height _____ Width _____ Depth _____ or Diameter _____

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture)
 Maker or Fabricator mark / name? If so, give name & location found _____

The "Dedication Text" is formed: cut into material raised up from material face

Record the text (indicate any separation if on different sides...) Please use additional sheet if necessary.
FOUR LARGE BRONZE PLAQUES ON THE SIDES OF THE BASE GIVE THE NAMES OF 1,278 MEN FROM STEUBEN CO., INDIANA,
WHO SERVED IN THE CIVIL WAR. THE NAMES ARE GROUPED BY REGIMENT.
THE 4TH MICHIGAN INFANTRY GROUP CONTAINS 47 NAMES.

Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

Type of Location

- | | | |
|--|---|--|
| <input type="checkbox"/> Cemetery | <input type="checkbox"/> Park | <input type="checkbox"/> Plaza/Courtyard |
| <input checked="" type="checkbox"/> "Town Square" | <input type="checkbox"/> Post Office | <input type="checkbox"/> School |
| <input type="checkbox"/> Municipal Building | <input type="checkbox"/> State Capitol | Other: _____ |
| <input type="checkbox"/> Courthouse | <input type="checkbox"/> College Campus | _____ |
| <input checked="" type="checkbox"/> Traffic Circle | <input type="checkbox"/> Library | _____ |

General Vicinity

- Rural (low population, open land)
- Town
- Suburban (residential, near city)
- Urban / Metropolitan

Immediate Locale (check as many as may apply)

- Industrial
- Street/Roadside within 20 feet
- Protected from the elements (canopy or enclosure, indoors)
- Protected from the public (fence or other barrier)
- Any other significant environmental factor _____
- Commercial
- Tree Covered (overhanging branches)

Condition Information

Structural Condition (check as many as may apply)

The following section applies to Monuments *with* Sculpture, and Monuments *without* Sculpture - including the base for Monuments with *Cannon*. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If hollow, is the internal support unstable/exposed? <small>(look for signs of exterior rust)</small>	___	___
Any evidence of structural instability? <small>(look for cracked joints, missing mortar or caulking or plant growth)</small>	___	___
Any broken or missing parts? <small>(look for elements (i.e., sword, musket, hands, arms, etc. - missing due to vandalism, fluctuating weather conditions, etc.)</small>	___	___
Any cracks, splits, breaks or holes? <small>(also look for signs of uneven stress & weakness in the material)</small>	___	___

Surface Appearance (check as many as may apply)

	Sculpture	Base
Black crusting	___	___
White crusting	___	___
Etched, pitted, or otherwise corroded (on metal)	___	___
Metallic staining (run-off from copper, iron, etc.)	___	___
Organic growth (moss, algae, lichen or vines)	___	___
Chalky or powdery stone	___	___
Granular eroding of stone	___	___
Spalling of stone (surface splitting off)	___	___
Droppings (bird, animal, insect remains)	___	___
Other (e.g., spray paint graffiti) - Please describe...	___	___

SURFACE OF THE BARRE GRANITE BASE, THE GRANITE SHAFT, AND THE CONDITION OF THE FIVE BRONZE STATUES, APPEARS TO BE EXCELLENT

Does water collect in recessed areas of the Memorial? ___ Yes ___ No Unable to tell

Surface Coating

Does there appear to be a coating? Yes No Unable to determine
 If known, identify type of coating.

Gilded Painted Varnished Waxed Unable to determine
 Is the coating in good condition? Yes No Unable to determine

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?
 Well maintained Would benefit from treatment In urgent need of treatment Unable to determine

Overall Description

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).
 PLACED IN A LARGE TRAFFIC CIRCLE IN DOWNTOWN ANGOLA, INDIANA. MONUMENT IS A BASE AND SHAFT OF GRANITE WITH A BRONZE STATUE
 OF COLUMBIA AT THE TOP. AROUND THE BASE ARE 4 OTHER BRONZE STATUES, OF CIVIL WAR SOLDIERS.
 TOTAL HEIGHT OF MONUMENT IS 70 FEET. IT IS A BELOVED LOCAL LANDMARK, AND IS WELL MAINTAINED BY THE CITY.
 FEATURES FOUR LARGE BRONZE TABLETS ON THE BASE WITH NAME OF ALL OF STEUBEN CO. INDIANA'S SOLDIERS IN THE CIVIL WAR.

Supplemental Background Information


In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-site Survey MAY 13, 2007
 Your Name CHRIS CZOPEK DEPT OF MICHIGAN SUV COLEGROVE-WOODRUFF CAMP 22
 Address 806 N. FRANCIS AVE City LANSING
 State MI Zip Code 48912 Telephone () _____

Please send this completed form to:

Todd A. Shillington, PDC



Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR
 National Civil War Memorials Committee

