### NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

# CIVIL WAR MEMORIAL ASSESSMENT FORM

#### PLEASE:

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.
- · Include a photograph of each viewable side and label it with name & direction of view.

#### - Thank You.

#### Type of Memorial

× Monument with Sculpture	Monument with Cannon	
Monument without Sculpture	Historical Marker Plaque	

#### Affiliation

_	G.A.R.	(Post	Name & No	O.W. Keyes #35	)	M.O.L.L.U.S.
	W.R.C.	(Corps	Name & No.	)	)	Other Allied Order
-	SUVCW	(Camp	Name & No.	O.W. Keys #5/Thomas P. Cheney #19 )	)	(Please describe below)
-	DUVCW	(Tent	Name & No	·	)	

\_ Other:

**Original Dedication Date**  $5/30/1899 + Z_n 1900$  Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

#### Location

The Memorial is a	currently located	at:			
Street/Road addr	ess or site locati	on Main and Th	nompson Street		
City/Village Ashlanc	Towi	nship	Cou	unty Grafton	
The front of the N	lemorial faces:	$\underline{\times}$ North	South _	East	West
Government Body, Name Town of Ashlar	nd	dual Owner (	of private cemetery Dept./Div.		
Street Address	PO Box 517	2			
City Ashland	1 		State NH	Zip Code	03217
Contact Person			Telephone (	)	
If the Memorial ha			ormer location(s)		

#### **Physical Details**

Material of Monument or base under a Sculpture or Cannon = <u>X</u>Stone <u>Concrete</u> Metal <u>Undetermined</u> If known, name specific material (color of granite, marble, etc.) <u>Concord Gray Granite</u> SUVCW -- CIVIL WAR MEMORIAL ASSESSMENT FORM (CWM #61)

•

.

.

Material of the Sculpture = Stone Concrete Metal Undetermined         If known, name specific material (color of granite, marble, etc.) Bronze         If the Sculpture is of metal, is it solid cast or "hollow?" Hollow
Material of Plaque or Historical Marker / Tablet = Bronze
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm         Markings on muzzle =         Markings on Left Trunion         Is inert ammunition a part of the Memorial?
Is inert ammunition a part of the Memorial? If so, describe
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points         Monument or Base:       Height       23       Width       7       Depth       7       or Diameter         Sculpture:       Height       7       Width       21/2       Depth       2       or Diameter
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you! Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found
The "Dedication Text" is formed: cut into material $\underline{\times}$ raised up from material face Record the text (indicate any separation if on different sides) Please use additional sheet if necessary.
Environmental Setting
(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.) Type of Location
Cemetery      Park      Plaza/Courtyard        Town Square"      Post Office      School        Nunicipal Building      State Capitol       Other:        Courthouse      College Campus         X Traffic Circle      Library

.

> This form may be photocopied. <

#### **General Vicinity**

Rural (low population, open land) X Town \_\_\_ Urban / Metropolitan

\_\_\_\_ Suburban (residential, near city)

Immediate Locale (check as many as may apply)

- Industrial Commercial
- × Street/Roadside within 20 feet Tree Covered (overhanging branches) Protected from the elements (canopy or enclosure, indoors)
- Protected from the public (fence or other barrier)
- Any other significant environmental factor

#### Condition Information

#### **Structural Condition** (check as many as may apply)

Sculpture -The following section applies to Monuments *with* Sculpture, and Monuments without <u>Sculpture</u> - Sculpture - Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

Sculpture		Base
If hollow, is the internal support unstable/exposed?	<u>n</u>	_ <u>n</u>
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth)	<u>n</u>	<u>n</u>
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc missing	<u> </u>	<u></u>
due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes?	n	n
(also look for signs of uneven stress & weakness in the material)		
Surface Appearance (check as many as may apply)		
	Sculpture	Base
Black crusting		
White crusting		
Etched, pitted, or otherwise corroded (on metal)	3 <b></b> 1 <b>-</b> -1	
Metallic staining (run-off from copper, iron, etc.)		
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone		
Granular eroding of stone		(Anteridade and Anterior anterior anterior anterior anterior anterior anterior anterior anterior
Spalling of stone (surface splitting off)		
Droppings (bird, animal, insect remains)		-
Other (e.g., spray paint graffiti) - Please describe		

Does water collect in recessed areas of the Memorial? \_\_\_\_Yes \_\_\_\_No \_\_X Unable to tell

#### **Surface Coating**

Does	there	appear	to	be	а	coating?	$\underline{\times}$	Yes		No	-	Unable	to	determine
If know	wn, ide	ntify typ	e o	f coa	tin	g.								
G	ilded	Pain	ted		Va	arnished	W	axed	X	Unal	ole to	determi	ne	
Is the	coating	in good	con	ditio	n?	X Yes		No		×	Una	ble to det	term	nine

#### Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial? X Well maintained \_\_\_\_\_\_ Would benefit from treatment \_\_\_\_\_ In urgent need of treatment \_\_\_\_\_\_ Jnable to determine

## **Overall Description**

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) . Looks like this monument is in good condition.

#### Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

#### Inspector Identification

 Date of On-site Survey 4/30/2008

 Your Name Dan Meehan

 Address 24 Corson St.

/ 10/01/000	21 COISC	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	CHUINI	OILV MI		
State _	NH	Zip Code 03867	Telephone			

Please send this completed form to:

#### Kevin P. Tucker, PDC, Chair

Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR National Civil War Memorials Committee

Artist:	Unknown, sculptor. Swenson, John, contractor.
Title:	The Soldiers Monument.
Other Titles:	Civil War Soldiers Monument. Dedicated May 30, 1899. Relocated 1900.
Medium:	Figure: bronze; Base: Concord gray granite.
Dimensions:	Figure: approx. 7 x 2 1/2 x 2 ft.; Base: approx. 23 x 7 x 7 ft.
Inscription:	(On bronze plaque on front of base: list of twenty-seven names) (On lower front of base, raised letters:) LINCOLN (On bronze plaque on back of base:) IN MEMORY OF THE/SOLDIERS OF ASHLAND IN/THE WAR. 1861-1865/ERECTED BY THE TOWN./O.W. KEYE'S POST G.A.R./AND WOMAN'S RELIEF CORPS./DEDICATED MAY 30TH 1899/THOMAS P. CHENEY/6TH N.H. VOL'S/FRANK L. HUGHES/12TH N.H. VOL'S/EDWARD P. WARNER/143D IND. VOL'S./TOWN/COMMITTEE (On lower back of base:) SHERMAN (On bronze plaque on side of base: list of twenty-eight names) (On lower side of base:) SHERIDAN (On other side of base: list of twenty-eight names) (On other lower side of base:) GRANT
Description:	A mustached Union infantryman dressed in a Civil War uniform that consists of a long overcoat, cape, trousers, and boots. He stands at parade rest with his proper left foot forward and holds the barrel of a rifle with both hands. The butt of the rifle rests near the figure's feet. The figure wears a belt around his waist with a bayonet at his proper left side and two pouches at his proper right side. The figure is placed atop a tall base that consists of tall polished column surmounted by a composite capital. The column stands atop a stepped lower section with a crenelated top and bartizan corners. A granite curb surrounds the monument and contains shrubs and flowers.
Owner:	Administered by Town of Ashland, 10 Highland Street, P. O. Box 517, Ashland, New Hampshire 03217 Located Monument Square, Junction of Main & Thompson Streets, Ashland, New Hampshire
Provenance:	Formerly located Town Hall, Highland Street, Ashland, New Hampshire before 1900.
Remarks:	At its annual meeting in 1898 the Town of Ashland voted to appropriate \$1,500 for a Civil War soldiers monument provided that the local post of the Grand Army of the Republic and the Women's Relief Corps supplied the remainder of the money. The Grand Army of the Republic Post donated \$200 and the Women's Relief Corps raised \$300. The town contracted with John Swenson, a Concord quarryman, who produced the elaborate base. When the site of the monument was announced it aroused strong opposition from a group of townspeople who felt that the monument should be placed at a more prominent place on Main Street where strangers passing through the town would see it. A petition signed by 182 voters asking for the Main Street location did not dissuade the committee. The monument was installed as planned.
·	In March 1900, at the next annual meeting, the town voted to move the monument and appropriated \$450.00 for its relocation. By May, a new site had been chosen and the monument dismantled. The new site, a small triangle at the intersection of Main, Highland, and River Streets, was itself ruled out as the owner of the land refused to have the monument installed there. The committee was forced to use its second choice, a small square at the intersection of Main and Thompson Streets, soon renamed Monument Square. IAS files contain related articles from The Ashland Item, June 10, 1899; the Concord Monitor, May 31, 1899; and The Manchester Union, May 29, 1899; June 7, 1899, pg. 2; and June 16, 1899, pg. 1, 3. IAS files contain related excerpts from Doris Tatham and John Smith's "Ashland Centennial Book," Ashland, New Hampshire, 1968, pg. 68, 69; and David Ruell's typescript, "The Public Sculpture of New Hampshire," Concord, New Hampshire: New Hampshire Historical Society, 1980, pg. 44-47. IAS files contain transcription of names of Civil War dead from Ashland that appear on the plaque. The monument is now the main element of the town seal.

.

.

•

•





# • IN MEMORY OF THE SOLDIERS OF ASHLAND N THE MAR. 1361 - 1365 ED BY THE TOWN. ENERI D.W. KEYES POST G.A.R. AND WOMAN'S RELIEF RIK DEDIGATED MAY 30TH 1399 THOMAS P. CHENEY STH N.H. VOL'S FRANK L. HUGHES OM/R 12TH M H VOLS ROMMATTEE ARD 2 WARNER KASP IND. VOLS