Sons of Union Veterans of the Civil War Dept. of California & Pacific



Civil War Memorial Assessment Form

(Form CWM #61)

Used for periodic assessments of the condition of Grand Army of the Republic (GAR) and Civil War memorials in the Department of California & Pacific, SUVCW (includes California, Nevada and Hawaii)

For more information please go to: http://www.suvpac.org/memorials.html

FORM CWM #61

Submitted 5 March 2011

PAGE 1 OF 4

NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

 PLEASE: Type or print, using a ball-point pen, when filling Do not guess at the information. An answer of linclude a photograph of each viewable side at the information. 	f, "Unknown," is more helpful.
Type of Memorial Monument with Sculpture	- Thank You. Monument with Cannon Historical Marker Plaque
Affiliation General John Frank XX G.A.R. (Post Name & No. Post #110 Col. W.R.C. (Corps Name & No. SUVCW (Camp Name & No. DUVCW (Tent Na	lin Miller usa, Ca. Other Allied Order (Please describe below)
local paper's article that would have information on the <i>first</i> dedice Please submit a copy of your findings with full identification of the Location The Memorial is <i>currently</i> located at: Street/Road address or site location1974 City/VillageColusaTownship	cation ceremony and/or other facts on the memorial. e paper & date of publication. Thank you. Wilson Avenue
The front of the Memorial faces: North Government Body, Agency, or Individual Owner (of Name Colusa Community Cemetery	South East _x_West
Street Address 1974 Wilson Ave. City Colusa	State ca Zip Code 95932
Contact Person	Telephone ()
If the Memorial has been moved, please list form	
Physical Details Material of Monument or base under a Sculpture or Cannon = If known, name specific material (color of granite, m	x_Stone Concrete Metal Undetermined arble, etc.) Granite

SUVCW CIVIL WAR MEMORIAL ASSESSMENT FORM (CWM#61)	PAGE 2 OF 4
Material of the Sculpture = _x_ StoneConcrete Metal If known, name specific material (color of granite, marble, etc.) If the Sculpture is of metal, is it solid cast or "hollow?"	
Material of Plaque or Historical Marker / Tablet =	-
Material of Cannon =BronzeIron - Consult known Ordnance Markings on muzzle = Markings on Left Trunion Right Trunion Is inert ammunition a part of the Memorial? If so, describe	
Approximate Dimensions (indicate unit of measure) - taken from tall Monument or Base: Height 7"in Width 1 1/2" Depth o Sculpture: Height Width Depth or	Diameter Z. / I/Z
For Memorials with multiple Sculptures, please record this information sheet of paper for each statue and attach to this form. Please described each statue and any weapons/implements involved (in case you separated from this form). Thank you!	Tibe the pose of
Markings/Inscriptions (on stone-work / metal-work of monument, Maker or Fabricator mark / name? If so, give name & location found Section I, Lot 28, Graves 1 - 5	G.A.R.
The "Dedication Text" is formed: cut into material raised up	
Record the text (indicate any separation if on different sides) Please use addition	al sheet if necessary.
N/A	
Environmental Setting	and an address of the second s
(The general vicinity and immediate locale surrounding a memorial can play a major role in it Type of Location	s overall condition.)

Park

Post Office

Library

State Capitol
College Campus

Cemetery "Town Square"

Courthouse

Traffic Circle

Municipal Building

Plaza/Courtyard

School

Other:

General Vicinity X Rural (low population, open land) Town	_Subi Urba	urban (residential, near an / Metropolitan	city)
Immediate Locale (check as many as may apply) Industrial Commercial Street/Roadside within 20 feet Tree Cove Protected from the elements (canopy or enclosure Protected from the public (fence or other barri	e, Indoc ier)	ors)	1
Any other significant environmental factor	GAR I	Lot located inside	de cemetery.
			and the second s
Condition Information			
Structural Condition (check as many as may ap	oply)	numents without Sculpture	
The following section applies to Monuments with Sculpture,	and wo	numents without occuptore	ne detected
including the base for Monuments with Cannon. Instability by a number of factors. Indicators may be obvious or s base.	in the subtle. \	/isually examine the sculpt	ture and its
		Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	N/A		Approximates
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant gr	owth)	N/A	
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc midue to vandalism, fluctuating weather conditions, etc.)	issing	N/A	
	II/A rial)	particular formers	
Surface Appearance (check as many as may	apply)	Contesturo	Base
District and the second		Sculpture	Dusc
Black crusting White crusting		and in	*****
Etched, pitted, or otherwise corroded (on metal)			"
Metallic staining (run-off from copper, iron, etc.)		Page 15	
Organic growth (moss, algae, lichen or vines)	N/A		
Chalky or powdery stone		- 2	auma 4
Granular eroding of stone		Section in the section of the sectio	
Spalling of stone (surface splitting off)		MAGE 1	pope et
Droppings (bird, animal, insect remains) Other (e.g., spray paint graffiti) - Please describe)		
Does water collect in recessed areas of the Memoria	al?	Yes <u>x</u> No Un	able to tell

Surface Coating Does there appear to be a coating? Yes xxx No Unable to determine If known, identify type of coating. Gilded Painted Varnished Waxed Unable to determine
Is the coating in good condition? Yes No Unable to determine Basic Surface Condition Assessment (check one)
In your opinion, what is the general appearance or condition of the Memorial?
See attatched list
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you. Inspector Identification Date of On-site Survey March 5, 2011 Your Name John L. Morton, Colusa County Historical Researcher. Address P.O. Box 發致 342 State Ca Zip Code 95932 Telephone
Please send this completed form to:
Bruce B. Butgereit, PDC, Chair Thank you for your help, and attention to detail.
SONS OF UNION VETERANS OF THE CIVIL WAR

National Civil War Memorials Committee

Grand Army of the Republic Lot Section I, Lot 28, Graves 1 - 5

1) George Carson - Sgt, Company A, 1st Maryland Cavalry, Potomac Home Brigade Sgt, Company G, 13th Maryland Infantry

B - January 26, 1835

D - November 12, 1920

Buried - Lot 28, Grave 1

2) John Lacy - Private, Company G, 2nd Colorado Cavalry Private, Company I, 2nd Colorado Infantry

B - 1829

D - June 18, 1891

Buried - Lot 28, Grave 2

3) John Frederick Harre - Private, Company A, 7th New York Infantry

B - 1826

D - June 12, 1895


Buried - Lot 28, Grave 3

4) William McCallister - Captain, Company I, 140th Pennsylvania Infantry

B - January 1, 1828

D - August 10, 1896

Buried - Lot 28, Grave 4



GRAND ARMY OF THE REPUBLIZ LOT SECTION IS LOT 28, GRAVES 1-5

Colusa Community Cemetery Old Soldiers Lot Section G, Lot 9, Graves 3 - 5

Left - Singleton H. Stewart - Private, Company D, 2nd Oregon Volunteers

B - November 21, 1838

Indian War Veteran

D - October 18, 1909

Buried - Lot 9, Grave 3

Middle - Turner McGhee - Private, Company G, 12th Missouri Cavalry,

B - 1840

Union Army

D - January 12, 1907

Buried - Lot 9, Grave 4


Right - Oscar Getman - Private, Company C, 7th Illinois Infantry, Union

B - 1836

Army

D - May 10, 1905

Buried - Lot 9, Grave 5



OLD SOLIDER'S LOT SECTION G LOT 9, GRAVES 3-5