

NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:			
 Type or print, using a ball-point pen, when filling out this form. Legibility is critical. Do not guess at the information. An answer of, "Unknown," is more helpful. 			
- Thank You.			
Type of Memorial X BUILDING (ZND FLOOR)			
Monument with Sculpture Monument with Cannon			
Monument <u>without</u> Sculpture Historical Marker Plaque			
Affiliation - 2ND FLOOR			
X G.A.R. (Post Name & No. STANTON POST 16)M.O.L.L.U.S.			
W.R.C. (Corps Name & No. STANTON CORPS # 16) _ Other Allied Order			
X SUVCW (Camp Name & No. GEV. W.S. ROSECRING Z.) (Please describe below			
X DUVCW (Tent Name & No. CLARA BARTON TENT 14			
X Other: LADIES OF THE G.A.R GENERAL H.W. LAWTON CIRCLE 29			
Original Dedication Date 1925 Please consult any/all newspaper archives for			
Original Dedication Date Please consult any/all newspaper archives for a local paper's article that would have information on the <i>first</i> dedication ceremony and/or other facts on the memorial			
Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.			
Location			
The Memorial is currently located at:			
Street/Road address or site location 1816 FIGNEROA STREET			
City/Village Los ANGELES Township Los ANGELES County CALLEGENIA			
The front of the Memorial faces: North South East X West			
Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)			
Name Dept./Div			
Street Address			
City LOS ANGELES State CA Zip Code			
Contact Person Telephone ()			
If the Memorial has been moved, please list former location(s)			
Physical Details All			
Physical Details Material of Monument or base under a Sculpture or Cannon = Stone Concrete Metal Undetermined			

If known, name specific material (color of granite, marble, etc.)

Material of the Sculpture = Stone Concrete Metal Undetermined If known, name specific material (color of granite, marble, etc.) If the Couletture is of metal, is it colid past or "hollow?"			
If the Sculpture is of metal, is it solid cast or "hollow?"			
Material of Plaque or Historical Marker / Tablet =			
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle =			
Markings on muzzle =			
Is inert ammunition a part of the Memorial? If so, describe			
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height Width Depth or Diameter Sculpture: Height Width Depth or Diameter Proof Buttotog - Entire and Front GNA Aured ORDERS For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!			
Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found			
The "Dedication Text" is formed: cut into material raised up from material face			
Record the text (indicate any separation if on different sides) Please use additional sheet if necessary.			
Environmental Setting (The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)			
Type of Location			
Cemetery Park Plaza/Courtyard			
"Town Square" Post Office School State Capitol Other: DownTown			
Courthouse College Campus METROPOLITAN Library			

	General Vicinity Rural (low population, open land) Town	_ Suburban (residential, no _ Urban / Metropolitan	ear city)
	Immediate Locale (check as many as may apply) Industrial Street/Roadside within 20 feet Protected from the elements (canopy or encloance) Protected from the public (fence or other barried Any other significant environmental factor	er)	
×	Condition Information Structural Condition (check as many as may any	alv)	
	Structural Condition (check as many as may approximately The following section applies to Monuments with Sculpture, the base for Monuments with Cannon. Instability in the senumber of factors. Indicators may be obvious or subtle. Visually in the senumber of factors.	and Monuments without Sculptuculpture and its base can be co	letected by a
		Sculpture	Base
	If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	<u> </u>	
	Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant grown broken or missing parts?	wth)	
	(look for elements (i.e., sword, musket, hands, arms, etc mis- due to vandalism, fluctuating weather conditions, etc.)	sing	200 HCCC
X.	Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)		
	Surface Appearance (check as many as may app	oly) Sculpture	Base
	Black crusting		
	White crusting Etched, pitted, or otherwise corroded (on metal)	<u> </u>	-
	Metallic staining (run-off from copper, iron, etc.)		
	Organic growth (moss, algae, lichen or vines)		
	Chalky or powdery stone		-
	Granular eroding of stone Spalling of stone (surface splitting off)		
	Droppings (bird, animal, insect remains) Other (e.g., spray paint graffiti) - Please describe		
	Does water collect in recessed areas of the Memorial?	Yes No U	nable to tell

Surface Coating Does there appear to be a coating? Yes No Unable to determine
If known, identify type of coating.
Gilded Painted Varnished Waxed Unable to determine
Is the coating in good condition? Yes No Unable to determine
Basic Surface Condition Assessment (check one)
In your opinion, what is the general appearance or condition of the Memorial? Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description A WONDERFUL, "CLASSY" BUILDING!
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). BUTLDING WELL MAINTAINED. GAR MEETING ROOM SAME AS
ORIGINALLY WAS AND INCHUSES TWO LORGE DUPLAY CASES FULL
OF GAR ENCAMPMENT (NATH, CALIF, KANSAS) RIBBONS AND MEDALS
2ND FLOUR FOYER WAS DUPLAY CASE ARTHACTS FROM ANTIETAM BATTLEFIELD.
DISPLAY CASE 157 (GROWND) FLOOR HAS A DRUM (HEAD BUSTED) CARRIED BY
A GOR MEMBER DURING CIVIL WAR, [LAST GAR DIED 1953, OTHER ALISED
ORDER GROUPS DISBANDED BY MID 1960'S). THIS PORTEN FIGURES STREET
Supplemental Background Information FORMERLY U.S. ROUTE & GAR HIGHWAY
In addition to your on-site survey, any additional information you can provide on the described
Memorial will be welcomed. Please label each account with its source (author, title, publisher,
date, pages). Topics include any reference to the points listed on this questionnaire, plus any
previous conservation treatments - or efforts to raise money for treatment. Thank you.
Inamedar Identification
Inspector Identification
Date of On-site Survey 12 JUNE 1999 Your Name GENE ARM ISTEAD
Address 747 MY CORTE DRIVE City ESCONDIDO
State CA Zip Code 92026-1824 Telephone
State CH Zip Code 12028 121 Telephone

Please send this completed form to:

Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War National Civil War Memorials Committee

QEN. W. S. ROSECRANJ CAMP NO. 2 S. U. V. C. W.



AND

AUXILIARY NO. 2

S. U. V. C. W.

Department of California and Pacific