FORM CWM #61 Page 1 of 4

NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- 1. Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- 2. Do not guess at the information. An answer of, "Unknown," is more helpful. .Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

FORM CWM #61 Page 2 of 4

Physical Details

Material of Monument or base under a Sculpture or Cannon = name specific material (color of granite, marble, etc.)	Stone Concrete Metal Undetermined If known.c.)
SUVCW CIVIL WAR	
Material of the Sculpture = StoneConcre If known, name specific material (color of granite, r If the Sculpture is of metal, is it solid cast or "holl	marble, etc.)
Material of Plaque or Historical Marker / Tablet =	·
Material of Cannon =BronzeIron - Cons Markings on muzzle =	ult known Ordnance Listing to confirm
Markings on muzzle =	Right Trunion
Is inert ammunition a part of the Memorial?	_ If so, describe
Approximate Dimensions (indicate unit of mea Monument or Base: Height 60" Width 69" Sculpture: Height Width Depth	sure) - taken from tallest / widest points Depth 40" or Diameter or Diameter
for each statue and attach to this form. Please de	ecord this information on a separate sheet of paper escribe the "pose" of each statue and any tos become separated from this form). Thank you!
Markings/Inscriptions (on stone-work / metal-w Maker or Fabricator mark / name? If so, give name	
The "Dedication Text" is formed: cut into ma	terial raised up from material face
Record the text (indicate any separation if on differ Defenders Parkway Dedicated by Mothers of the Defenders of the Flag Soldiers Sailors Marines Who So Gallantly Responded to our Country's Call	rent sides) Please use additional sheet if necessary.
1776 1861 1898 1917	
Environmental Setting (The general vicinity and immediate locale surrounding a memory Type of Location	norial can play a major role in its overall condition.)
Town Square" P Municipal Building S Courthouse C	ark Plaza/Courtyard ost Office School tate Capitol Other: tollege Campus ibrary

FORM CWM #61 Page 3 of 4

General Vicinity Rural (low population, open land) Town	Suburban (residen Urban / Metropolita			
Immediate Locale (check as many as may apply) Industrial Commercial Street/Roadside within 20 feet * Tree Covered (composed from the elements (canopy or enclosure, incomposed from the public (fence or other barrier) Any other significant environmental factor	doors)			
Condition Information				
Structural Condition (check as many as may apply)				
The following section applies to Monuments with Sculpture, and including the base for Monuments with Cannon. Instability in the number of factors. Indicators may be obvious or subtle. Visually	sculpture and its base can	be detected by a		
	Sculpture	Base		
If hollow, is the internal support unstable/exposed? (Look for signs of exterior rust)				
Any evidence of structural instability?				
(Look for cracked joints, missing mortar or caulking or plant gr Any broken or missing parts?	owth)			
(Look for elements (i.e., sword, musket, hands, arms, etc mi	ssing			
due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes?				
(Also look for signs of uneven stress & weakness in the materi	ial)			
Surface Appearance (check as many as may apply)				
	Sculpture	Base		
Black crusting				
White crusting Etched, pitted, or otherwise corroded (on metal)				
Metallic staining (run-off from copper, iron, etc.)				
Organic growth (moss, algae, lichen or vines)				
Chalky or powdery stone				
Granular eroding of stone Spalling of stone (surface splitting off)				
Droppings (bird, animal, insect remains)				
Other (e.g., spray paint graffiti) - Please describe				
Not readily visible from the street, the marker is part of a grouping of monuments in what				
monument and the named parkway. The other monuments celebrate the founding of Pas- but without reference to their service] and a marker celebrating the founding of a local		ns by name,		
22				
Does water collect in recessed areas of the Memorial?	_ Yes No <u>×</u> Unable	to tell		

FORM CWM #61 Page 4 of 4

Su	ırfa	ce	Co	ati	na
		\mathbf{v}	~	uci	

Does there appear to be a coating? Yes No <u>x</u> Unable to determine If known, identify type of coating. Gilded Painted Varnished Waxed Unable to determine Is the coating in good condition? Yes No Unable to determine
Basic Surface Condition Assessment (check one)
In your opinion, what is the general appearance or condition of the Memorial? Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). Overall in very good condition. It is along a walking path used by local residents, and is in sight from a local residential complex, but is not
readily visible from outside the park area otherwise.
GPS location: 34 degrees, 08.726 minutes north; 118 degrees, 09.680 minutes west

Supplemental Background Information


In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-	site Survey 6 Septembe	r 2012		
Your Name	Nicholas D. Smith			
Address 426	N. Michigan Ave. #4		City Pasadena	
State CA	Zip Code 91106	Telephon		
What Order	or Organization is s	submitter a member of?	SUV, Rosecrans Camp #2, Cal	lifornia Pacific

Please send this completed form to

Walt Busch, PDC, Chair



Thank you for your help, and attention to detail. Sons of Union V

CIVIL WAR VETERANS OF THE National Civil War Memorials Committee

