FORM CWM #61 Page 1 of 4

NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- 1. Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- 2. Do not guess at the information. An answer of, "Unknown," is more helpful. .Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial Monument with Sculpture Monument with Cannon xxx Monument without Sculpture Historical Marker Plaque Other (flag pole, G.A.R. buildings, stained glass windows, etc.)
Affiliation
Original Dedication Date August 21, 2009 Please consult any/all newspaper archives for a local paper article that would have information on the <i>first</i> dedication ceremony and/or other facts on the memorial. Please submit a copy your findings with full identification of the paper & date of publication. Thank you. Location The Memorial is <i>currently</i> located at:
Street/Road address or site location Immediately west of 4105 Hempstead Turnpike City/Village Bethpage Township County Nassau State New York County Nassau
The front of the Memorial faces: North South _xxx East West
Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in) Name Lyceum Cemetery (aka German Methodist Church Cemetery) Dept./Div. Street Address Immediately west of 4105 Hempstead Turnpike City
State NY Zip Code 11714 Contact Person Telephone () If the Memorial has been moved, please list former location(s).

FORM CWM #61 Page 2 of 4

Physical Details

Material of Monument or base under a Sculptur name specific material (color of granite	re or Cannon =Stone Concret e, marble, etc.) ^{Black}	e Metal Undetermined If known		
SUVCW CIVIL WAR				
Material of the Sculpture = Stone If known, name specific material (color If the Sculpture is of metal, is it solid	of granite, marble, etc.)			
Material of Plaque or Historical Marke	er / Tablet =	 		
Material of Cannon =Bronze Markings on muzzle =	Iron - Consult known Ordnand	ce Listing to confirm		
Markings on Left Trunion	Right Trunion			
Markings on muzzle = Markings on Left Trunion_ Is inert ammunition a part of the Mem	norial? If so, describe _			
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height 4" Width 17" Depth 20" or Diameter Sculpture: Height Width Depth or Diameter				
For Memorials with multiple Sculpture for each statue and attach to this form weapons/implements involved (in case)	n. Please describe the "pose"	of each statue and any		
Markings/Inscriptions (on stone-wo Maker or Fabricator mark / name? If so				
The "Dedication Text" is formed:	cut into material <u>xxx</u> raised u	p from material face		
Record the text (indicate any separation Alfred and Cornelius Walters Soldiers of the Union Alfred and				
shop. They, along with eleven others from this area, enlisted in	the Union Army during the summer of 1862. As sold	iers in the 145th Regiment, New York		
Volunteer Infantry, the men fought at the battles of Chancellorsville a	nd Gettysburg. Later, they were transfered to the 107th	Regiment, New York Volunteer Infantry		
and fought under General William Tecumseh Sherman in the March	to the Sea. Alfred died of disease at Cumberland Hos	spital, Nashville, Tennessee on January		
29, 1865. Cornelius was wounded during the Battle at Ne	w Hope Church, Georgia but survived until the	end of the war.		
Civil War Veterans - Never Fall Victim to Faded Tombstones or F		, New York In cooperation with the		
Farmingdale Bethpage Historical Society Eagle Project o	f Patrick C. Looney August 21, 2009			
Environmental Setting (The general vicinity and immediate locale surro	ounding a memorial can play a major r	role in its overall condition.)		
XXX Comotory	Park	Plaza/Courtyard		
Cemetery "Town Square"	Post Office	Plaza/Courtyard School		
Municipal Building	State Capitol	Other:		
Courthouse	College Campus	Julio1.		
Traffic Circle	Library			

FORM CWM #61 Page 3 of 4

General Vicinity Rural (low population, open land) Town	Suburban (residen Urban / Metropolita			
Immediate Locale (check as many as may apply) Industrial _xxx_ Commercial Street/Roadside within 20 feet _xxx_ Tree Covered (overhanging branches) Protected from the elements (canopy or enclosure, indoors) Protected from the public (fence or other barrier) Any other significant environmental factor _Approximately 30 feet from Hempstead Turnpike.				
Condition Information				
Structural Condition (check as many as may apply)				
The following section applies to Monuments with Sculpture, and including the base for Monuments with Cannon. Instability in the number of factors. Indicators may be obvious or subtle. Visually	sculpture and its base can	be detected by a		
	Sculpture	Base		
If hollow, is the internal support unstable/exposed? (Look for signs of exterior rust)				
Any evidence of structural instability?				
(Look for cracked joints, missing mortar or caulking or plant gr	owth)			
Any broken or missing parts? (Look for elements (i.e., sword, musket, hands, arms, etc m	issing			
due to vandalism, fluctuating weather conditions, etc.)				
Any cracks, splits, breaks or holes? (Also look for signs of uneven stress & weakness in the mater	ial)			
Surface Appearance (check as many as may apply)				
	Sculpture	Base		
Black crusting				
White crusting Etched, pitted, or otherwise corroded (on metal)				
Metallic staining (run-off from copper, iron, etc.)				
Organic growth (moss, algae, lichen or vines)				
Chalky or powdery stone				
Granular eroding of stone				
Spalling of stone (surface splitting off) Droppings (bird, animal, insect remains)				
Other (e.g., spray paint graffiti) - Please describe				
Monument is in excellent condition as it is only 9 years old.				
Does water collect in recessed areas of the Memorial?	_ Yes <u>xxx</u> No Unable	e to tell		

FORM CWM #61 Page 4 of 4

Surface Coating

Does there appear to be a coating? Yes <u>xxx</u> No Unable to determine If known, identify type of coating.				
Gilded Painted Varnished Waxed Unable to determine				
Is the coating in good condition? Yes No Unable to determine				
Basic Surface Condition Assessment (check one)				
In your opinion, what is the general appearance or condition of the Memorial? XXX Well maintained Would benefit from treatment In urgent need of treatment Unable to determine				
Overall Description				
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). Approximately five feet south of the monument stands a second monument to Alfred S. Walters. The second monument also faces east and sits approximately				
seven feet east of Alfred S. Walters' headstone. The headstone is white and in good condition. The engraving is mostly worn away. The dimentions are				
55"X22"X10". The second monument is in excellent condition. The dimensions are 23"X12"X4" The second monument is engraved as follows:				
ALFRED S. WALTERS A SOLDIER OF THE UNION SON OF TREADWELL AND SARA WALTERS ENLISTED IN 1862 AT AGE 17				
FOUGHT AT CHANCELLORSVILLE AND GETTYSBURG FOLLOWING SHERMAN TO ATLANTA DIED THE 29TH OF JANUARY 1865				
AGED 20 VEARS				

Supplemental Background Information


In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-site Survey May 4, 2018	
Your Name Christopher Shand	
Address 1854 Old Mill Road	City Merrick
State NY Zip Code 11566	Telephone ()
What Order or Organization is submitter	a member of? Moses A. Baldwin Camp #544, SUVCW

Please send this completed form to

Walt Busch, PDC, Chair



Thank you for your help, and attention to detail. Sons of Union V

CIVIL WAR VETERANS OF THE National Civil War Memorials Committee

