PAGE 1 OF 4

NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

 PLEASE: Type or print, using a ball-point pen, when filling out this form. Legibility is critical. Do not guess at the information. An answer of, "Unknown," is more helpful. Include a photograph of each viewable side and label it with name & direction of view - Thank You. 			
Type of Memorial Monument with Sculpture Monument without Sculpture Monument without Sculpture Monument without Sculpture Monument without Sculpture			
Affiliation G.A.R. (Post Name & No			
Location The Memorial is currently located at: Street/Road address or site location U.S. Gowt Home Physical 5'4e City/Village Gowa Township Galera County To Daviess			
The front of the Memorial faces: North South East West Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in) Name U.S. Grant Home Dept./Div. Street Address P.O. Box 333 City Galua State /C Zip Code 6/036 Contact Person Terry Miller Telephone (\$15") 277-9406			
If the Memorial has been moved, please list former location(s)			
Physical Details Material of Monument or base under a Sculpture or Cannon =Stone Concrete Metal Undetermined If known, name specific material (color of granite, marble, etc.)			

Material of the Sculpture = Stone Concrete Metal Undetermined If known, name specific material (color of granite, marble, etc.) Undetermined
If the Sculpture is of metal, is it solid cast or "hollow?" Solid
Material of Plaque or Historical Marker / Tablet =
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle = Right Trunion Right Trunion
Markings on Left Trunion Right Trunion Is inert ammunition a part of the Memorial? If so, describe
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height 3 Width 3 Depth 3 or Diameter Sculpture: Height 35 Width 6 Depth 2.57 or Diameter
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!
Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found
The "Dedication Text" is formed: cut into material raised up from material face
Record the text (indicate any separation if on different sides) Please use additional sheet if necessary. Sows of Union Veterars of the Civil War
Environmental Setting
(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.) Type of Location
Cemetery Park Plaza/Courtyard
"Town Square" Post Office School Municipal Building State Capitol Other:
Municipal Building State Capitol Other: Courthouse College Campus
Traffic CircleLibrary

	urban (residential, ne an / Metropolitan	ar city)
Immediate Locale (check as many as may apply) Industrial Commercial Street/Roadside within 20 feet Tree Covered (ov Protected from the elements (canopy or enclosure, indoor Protected from the public (fence or other barrier) Any other significant environmental factor	ors)	
Condition Information	-	
Structural Condition (check as many as may apply) The following section applies to Monuments <i>with</i> Sculpture, and Monimolarity the base for Monuments with <i>Cannon</i> . Instability in the state of the	culpture and its base car	be detected
If hollow, is the internal support unstable/exposed?	Sculpture	Base
(look for signs of exterior rust) Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth) Any broken or missing parts?		
(look for elements (i.e., sword, musket, hands, arms, etc missing due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)		
Surface Appearance (check as many as may apply)	Sculpture	Base
Black crusting White crusting Etched, pitted, or otherwise corroded (on metal) Metallic staining (run-off from copper, iron, etc.) Organic growth (moss, algae, lichen or vines) Chalky or powdery stone Granular eroding of stone Spalling of stone (surface splitting off) Droppings (bird, animal, insect remains)		
Other (e.g., spray paint graffiti) - Please describe	Yes i No Un	able to tell

Surface Coating Does there appear to be a coating? Yes No Unable to determine If known, identify type of coating Gilded Painted Varnished Waxed Unable to determine Is the coating in good condition? Yes No Unable to determine
Basic Surface Condition Assessment (check one)
In your opinion, what is the general appearance or condition of the Memorial? Well maintained Would benefit from treatment In urgent need of treatment Unable to determine Overall Description Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). Ornate Cast row Revel New The Julia Grant statue at Grant flow history size.
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.
Inspector Identification
Pate of On-site Survey
Your Name Greg Caster Address 1908 267 ST. City Rockford State 1 Zip Code 61108 Telephone
State Zip Code Telephone
Please send this completed form to:
Kevin P. Tucker, PDC, Chair
Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR

National Civil War Memorials Committee