

Material of the Sculpture = Stone ___ Concrete ___ Metal ___ Undetermined
If known, name specific material (color of granite, marble, etc.) _____
If the Sculpture is of metal, is it solid cast or "hollow?" SOLID CAST

Material of Plaque or Historical Marker / Tablet = STONE

Material of Cannon = ___ Bronze ___ Iron - Consult known Ordnance Listing to confirm
Markings on muzzle = _____
Markings on Left Trunion _____ Right Trunion _____
Is inert ammunition a part of the Memorial? NO If so, describe _____

Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points
Monument or Base: Height 5' Width 5' Depth 5' or Diameter _____
Sculpture: Height 10' Width 3' Depth 2' or Diameter _____

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture)
Maker or Fabricator mark / name? If so, give name & location found Lower Rt. Corner
W.H. HOWLETTEN, CITY LOWER STAIRS

The "Dedication Text" is formed: ___ cut into material raised up from material face

Record the text (indicate any separation if on different sides...) Please use additional sheet if necessary.
ERECTED MAY 30, 1885 BY THE CITIZENS OF
JERSEY Co.
LETTER CHIPPED
SHILOH VICKSBURG ATLANTA, CHICKAMAUGA - IN
RAISED LETTERS

Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

Type of Location

- Cemetery
- ___ "Town Square"
- ___ Municipal Building
- ___ Courthouse
- ___ Traffic Circle
- ___ Park
- ___ Post Office
- ___ State Capitol
- ___ College Campus
- ___ Library
- ___ Plaza/Courtyard
- ___ School
- Other: _____

General Vicinity

- Rural (low population, open land) Suburban (residential, near city)
 Town Urban / Metropolitan

Immediate Locale check as many as may apply)

- Industrial Commercial
 Street/Roadside within 20 feet Tree Covered (overhanging branches)
 Protected from the elements (canopy or enclosure, indoors)
 Protected from the public (fence or other barrier)

Any other significant environmental factor _____

IN CENTER OF EIGHT SIDED BARRIER TO MAJOR ISOLATE FROM
CEMETERY TRAFFIC

Condition Information

Structural Condition (check as many as may apply)

The following section applies to Monuments *with* Sculpture, and Monuments *without* Sculpture - including the base for Monuments with *Cannon*. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	___	___
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant growth)	___	___
Any broken or missing parts? (look for elements (i.e. sword, musket, hands, arms, etc. - missing due to vandalism, fluctuating weather conditions, etc.)	___	<input checked="" type="checkbox"/>
Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)	___	___

Surface Appearance (check as many as may apply)

	Sculpture	Base
Black crusting (some)	<input checked="" type="checkbox"/>	___
White crusting	___	___
Etched, pitted, or otherwise corroded (on metal)	___	___
Metallic staining (run-off from copper, iron, etc.)	___	___
Organic growth (moss, algae, lichen or vines)	___	___
Chalky or powdery stone	___	___
Granular eroding of stone	___	___
Spalling of stone (surface splitting off)	___	___
Droppings (bird, animal, insect remains)	___	___
Other (e.g., spray paint graffiti) - Please describe...	___	___

Does water collect in recessed areas of the Memorial? ___ Yes No ___ Unable to tell

Surface Coating

Does there appear to be a coating? Yes No Unable to determine
 If known, identify type of coating.

Gilded Painted Varnished Waxed Unable to determine
 Is the coating in good condition? Yes No Unable to determine

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?
 Well maintained Would benefit from treatment In urgent need of treatment Unable to determine

Overall Description

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).

UNION SOLDIER W/ MUSKET, BROKEN WHEEL AND
STONE CANNONBALLS
4 RED MARBLE PILLARS - (3')
ON FOUR SIDES OF PEDAISTL - WAR SYMBOL DEDICATION
CROSSED CANNONS - CANNONBALLS EAGLE (NO HEAD)
ONE BRASSY PILLAR CORINTHIAN TOP BROKEN

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-site Survey Sept. 12, 1999
 Your Name CAROL BROWN
 Address ~~208 W Fletcher~~ 208 W Fletcher City TAMMONG Jerseyville
 State Ill. Zip Code 62052 Telephone [REDACTED]

Please send this completed form to: **KENT ARMSTRONG**



Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR
 National Civil War Memorials Committee

Dear Kent,
 Sorry this took so long.
 My sister misplaced the form
 but after I returned home
 we found it.
 I am now in Illinois
 permanently.

Best wishes
 to the
 24th!
 Sherill Brown
 Gettysburg, PA





