FORM CWM #61 Page 1 of 4

NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- 1. Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- 2. Do not guess at the information. An answer of, "Unknown," is more helpful. .Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

FORM CWM #61 Page 2 of 4

Physical Details

Material of Monument or base under a Sculpture or C name specific material (color of granite, mai		Metal Undetermined If known
SUVCW CIVIL WAR		
Material of the Sculpture = \times Stone If known, name specific material (color of gr If the Sculpture is of metal, is it solid cast	ranite, marble, etc.)	
Material of Plaque or Historical Marker / T	ablet = Concrete	
Material of Cannon =Bronze _x _Iron Markings on muzzle = _No. 93 _30 PDR _4.2 Markings on Left Trunion1862 Is inert ammunition a part of the Memorial	- Consult known Ordnance L	isting to confirm
Markings on Left Trunion 1862	Right Trunion R.P.P. V	V.P.F.
Is inert ammunition a part of the Memorial Steel base for projectile(s) attached to monument base	!? _x If so, describe	
Approximate Dimensions (indicate unit of Monument or Base: Height 34 in Width Sculpture: Height Width	of measure) - taken from tall 52 in Depth 107 in or D Depth or Diameter _	est / widest points Diameter
For Memorials with multiple Sculptures, please for each statue and attach to this form. Please weapons/implements involved (in case you	ease describe the "pose" of	each statue and any
Markings/Inscriptions (on stone-work / r Maker or Fabricator mark / name? If so, give CONSTANTINE TO HER SOLDIERS 1861-1865		
The "Dedication Text" is formed: _x_ cut i	nto material raised up fr	om material face
Record the text (indicate any separation if o	n different sides) Please use	additional sheet if necessary.
Breech markings - Patented 1861 4250 (weight)		-
Foundry number 234 on right rim base, US on top side of tube.		
Environmental Setting (The general vicinity and immediate locale surroundin Type of Location	ng a memorial can play a major role	in its overall condition.)
Cemetery Town Square" Municipal Building Courthouse Traffic Circle	 × Park Post Office State Capitol College Campus Library 	Plaza/Courtyard School Other:

FORM CWM #61 Page 3 of 4

General Vicinity Rural (low population, open land) Town	Suburban (residen Urban / Metropolita	
Immediate Locale (check as many as may apply) Industrial Commercial Street/Roadside within 20 feet Tree Covered (o Protected from the elements (canopy or enclosure, incomposite protected from the public (fence or other barrier) Any other significant environmental factor	doors)	
Condition Information		
Structural Condition (check as many as may apply)		
The following section applies to Monuments <i>with</i> Sculpture, and including the base for Monuments with <i>Cannon</i> . Instability in the number of factors. Indicators may be obvious or subtle. Visually	sculpture and its base can	be detected by a
	Sculpture	Base
If hollow, is the internal support unstable/exposed? (Look for signs of exterior rust)		No
Any evidence of structural instability?		Yes
(Look for cracked joints, missing mortar or caulking or plant groups Any broken or missing parts? (Look for elements (i.e., sword, musket, hands, arms, etc missing to vandalism, fluctuating weather conditions, etc.)	<u> </u>	Yes
Any cracks, splits, breaks or holes? (Also look for signs of uneven stress & weakness in the materi	al)	Yes
Surface Appearance (check as many as may apply)		
	Sculpture	Base
Black crusting		
White crusting Etched, pitted, or otherwise corroded (on metal)		
Metallic staining (run-off from copper, iron, etc.)		
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone		
Granular eroding of stone		
Spalling of stone (surface splitting off)		
Droppings (bird, animal, insect remains) Other (e.g., spray paint graffiti) - Please describe None of the above.		
Does water collect in recessed areas of the Memorial?	Yes X No Unable	to tell

FORM CWM #61 Page 4 of 4

•			_	4.5	
Sι	irt:	മറമ	()	oati	na
U	4119	acc	\sim	Jau	нч

Does there appear to be a coating? <u>×</u> Yes No Unable to determine If known, identify type of coating.
Gilded x Painted Varnished Waxed Unable to determine
Is the coating in good condition? _x Yes No Unable to determine
Basic Surface Condition Assessment (check one)
In your opinion, what is the general appearance or condition of the Memorial? X Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) . Sons Camp 135 soda blasted and painted this monument August 2011.
It was donated to J.C. Joss GAR 124, 11/13/1897, and was shipped from the New York Arsenal.

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.

Inspector Identification

Date of On-site Survey 6/22/2013	_
Your Name Chuck Worley	
Address 68341 Crooked Creek Rd.	City White Pigeon
State MI Zip Code 49099 Telepl	nor
What Order or Organization is submitter a memb	ner of? SUVCW Camp 135

Please send this completed form to



Thank you for your help, and attention to detail. Sons of Union \boldsymbol{V}

CIVIL WAR VETERANS OF THE National Civil War Memorials Committee















