16 MIZ

SONS OF UNION VETERANS OF THE CIVIL WAR DEPARTMENT OF MICHIGAN CIVIL WAR MEMORIAL ASSESSMENT FORM

| P | L | E | A | S | E | |
|---|---|---|---|---|---|--|
| | | | | | | |

- Type or print, using a ball-point pen when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.

• Include a BLACK & WHITE photograph of each viewable side and label it with name & direction of view. - Thank You. Type of Memorial

 ★ Monument with Sculpture

 ← Monument with Cannon
 ← Historical Marker

 ___ Historical Marker ___ Plaque Affiliation X G.A.R. (Post Name & No. V. O. BRETZ POST NO. 382) __ M.O.L.L.U.S. W.R.C. (Corps Name & No.______) __Other Allied Order SUVCW (Camp Name & No.______) Which?____ __ DUVCW (Tent Name & No._____) Other: _____ **Dedication Date**Please consult any/all newspaper archives for a local paper's article that would have information on the dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you. Location The Memorial is *currently* located at: Street/Road address or site location _____ LAKESIDE (LAKEWOOD) CEMETERY - CEMETERY RD &M-50 City/Village LAKE ODESSA Township ODESSA County /ONIA The front of the Memorial faces: X North South East West Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)... Name VILLAGE OF CAKE ODESSA Dept./Div. CEMETERY Street Address PAGE MEMORIAL BUILDING City LAKE ODESSA State (if not Michigan) MI Zip Code 48849 Contact Person PRESIDENT, TERRY ENGLE Telephone (616) 074-8698 If Memorial has been moved, please list former location(s)... Physical Details Material of Monument or base under a Sculpture or Cannon = X Stone ___ Concrete ___ Metal ___ Undetermined If known, name specific material (color of granite, marble, etc.) GREY GRANITE

| Material of the Sculpture = X StoneConcrete If known, name specific material (color of granite, marble, etc If the Sculpture is of metal, is it solid cast or "hollow?" _ | .) GREY GRANITE |
|---|---|
| Material of Plaque or Historical Marker / Tablet = | |
| Material of Cannon =BronzeIron - Consult kno Markings on muzzle = Markings on Left TrunionRight Is inert ammunition a part of the Memorial?If so, | Trunion |
| Approximate Dimensions (indicate unit of measure) - to Monument or Base: Height 9年 Width 4年 Dept Sculpture: Height 6年 Width 12年 Dept | h 4FT or Diameter |
| For Memorials with multiple Sculptures, please record sheet of paper for each statue and attach to this form. each statue and any weapons/implements involved (separated from this form). Thank you! | Please describe the "pose" of |
| Markings/Inscriptions (on stone-work / metal-work of m Maker or Fabricator mark / name? If so, give name & loc | nonument, base, sculpture) cation found |
| The "Dedication Text" is formed: cut into material face | x raised up from material |
| Record the text (indicate any separation if on different sides) Please NORTH SIDE - "CHICAMAUGA" AT TOP, CRUSSED FLAGS SET CITIZENS OF CRESSA TOWNSHIP UNDER THE AUSPICES OF WEST SIDE - "ANTIETAM" AT TOP, MUZZEE OF CANNOT UNDER VETH. SOUTH SIDE - "GETTYS BURGE" AT TOP, G. A.R. BADGE COE EAST SIDE - "SHILDH" AT TOP, MUZZEE OF CANNOT KNAPSACK ON RIGHT | TIM CENTER "ERECTED BY THE V.O. BRETZ POST NO. 882 GAR." ON WITH CROSSED SWIRDS OT INTO CENTER ON WITH CANTEEN ON CEFT AND |
| Environmental Setting (The general vicinity and immediate locale surrounding a memorial can play Type of Location X Cemetery Park "Town Square" Post Office | a major role in its overall condition.) Plaza/Courtyard School |
| Municipal Building State Capitol Courthouse College Campus Traffic Circle Library | Other: |

| General Vicinity | . / Cuburban /residential no | :A\ |
|--|---|--------------------|
| Rural (low population, open land) Town | Suburban (residential, neadle | ar city) |
| Immediate Locale (check as many as may appl | 5.0 | |
| Industrial | Commercial | |
| X Street/Roadside within 20 feet | Tree Covered (overhangin | g branches) |
| Protected from the elements (canopy or end | | |
| Protected from the public (fence or other ba | rrier) | |
| Any other significant environmental factor _ | | |
| | | |
| | 7.00 | |
| | e see a suit la | |
| Condition Information | | |
| Condition information | | |
| | | |
| Structural Condition (check as many as may a | | 77 20 1001 1000 |
| The following section applies to Monuments with Sculptur | | |
| the base for Monuments with <i>Cannon</i> . Instability in the number of factors. Indicators may be obvious or subtle. V | | |
| multiple of factors. Indicators may be obvious of cubits. | | base. |
| | Sculpture | Base |
| If he live is the interval of the analysis and a second of the live of the liv | | |
| If hollow, is the internal support unstable/exposed? (look for signs of exterior rust) | rikogelijek vog P rista n egusti. Ist | |
| Any evidence of structural instability? | Arres and the state of the | |
| (look for cracked joints, missing mortar or caulking or plant | growth) | |
| Any broken or missing parts? | generalija ne up a | |
| (look for elements (i.e., sword, musket, hands, arms, etc r | nissing | The second |
| due to vandalism, fluctuating weather conditions, etc.) | | |
| Any cracks, splits, breaks or holes? | | |
| (also look for signs of uneven stress & weakness in the mat | erial) | |
| Surface Appearance (check as many as may a | (ylqqı | |
| , | Sculpture | Base |
| Black crusting | | X |
| White crusting | a year a contract of | |
| Etched, pitted, or otherwise corroded (on metal) | | |
| Metallic staining (run-off from copper, iron, etc.) | | |
| Organic growth (moss, algae, lichen or vines) | ealil V J | X |
| Chalky or powdery stone | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | |
| Granular eroding of stone | 1 00 V | |
| Spalling of stone (surface splitting off) | | - |
| Droppings (bird, animal, insect remains) | | - |
| Other (e.g., spray paint graffiti) - Please describ | | |
| Other (e.g., spray paint grantil) - Flease descri | 76 | |
| | | |
| | | |
| | | |

| Does water collect in recessed areas of the Memorial? | Yes X No Unable to tell |
|--|---|
| Surface Coating Does there appear to be a coating? YesX N If known, identify type of coating. Gilded Painted Varnished Wax Is the coating in good condition? Yes No | |
| Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or cond X Well maintained Would benefit from treatment In urgent ne | lition of the Memorial? |
| Overall Description Briefly describe the Memorial (affiliation / overall condition & any co SCULPTBEE OF INFANTRYMAN AT A LOADING . HAVERSACK LOCK PLATE ON RIFLE IS INVERTED. | ncern not already touched on) . STANCE WITH CANTEEN AND |
| | |
| Supplemental Background Information In addition to your on-site survey, any additional information Memorial will be welcomed. Please label each account with date, pages). Topics include any reference to the points list previous conservation treatments - or efforts to raise money for the supplemental previous conservation treatments. | its source (author, title, publisher, ted on this questionnaire, plus any |
| Inspector Identification Date of On-site Survey SEPT 1999 Your Name Dove Armstrone | |
| Address 236 E FREPERICK | City CANSING. |
| State (If Non-Michigan Resident) Zip Code _48906 | |

Please send this completed form to:

William R. Morris 10324 W. Stanley Rd. Flushing, MI 48433-9247

Thank you for your help, and attention to detail.

Kent Armstrong, Chair Memorials Subcommittee - Department of Michigan

