FORM CWM #61 Page 1 of 4

NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- 1. Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- 2. Do not guess at the information. An answer of, "Unknown," is more helpful. .Include a photograph of each viewable side and label it with name & direction of view.

- Thank You.

Type of Memorial Monument with Sculpture Monument with Cannon Monument without Sculpture Historical Marker Plaque X Other (flag pole, G.A.R. buildings, stained glass windows, etc.)
Affiliation _ G.A.R. (Post Name & No) M.O.L.L.U.S _ SUVCW (Camp Name & No) (Please describe below) _ WRC (Corps Name & No)) _ ASUVCW (Aux Name & No)) _ DUVCW (Tent Name & No)) _ LGAR (Circle Name & No
Original Dedication Date unknown Please consult any/all newspaper archives for a local paper's article that would have information on the <i>first</i> dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.
Location The Memorial is currently located at: N39.117292 and W93.211042 Street/Road address or site location 475 Davis Avenue City/Village Marshall Township Marshall County Saline State Missouri The front of the Memorial faces: North South X East West
Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in) Name Missouri National Guard Armory Dept./Div. Marshall National Guard Armory Street Address 475 Davis Avenue City State MO Zip Code 65340 Contact Person Telephone ()
If the Memorial has been moved, please list former location(s).

FORM CWM #61 Page 2 of 4

Physical Details

Material of Monument or base under a Sculp name specific material (color of gran		
SUVCW CIVIL WAR		
Material of the Sculpture = Storing If known, name specific material (co If the Sculpture is of metal, is it sol	lor of granite, marble, etc.)	
Material of Plaque or Historical Ma	rker / Tablet =	
Material of Cannon =Bronze _X Markings on muzzle = _none visible Markings on Left Trunion_none visible Is inert ammunition a part of the M	Iron - Consult known Ordnand	e Listing to confirm
Markings on Left Trunion none visible	Right Trunion none	evisible
Is inert ammunition a part of the M	emorial? If so, describe _	
Approximate Dimensions (indicated Monument or Base: Height 42" Sculpture: Height Width	te unit of measure) - taken from the width 48" Depth 24" or Diamete	tallest / widest points r Diameterer
For Memorials with multiple Sculpt for each statue and attach to this for weapons/implements involved (in o	orm. Please describe the "pose"	of each statue and any
Markings/Inscriptions (on stone- Maker or Fabricator mark / name? If Tube Cannon 843939		
The "Dedication Text" is formed: _	cut into material raised սր	o from material face
Record the text (indicate any separa	ation if on different sides) Please u	se additional sheet if necessary.
Environmental Setting		
(The general vicinity and immediate locale s Type of Location	urrounding a memorial can play a major re	ole in its overall condition.)
Cemetery	Park	Plaza/Courtyard
"Town Square"	Post Office	School
Municipal Building	State Capitol	Other:
Courthouse	College Campus	National Guard Amory
Traffic Circle	Library	

FORM CWM #61 Page 3 of 4

General Vicinity Rural (low population, open land) Town	Suburban (residen Urban / Metropolita	
Immediate Locale (check as many as may apply) Industrial Commercial × Street/Roadside within 20 feet Tree Covered (composed from the elements (canopy or enclosure, incomposed from the public (fence or other barrier) Any other significant environmental factor	doors)	
Condition Information		
Structural Condition (check as many as may apply)		
The following section applies to Monuments with Sculpture, and including the base for Monuments with Cannon. Instability in the number of factors. Indicators may be obvious or subtle. Visually	sculpture and its base can	be detected by a
If hollow, is the internal support unstable/exposed?	Sculpture	Base
(Look for signs of exterior rust) Any evidence of structural instability?	<u>—</u>	
(Look for cracked joints, missing mortar or caulking or plant gr Any broken or missing parts?	rowth)	
(Look for elements (i.e., sword, musket, hands, arms, etc midue to vandalism, fluctuating weather conditions, etc.)	issing	
Any cracks, splits, breaks or holes? (Also look for signs of uneven stress & weakness in the mater)	ial)	
Surface Appearance (check as many as may apply)		
	Sculpture	Base
Black crusting White crusting		
Etched, pitted, or otherwise corroded (on metal)		
Metallic staining (run-off from copper, iron, etc.)		
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone Granular eroding of stone		
Spalling of stone (surface splitting off)		
Droppings (bird, animal, insect remains)		
Other (e.g., spray paint graffiti) - Please describe		
Does water collect in recessed areas of the Memorial?	_ Yes ^x _ No Unable	to tell

FORM CWM #61 Page 4 of 4

Surface Coating
Does there appear to be a coating? X Yes No Unable to determine If known, identify type of coating. Gilded X Painted Varnished Waxed Unable to determine Is the coating in good condition? Yes No Unable to determine
Basic Surface Condition Assessment (check one)
In your opinion, what is the general appearance or condition of the Memorial? X Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description
Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on). 3-inch ordinance riffle mounted on a concrete block at front entrance to the Marshal National Guard Armory. Cannon measures 64" long with a 3" barrel. A brace tag on the concrete states "Tube Cannon 843939."

Supplemental Background Information
In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.
Inspector Identification
Date of On-site Survey 22 July 2015 Your Name Dale Crandell
What Order or Organization is submitter a member of? Westport Camp #64
Please send this completed form to

Thank you for your help, and attention to detail. Sons of Union \boldsymbol{V}

CIVIL WAR VETERANS OF THE National Civil War Memorials Committee





