Physical Details

NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

 PLEASE: Type or print, using a ball-point pen, when Do not guess at the information. An answer Include a photograph of each viewable side a 	er of, "Unknown," is more helpful.
Type of Memorial	
Monument <i>with</i> Sculpture Monument <u>without</u> Sculpture	Monument with Cannon X Historical Marker Plaque
Affiliation	
G.A.R. (Post Name & No	\ MOLLUS
W.R.C. (Corps Name & No.) Other Allied Order
SUVCW (Camp Name & No) (Please describe below
DUVCW-(Tent Name & No	
X Other: Dr. J.A. Carter	
Location The Memorial is currently located at: Street/Road address or site location City Park, No.	
City/Village Carthage Township	County Jasper
The front of the Memorial faces: North Government Body, Agency, or Individual Owner (X South East West of private cemetery that Memorial is located in)
Name City of Carthage	Dept./Div.
Street Address 326 Grant St	Chala up Zin Codo ssees
Centest Borson www.	State MO Zip Code 65836
Contact Person Unknown	_ Telephone (417) 237-7000
If the Memorial has been moved, please list fo	ormer location(s)

Material of Monument or base under a Sculpture or Cannon = X Stone ___ Concrete ___ Metal ___ Undetermined

If known, name specific material (color of granite, marble, etc.) Grey Granite & mortar

Material of the Sculpture = _ If known, name specific material If the Sculpture is of metal, is	l (color of gra	anite, marble, etc.)		
Material of Plaque or Historic	al Marker /	Tablet = Grey Gran	ite	
Material of Cannon =Bro Markings on muzzle = _not applie Markings on Left Trunion Is inert ammunition a part of the	cable			
Approximate Dimensions (i Monument or Base: Height _ Sculpture: Height _				
For Memorials with multiple sheet of paper for each state each statue and any weap separated from this form). The	ue and attac oons/implem	ch to this form.	Please desc	cribe the "pose" of
Markings/Inscriptions (on s Maker or Fabricator mark / na				
The "Dedication Text" is form	ed: <u>×</u> cut	into material	_ raised up	from material face
Record the text (indicate any separ			e use additiona	al sheet if necessary.
Environmental Setting (The general vicinity and immediate loc	ale surrounding	a memorial can play a	major role in its	overall condition.)
Type of Location Cemetery "Town Square" Municipal Building Courthouse Traffic Circle		Park Post Office State Capitol College Campus Library	Othe	Plaza/Courtyard School er: Roadside

General Vicinity Rural (low population, open land) Town	Suburban (residential, r Urban / Metropolitan	near city)
Immediate Locale (check as many as may applyIndustrial Street/Roadside within 20 feet Protected from the elements (canopy or enclo Protected from the public (fence or other barr Any other significant environmental factor	Commercial Tree Covered (overhang osure, indoors) rier)	ging branches)
Condition Information	į.	
Structural Condition (check as many as may an The following section applies to Monuments with Scuincluding the base for Monuments with Cannon. Instability by a number of factors. Indicators may be obvious or subase.	ilpture, and Monuments <u>witho</u> in the sculpture and its base ca	an be detected
	Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)		
Any evidence of structural instability? (look for cracked joints, missing mortar or caulking or plant groups)		
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc misdue to vandalism, fluctuating weather conditions, etc.)	ssing	
Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the materi	al)	and the second
Surface Appearance (check as many as may ap	oply) Sculpture	Base
Black crusting	-	-
White crusting	abeninostrian	s)#a/filifilitation/colorada
Etched, pitted, or otherwise corroded (on metal) Metallic staining (run-off from copper, iron, etc.)		MANAGEMENT
Organic growth (moss, algae, lichen or vines)	•	
Chalky or powdery stone		-
Granular eroding of stone	- ·	9-19-16-16-16-16-16-16-16-16-16-16-16-16-16-
Spalling of stone (surface splitting off)		MAN 1974 (A) (A) (A)
Droppings (bird, animal, insect remains)	-	
Other (e.g., spray paint graffiti) - Please describe	····	
Does water collect in recessed areas of the Memorial?	Yes _X_NoU	Inable to tell

Surface Coating
Does there appear to be a coating? Yes _X No Unable to determine
If known, identify type of coating.
Gilded Painted Varnished Waxed Unable to determine Is the coating in good condition? Yes No Unable to determine
Is the coating in good condition?YesNoUnable to determine
Basic Surface Condition Assessment (check one)
In your opinion, what is the general appearance or condition of the Memorial? X Well maintained Would benefit from treatment In urgent need of treatment Unable to determine
Overall Description Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).
This text is on the entrance to the park and is right next to "Line of Battle July 5, 1861 No. 4" marker, the entrance pillar on the other side gives the dedication
of the park date and that it was donated by Dr. Carter.
In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you. Inspector Identification Date of On-site Survey 18 Dec 2006 Your Name Walter E. Busch, US Grant Camp #68 Commander
Please send this completed form to:
riease send this completed form to:
Todd A. Shillington, PDC

Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War National Civil War Memorials Committee



