FORM CWM #61 **PAGE 1** OF 4

NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

PLEASE:

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.
- Include a photograph of each viewable side and label it with name & direction of view.

- Thank You. Type of Memorial Monument with Sculpture _ Monument with Cannon X Historical Marker Plaque Monument without Sculpture **Affiliation** G.A.R. (Post Name & No._____ M.O.L.L.U.S.) ___ Other Allied Order W.R.C. (Corps Name & No._____ SUVCW (Camp Name & No.) (Please describe below) DUVCW (Tent Name & No. X Other: Drury College (probably some graduating class) Original Dedication Date pre-1970 Please consult any/all newspaper archives for a local paper's article that would have information on the first dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you. Location The Memorial is *currently* located at: Street/Road address or site location N37°13.125' W93°17.179 East of Burnham Hall City/Village Springfield Township County Greene The front of the Memorial faces: North South East X West Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)... Name Drury University Dept./Div. Street Address 900 No Benton Ave State MO City Springfield Zip Code 65802 Contact Person _____ Telephone (800) 922-2274 If the Memorial has been moved, please list former location(s)... **Physical Details** Material of Monument or base under a Sculpture or Cannon = XStone ___ Concrete ___ Metal ___ Undetermined If known, name specific material (color of granite, marble, etc.) common stone

Material of the Sculpture = If known, name specific mate If the Sculpture is of metal,	rial (color of gr	ranite, marble, et	c.)	
Material of Plaque or Histo				
Material of Cannon =B Markings on muzzle =			own Ordnar	nce Listing to confirm
Markings on Left Trunion_		Right	Trunion	
Is inert ammunition a part of	of the Memori	al? If so	o, describe	
Approximate Dimensions Monument or Base: Heigh Sculpture: Heigh	(indicate unit t <u>3 1/2 ft</u> Wid t Wi	of measure) - t dth <u>2 ft</u> De dth De	taken from pth2ft_oth	tallest / widest points or Diameter or Diameter
For Memorials with multiple sheet of paper for each state and any we separated from this form).	atue and atta apons/implem	ch to this form.	Please de	escribe the "pose" of
Markings/Inscriptions (on Maker or Fabricator mark /				• • •
The "Dedication Text" is for	med: cut	into material _	imes raised u	p from material face
Record the text (indicate any sep See Attached	paration if on diff	erent sides) Plea	ase use additi	onal sheet if necessary.
				· · · · · · · · · · · · · · · · · · ·
Environmental Setting				
(The general vicinity and immediate I Type of Location	ocale surrounding	a memorial can play	a major role in	its overall condition.)
Cemetery	Р	ark		Plaza/Courtyard
_	P	ost Office	_ _	School
Municipal Building		State Capitol	0	ther:
Courthouse	<u>×</u> (College Campus	_	
Traffic Circle		ibrary		

General Vicinity				
Rural (low population, open land) Town Suburban (residential, near city) Urban / Metropolitan				
Immediate Locale (check as many as may apply) _ Industrial Commercial _ Street/Roadside within 20 feet Tree Covered (over the elements (canopy or enclosure, indoo the protected from the public (fence or other barrier) Any other significant environmental factor	rs)			
Condition Information				
Structural Condition (check as many as may apply) The following section applies to Monuments <i>with</i> Sculpture, and Mon	uments without Sculpt	ure -		
including the base for Monuments with <i>Cannon</i> . Instability in the so by a number of factors. Indicators may be obvious or subtle. Vi base.				
	Sculpture	Base		
If hollow, is the internal support unstable/exposed?				
(look for signs of exterior rust) Any evidence of structural instability?				
(look for cracked joints, missing mortar or caulking or plant growth)				
Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc missing				
due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes?				
(also look for signs of uneven stress & weakness in the material)				
Surface Appearance (check as many as may apply)		_		
Black crusting	Sculpture	Base		
White crusting				
Etched, pitted, or otherwise corroded (on metal)				
Metallic staining (run-off from copper, iron, etc.)				
Organic growth (moss, algae, lichen or vines)	-			
Chalky or powdery stone Granular eroding of stone				
Spalling of stone (surface splitting off)				
Droppings (bird, animal, insect remains)				
Other (e.g., spray paint graffiti) - Please describe				
Does water collect in recessed areas of the Memorial?	res No X l	Jnable to tell		

Surface Coating Does there appear to be a coating? Yes No Unable to determine f known, identify type of coating. Gilded Painted Varnished Waxed Unable to determine s the coating in good condition? Yes No X_ Unable to determine
Basic Surface Condition Assessment (check one)
n your opinion, what is the general appearance or condition of the Memorial? X Well maintained Would benefit from treatment In urgent need of treatment Unable to determine Dverall Description Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).
Supplemental Background Information n addition to your on-site survey, any additional information you can provide on the described
Memorial will be welcomed. Please label each account with its source (author, title, publisher late, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.
nspector Identification Date of On-site Survey Our Name Walt Busch US Grant 68
Please send this completed form to:
Bruce B. Butgereit, PDC, Chair

Thank you for your help, and attention to detail.

SONS OF UNION VETERANS OF THE CIVIL WAR National Civil War Memorials Committee

Drury College Entrenchement N37'13.125' W93'17.179 3 ½ h x 2 w

East of Burnham Hall

[TEXT]

This is the site of Civil War Entrenchments Used In Defense of Springfield.

200 Yards North is the Site of Indian Mounds.

200 Feet South Stood the Drury Academy Building.

Across This Site Ran the Ridge Road to St. Louis





