NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM


PLEASE:	
 Type or print, using a ball-point pen, when Do not guess at the information. An answ Include a photograph of each viewable side a 	ver of, "Unknown," is more helpful.
Time of Many 2.1	- Thank You.
Type of Memorial	
X Monument with Sculpture	Monument with Cannon
Monument without Sculpture	Historical Marker Plaque
A ffilia di aus	
Affiliation	
G.A.R. (Post Name & No)M.O.L.L.U.S.
vv.R.C. (Corps Name & No) Other Allied Order
SUVCW (Camp Name & No	(Please describe below)
DUVCW (Tent Name & No)
X Other: GRANT MEMOR	AL ASSOCIATION OF MISSOURI
Original Dedication Date	dedication ceremony and/or other facts on the memorial
Location The Memorial is currently located at: Νε Construction Street/Road address or site location Market City/Village Street/Street	1'54" N38° 37'39" MENER OF CITY HALL PROPERTY ET AT TUCKER
City/Village St Louis Township	County & Louis Copy
The front of the Memorial faces: X North	397
Commence D. I. A.	8 8
Government Body, Agency, or Individual Owner (of private cemetery that Memorial is located in)
Name City of Sthous	Dept./Div. FACILITIES MANAGEMENT
Street Address 1200 MARKET City ST Louis	Ctota 1 7 0 1 1 1 1 1
	State Mo Zip Code 63/03
Contact Person FACILITIES MANAGEMENT	_ relephone (314) 613-7280
If the Memorial has been moved, please list for	ormer location(s)
MAKNOWN ON N/A	
	- Carlos Car
Physical Details	
Material of Monument or base under a Sculpture or Cannon	= XStone Concrete Metal Undetermined
If known, name specific material (color of granite,	marble, etc.) GRANITE
, ,	

Material of the Sculpture =StoneConcreteX MetalUndetermined If known, name specific material (color of granite, marble, etc.)Bronzs If the Sculpture is of metal, is it solid cast or "hollow?"wkrown
Material of Plaque or Historical Marker / Tablet = Browze
Material of Cannon = MABronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle = Right Trunion Right Trunion Is inert ammunition a part of the Memorial? If so, describe
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height 10 Width 6 Depth 0 or Diameter Sculpture: Height 9'\$6" Width 3 Depth 3 or Diameter
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!
Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found R.P. Bringhurst American Brings Co Chicago, Icc.
The "Dedication Text" is formed: X cut into material raised up from material face
Record the text (indicate any separation if on different sides) Please use additional sheet if necessary. "PICTURE GRANT PROFILE ON HOMSE LABELED LOOKOUT MOUNTAIN" "ULYSSES S. GRANT" INSCRIBED ON BRONZE PLAQUE JETWEEN LOOKOUT MOUNTAIN PICTURE & STATUE.
R.P. BRINGHURST (Sculpton) BASE of STATUTE
AMERICAN BRONZE: CHICAGO ILL. BASE OF BTATHE
÷ 19
Environmental Setting (The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)
Type of Location
CemeteryParkPlaza/Courtyard★ "Town Square"Post OfficeSchoolMunicipal BuildingState CapitolOther:★ CourthouseCollege Campus
Traffic Circle Library

General Vicinity		
Rural (low population, open land) Town	Suburban (residential, near o	city)
Immediate Locale (check as many as may a Industrial Street/Roadside within 20 feet Protected from the elements (canopy or Protected from the public (fence or othe Any other significant environmental factor)	Commercial Tree Covered (overhanging brenclosure, indoors) r barrier)	ranches)
	<u> </u>	
	and the second second	
Condition Information		
w		
Structural Condition (check as many as m The following section applies to Monuments with Scu the base for Monuments with Cannon. Instability in number of factors. Indicators may be obvious or subtle	ulpture, and Monuments without Sculpture - in the sculpture and its base can be detected	ted by a
	Sculpture	Base
If hollow, is the internal support unstable/expose (look for signs of exterior rust)	d? <u>M4</u>	No
Any evidence of structural instability?	No	NO
(look for cracked joints, missing mortar or caulking or p Any broken or missing parts?	اهماد growth)	No
(look for elements (i.e., sword, musket, hands, arms, e due to vandalism, fluctuating weather conditions, etc.)	tc missing	
Any cracks, splits, breaks or holes?	<i>№</i>	<i>₩</i> υ
(also look for signs of uneven stress & weakness in the	A	
Surface Appearance (check as many as m		-
Black crusting	Sculpture	Base
White crusting	<u> </u>	No
Etched, pitted, or otherwise corroded (on m	No.	No
THE RESERVE TO SERVE THE PROPERTY OF THE PROPE		No No No
Metallic staining (run-off from copper, iron, e Organic growth (moss, algae, lichen or vine	FEET	N/A
Chalky or powdery stone	A STATE OF THE STA	1/2
Granular eroding of stone	<u>N/4</u>	
Spalling of stone (surface splitting off)	<u> </u>	No
Droppings (bird, animal, insect remains)	NA	No
Other (e.g., spray paint graffiti) - Please de	scribe.	No
ONE WOND of GRAFFITI: "W.	ATER" ON GRANITE.	
U		
		VI
Does water collect in recessed areas of the Men	norial? Yes 🔼 No Unabl	le to tell

Surface Coating Does there appear to be a coating? Yes No If known, identify type of coating. Gilded Painted Varnished Waxed Is the coating in good condition? Yes No	X. Unable to determine
Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or condition Well maintained X Would benefit from treatment In urgent need of	of the Memorial? treatment Unable to determine
Overall Description Briefly describe the Memorial (affiliation / overall condition & any concern OEXY GOOD SHAPE . INSPECT ON 2 YEAR CYCLE. C REMOVE GREEN ON SIDES/ROTTONIS OF BOOTS.	WILLD USE PURISHING TO
Supplemental Background Information In addition to your on-site survey, any additional information you Memorial will be welcomed. Please label each account with its state, pages). Topics include any reference to the points listed of previous conservation treatments - or efforts to raise money for treatments.	ource (author, title, publisher, n this questionnaire, plus any
Inspector Identification Date of On-site SurveyO7 MAR · 2005 Your NameWALTER E. Busch	Camp 68 MO SUVCW

Please send this completed form to:



Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War National Civil War Memorials Committee

General Ulysses S. Grant by Robert P. Bringhurst



Title: General Ulysses S. Grant, 1888

Artist: Robert P. Bringhurst Artist Bio: 1858-1925

Medium: Bronze with granite pedestal

Dimensions: 9'6

Location: City Hall Plaza Owner: City of St. Louis

Donor: Grant Memorial Association of Missouri

Purchase Price: \$10,000

The statue is a public tribute to Grant, who resided in St. Louis for six years. While here, he met and married Julia Dent and unsuccessfully farmed the land on Gravois, known today as Grant's Farm. Grant held many jobs here, including selling real estate and clerking in the Customs House. He applied for the position of County Engineer, but was rejected and finally moved away to work for his father-in-law before he became the 18th President of the United States.

The sculpture, a gift of the Grant Monument Association, was unveiled in 1888 on a site in the middle of 12th Street between Olive and Locust. Once the new City Hall was completed in 1898, the sculpture was moved to the south entrance. The Grand Army of the Republic, objecting that the south entrance was the 'back door' persisted in getting the city to appropriate \$1,500 in 1915 to move it to its current location.

