FORM CWM #61 Page 1

### NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL ASSESSMENT FORM

	oriai (cneck a			with Cann	on standalone Cannon
Historical Ma	with Occupture	Other (	flag pole. G	AR buildings.	stained glass windows, etc.)
1   10   10   10   10   10   10	r laque		ilag polo, o.	, t. banan 190,	otamou glado vimadivo, oto.)
Affiliation					
	MOLLUS	SUV	?\\\	WRC	ASUVCW
LGAR	DUVCW	Other	-	~~~	
If known, record name	e and number of post,	camp, corps, aux	kiliary, tent, circ	le or appropriate i	nformation of other groups:
Colegrove Post No. 166	s, GAR				
Original Dedicat	ion Date 17 Mar 1903	3	Please c	onsult any/a <b>ll</b> news	spaper archives for a local paper's arti
that would have inforr	mation on the <i>first</i> dedi	cation ceremony	and/or other fa	acts on the memor	ial. Please submit a copy of your findi
with full identification	of the paper & date of	publication. Thar	ък you.		
Location					
	currently located	l at:			
	lress or site locat				
402 E Michigan Ave		<u></u>	GPS Cod	ordinates N42°1	5'19032 W84°57'18.281
City/Village &/or	Township Marshal		_		
County Calhoun	I		State MI		Zip Code 49068
·			_		<u> </u>
The front of the	Memorial faces:	North	_ South _	East W	/est
Government Re	ody, Agency, or	Individual (	)wner		
Name Marshall Histo		marviadar	J WIICI		
Dept./Div. 402 E N	diahinan Aug				
			State MI		Zip Code
•				e (269 ) 781-854	
			<del>_</del>	· /	
Is Memorial on t	he National Regi	ster of Histor	ric Places _	YesN	lo ID # if known
It is mentioned in a hist	oric district application, bu	ut it is not consider	ed significant en	ough	
For Monuments	s with/without s	culpture:			
Physical Detail		oa.pta.o.			
		Sculpture or Ca	nnon =	Stone Concre	te MetalOther
If known, name spe	cific material (color	of granite, mark	ole, etc.)		
	ptureStone_ ecific material (color o			Other Is	t hollow or solid?

FORM CWM #61 Page 2 For Historic Marker or Plaque: Material of Plaque or Historical Marker / Tablet = For Cannons with/without monument: Material of Cannon = \_\_\_\_ Bronze \_\_\_\_ Iron Type of Cannon (if known) \_\_\_\_\_ Rifled \_\_\_\_YES \_\_\_\_ Markings: Muzzle\_\_\_\_\_\_ Base Ring/Breech\_\_\_\_ Left Trunion Right Trunion Is inert ammunition a part of the Memorial? [For camp/department monuments officer's use: Cannon on list of known ordnance] Yes For Other Memorials: (flag pole, G.A.R. buildings, stained glass windows, etc.) **GAR Hall** What best describes the memorial brick and wood building on a stone base built on a 11,151 Sq Feet Lot Materials of the Memorial Complete for All Memorials Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Height Width Depth or Diameter For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue (service, pose, etc) and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you! Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found Please attach legible photographs of all text &/or Record the text in the space below. Please use the addendum – narrative sheet if necessary.

FORM CWM #61 PAGE 3

(The general vicinity and in		g a memorial can play a maj	or role in its overall condit	ion.)
Type of Location Cemetery School	Park Municipal Building	Plaza/Courtyard State Capitol	"Town Square" Courthouse	Post Office College Campus
Traffic Circle	Library	Other: Historical Society / GAR	Building	
General Vicinity Rural (low population	on, open land) Su	burban (residential, near d	city) <u>~</u> Town Urb	oan / Metropolitan
Industrial Co		apply) eet/Roadside within 20 fe nclosure, indoors) Pro		
Any other significant en	vironmental factor			
[To deta	il the condition of a moni	ument used the addendur	n form for Monument's	Condition]
listed on this questionna Addendums attached to	aire, plus any previous co o this electronic file are th	or, title, publisher, date, pa conservation treatments - on the <i>Monument's Condition</i> grant money using form	r efforts to raise money and the <i>Narrative</i> form	for treatment. s. Only the <i>Monument'</i> s
Inspector Identificat Your Name Walter E B	usch	f On-site Survey 9 Aug	g 2022	
Address 1240 Konert Va	lley Dr			
City Fenton			Zip Code 63026	
Telephone( )		E-Mail		
•	of the Allied Orders of Missouri - Sons of Union Veter	of the G.A.R.? If so, y	which one?	
Please send this co	V	Valt Busch, PDC, Cha 1240 Konert Valley Di Fenton, MO 63026 (314) 630-8407 vebusch@hotmail.com	:	

Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War - Civil War Memorials Committee.

FORM CWM #61 ADDENDUM 1

#### SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL ASSESSMENT FORM ADDENDUM – MONUMENT'S CONDITION

Completion of this form is required when requesting grant money using form CWM-62 SUVCW Memorial Grant Application Form and Instructions.

#### **Condition Information**

#### **Structural Condition** (check as many as may apply)

The following section applies to <u>Monuments with Sculpture</u>, and <u>Monuments without Sculpture</u> including the base for <u>Monuments with Cannon</u>. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If hollow, is the internal support unstable/exposed?		
(Look for signs of exterior rust)		
Any evidence of structural instability?  (Look for cracked joints, missing mortar or caulking or plant growth)		
Any broken or missing parts?		
(Look for elements (i.e., sword, musket, hands, arms, etc missing		
due to vandalism, fluctuating weather conditions, etc.)		
Any cracks, splits, breaks or holes?  (Also look for signs of uneven stress & weakness in the material)		
(Also look for signs of unevert stress & weakness in the material)		
Surface Appearance (check as many as may apply)		
	Sculpture	Base
Black crusting	•	
White crusting		
Etched, pitted, or otherwise corroded (on metal)		<u> </u>
Metallic staining (run-off from copper, iron, etc.)		
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone		
Granular eroding of stone		
Spalling of stone (surface splitting off)		
Droppings (bird, animal, insect remains)		
Other (e.g., spray paint graffiti) - Please describe		
Generally in good Condition		
Does water collect in recessed areas of the Memorial?YesNo	Unable to tell	
Surface Coating		
· ·		
Does there appear to be a coating?Yes NoUnable to c	letermine	
If known, identify type of coating.		
Gilded Painted Varnished Waxed Unable	e to determine	
Is the coating in good condition?Yes No Unable to determine		
Pagis Surface Condition Assessment (shock and)		
Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or condition of the Memoria	al2	
Well maintained V Would benefit from treatment In urgent n		nable to determine
Well maintained would beliefft from treatment in digent in	eed of freatment of	lable to determine
Briefly describe the Memorial (affiliation / overall condition & any concern no	ot already touched on).	
	,	
Juguestan's Name, Walt Blisch		
Inspector's Name Walt BUsch Date	e	

#### SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL ASSESSMENT FORM ADDENDUM – NARRATIVE

[Generally used to record the text of monuments, but may be used for any other useful information, such as if the monument has been moved or if you have information about the day of dedication. May repeat use of page as often as necessary.]


	GPS Coordinates_N	J42°16'19032 W84°57'18.281		
City/Village and/or Township Marshall				
County Calhoun	State_MI	Zip Code		
TEXT				
The G.A.R. Hall was built in 1903 at a cost of \$3,000 Michigan Engineers and Mechanics, one of the three				
A cannon was placed on the west side of the G.A.R. shipped from the arsenal at the Watervliet, New Yor with a brass plate. Originally the monument was bet facing north. The city also donated the plot at Oakric by the government. This mortar is quite a collectors was shipped from the arsenal at Frankfort Philadelpl	k. In 1911 the City of Marshall e ween the curb and sidewalk and age Cemetery, decorated with a item being the first one cast by	erected a stone monument to the GAR veterans d faced south, later moved to the present location large siege mortar and cannon balls also donated		
The GAR Hall was the meeting place for the Colegron Relief Corps) in 1905, Ice Cream Social in 1914, Go of Union Veterans) were still meeting there as late a (Woman's Relief Corps) in 1948, the Seventh Day A the Marshall Art Center in 1975.	spel Center Church in 1936, Ch is 1957, V.F.W. (Veterans of Foi	nar Toe Dance Studio in 1939, the S.O.U.V. (Sons reign Wars) in 1946, D.A.U. Chapter No. 65		
In 1977 the building and grounds were sold by the C society restored the building and opened a historical 1992 the museum was changed to a Civil War Muse	I museum and archives at that lo	ocation. A restored porch was added in 1983. In		
Original source: http://www.marshallmich.com/history/GARHall.shtml				

Inspector's Name



The Grand Army of the Republic Hall. Built in 1903 for the victorious Civil War Veterans, it was sold in 1977 to the Marshall Historical Society for \$1. It was money well spent, for it is now the Society's archival center and War Museum. When the Grove Greene post card company used this 1900's photograph, they were sure to point out in the space for the postage stamp that "this is a real photograph."

# G.A.R. Memorial Hall







## Sold

Stock #: 586312

Type: Postcard

Era: Undivided Back

City: <u>Marshall</u>

State: <u>Michigan (MI)</u>

County: <u>Calhoun</u>

Publisher: <u>Standard Printing Co.</u>

Size:  $3.5" \times 5.5" (9 \times 14 \text{ cm})$ 



























