

NATIONAL ORGANIZATION SONS OF UNION VETERANS OF THE CIVIL WAR CIVIL WAR MEMORIAL ASSESSMENT FORM

Type of Memorial (check all applicable)

☐ Monument ☐ with Sculpture ☐ without Sculpture ☐ with Cannon ☐ standalone Cannon
☐ Historical Marker ☐ Plaque ☒ Other (flag pole, G.A.R. buildings, stained glass windows, etc.)

Note: try to record items separately. Cannons near monuments should be recorded & photographed separately, etc. Thank you.

Affiliation

☐ GAR ☐ MOLLUS ☐ SUVCW ☐ WRC ☐ ASUVCW
☐ LGAR ☐ DUVCW ☐ Other

If known, record name and number of post, camp, corps, auxiliary, tent, circle or appropriate information of other groups:

Shelby County Veterans Association consisting of GAR Post 138 [Brevet Brig. Gen. Cyrus Hall Post] and Cyrus Circle 245 of the Woman's Relief Corps

Original Dedication Date 1898 Please consult any/all newspaper archives for a local paper's article that would have information on the *first* dedication ceremony and/or other facts on the memorial. Please submit a copy of your findings with full identification of the paper & date of publication. Thank you.

Location

1st United Methodist Church

The Memorial is *currently* located at:

Street/Road address or site location 205 W Main St GPS Coordinates N39°24'24.071" W88°47'43.230"

City/Village &/or Township Shelbyville

County Shelby State IL Zip Code 62565

The front of the Memorial faces: ☐ North ☒ South ☐ East ☐ West

Government Body, Agency, or Individual Owner

Name Same Church as above

Dept./Div. _____

Street Address _____

City _____ State _____ Zip Code _____

Contact Person _____ Telephone () _____ ext _____

Is Memorial on the National Register of Historic Places ☐ Yes ☒ No ID # if known _____

For Monuments with/without sculpture:

Physical Details

Material of Monument or base under a Sculpture or Cannon = ☐ Stone ☐ Concrete ☐ Metal ☐ Other

If known, name specific material (color of granite, marble, etc.) _____

Material of the Sculpture ☐ Stone ☐ Concrete ☐ Metal ☐ Other Is it hollow or solid? _____

If known, name specific material (color of granite, marble, etc.) _____

For Historic Marker or Plaque:

Material of Plaque or Historical Marker / Tablet = _____

For Cannons with/without monument:

Material of Cannon = _____ Bronze _____ Iron Type of Cannon (if known) _____

Rifled _____ Yes _____ No

Markings: Muzzle _____ Base Ring/Breech _____

Left Trunion _____ Right Trunion _____

Is inert ammunition a part of the Memorial? _____ Yes _____ No

[For camp/department monuments officer's use: Cannon on list of known ordnance] _____ Yes _____ No

For Other Memorials: (flag pole, G.A.R. buildings, stained glass windows, etc.)What best describes the memorial **Stained Glass Windows**Materials of the Memorial **Glass, Kame and Lead Solder****Complete for All Memorials****Approximate Dimensions** (indicate unit of measure) - taken from tallest / widest points**btwn 18-22 ft** Height **11 ft** Width **2 inch** Depth or _____ Diameter

For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue (service, pose, etc) and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!

Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture)Maker or Fabricator mark / name? If so, give name & location found **No**

Please attach legible photographs of all text &/or Record the text in the space below. Please use the addendum – narrative sheet if necessary.

Shelby County Veteran Association**Left Panel: Cyrus No. 138 [GAR Medal] G.A.R.****Right Panel: W.R.C. - Cyrus No. 245 [WRC Medal]**

Environmental Setting

(The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)

Type of Location

☐ Cemetery ☐ Park ☐ Plaza/Courtyard ☐ "Town Square" ☐ Post Office
☐ School ☐ Municipal Building ☐ State Capitol ☐ Courthouse ☐ College Campus
☐ Traffic Circle ☐ Library Other: CHURCH

General Vicinity

☐ Rural (low population, open land) ☐ Suburban (residential, near city) ☒ Town ☐ Urban / Metropolitan

Immediate Locale (check as many as may apply)

☐ Industrial ☒ Commercial ☒ Street/Roadside within 20 feet ☐ Tree Covered (overhanging branches)
☒ Protected from the elements (canopy or enclosure, indoors) ☐ Protected from the public (fence or other barrier)

Any other significant environmental factor _____

[To detail the condition of a monument used the addendum form for *Monument's Condition*]

Submission of this form requires at least one type of identification so that you may be contacted regarding the information on this form. This information will most likely be in the public domain. Your name is required; please include one (or more) pieces of contact information.

1. If a member of an Allied Order, the name of your camp, auxiliary, tent, circle or corps; along with your department;
2. Physical Address;
3. Phone Number
4. E-Mail address.

By submitting this, you are allowing the posting of this information on the internet.

Inspector Identification _____ Date of On-site Survey 09/22/2026
 Your Name Walt Busch
 Address 1240 Konert Valley Dr
 City Fenton State MO Zip Code 63026
 Telephone () _____ E-Mail _____

Are you a member of the Allied Orders of the G.A.R.? If so, which one?

MO-SUVCW US Grant Camp 68, MO - MOLLUS, Logan's Brigade

Supplemental Background Information

In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Photographs & GPS Co-ordinates are very much desired.

Pages 4 & 5 attached to this electronic file are the Monument's Condition and the Narrative forms. Only the Monument's Condition form is required if you are requesting grant money using form CWM-62 *SUVCW Memorial Grant Application Form and Instructions*.

Please mail (or e-mail pdf, and picture files) to:

Walt Busch, PDC, Chair, 1240 Konert Valley Dr., Fenton, MO 63026, cwmemorials@suvchw.org (314) 630-8407

Thank you for your help, and attention to detail.

Sons of Union Veterans of the Civil War - Civil War Memorials Committee.

>This form may be photocopied.<

©2007-2023 Sons of Union Veterans of the Civil War, a Corporation

SONS OF UNION VETERANS OF THE CIVIL WAR
CIVIL WAR MEMORIAL ASSESSMENT FORM
ADDENDUM – MONUMENT'S CONDITION

Completion of this form is required when requesting grant money using form CWM-62 *SUVCW Memorial Grant Application Form and Instructions*.

Condition Information

Structural Condition (check as many as may apply)

The following section applies to Monuments with Sculpture, and Monuments without Sculpture including the base for Monuments with Cannon. Instability in the sculpture and its base can be detected by a number of factors. Indicators may be obvious or subtle. Visually examine the sculpture and its base.

	Sculpture	Base
If hollow, is the internal support unstable/exposed? (Look for signs of exterior rust)	_____	_____
Any evidence of structural instability? (Look for cracked joints, missing mortar or caulking or plant growth)	_____	_____
Any broken or missing parts? (Look for elements (i.e., sword, musket, hands, arms, etc. - missing due to vandalism, fluctuating weather conditions, etc.)	_____	_____
Any cracks, splits, breaks or holes? (Also look for signs of uneven stress & weakness in the material)	_____	_____

Surface Appearance (check as many as may apply)

	Sculpture	Base
Black crusting	_____	_____
White crusting	_____	_____
Etched, pitted, or otherwise corroded (on metal)	_____	_____
Metallic staining (run-off from copper, iron, etc.)	_____	_____
Organic growth (moss, algae, lichen or vines)	_____	_____
Chalky or powdery stone	_____	_____
Granular eroding of stone	_____	_____
Spalling of stone (surface splitting off)	_____	_____
Droppings (bird, animal, insect remains)	_____	_____
Other (e.g., spray paint graffiti) - Please describe...	_____	_____

There appears to be a mild crusting on the exterior of the windows (Limestone Stain?) and they would probably benefit from a mild cleaning. But generally, they appear in excellent shape.

Does water collect in recessed areas of the Memorial? _____ Yes ☒ No _____ Unable to tell

Surface Coating

Does there appear to be a coating? _____ Yes ☒ No _____ Unable to determine

If known, identify type of coating.

_____ Gilded ☒ Painted _____ Varnished _____ Waxed _____ Unable to determine

Is the coating in good condition? _____ Yes _____ No _____ Unable to determine

Some of the Stained Glass consists of glass painted to create the images

Basic Surface Condition Assessment (check one)

In your opinion, what is the general appearance or condition of the Memorial?

☒ Well maintained _____ Would benefit from treatment _____ In urgent need of treatment _____ Unable to determine

Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on) .

Inspector's Name Walt Busch

Date 09/22/2026

SONS OF UNION VETERANS OF THE CIVIL WAR
CIVIL WAR MEMORIAL ASSESSMENT FORM
ADDENDUM – NARRATIVE

[Generally used to record the text of monuments, but may be used for any other useful information, such as if the monument has been moved or if you have information about the day of dedication. May repeat use of page as often as necessary.]

The Memorial is *currently* located at: 1st United Methodist Church

Street/Road address or site location _____

205 W Main St

GPS Coordinates N39°24'24.071" W88°47'43.230"

City/Village and/or Township Shelbyville

County Shelby

State IL

Zip Code 62565

TEXT

NOTE:

Pictures are not permitted to be used except in this report or by the SUVCW or the Woman's Relief Corps as they deem necessary. Otherwise, permission to use these pictures by any other organization or persons requires the approval of the 1st United Methodist Church, Shelbyville, IL.

The glass records the name of the "Shelby County Veterans Association", this appears to be an umbrella group for the GAR, WRC and others and was active apparently in Shelby County throughout, at least, the 1890s.

Inspector's Name _____ Date _____

First United Methodist Church

PRAYER
WORKS

CHEVROLET
LEACH-WILSON

FIRST
UNITED METHODIST CHURCH

PASTOR
MICHAEL
MADDEN

WORSHIP - 9:00AM
SUNDAY SCHOOL - 10:15AM
205 W MAIN ST





BUILT
1898

METHODIST
CHURCH













Vetters & Son Association
1892



No Use Of These Photos without the Expressed Permission of the
1st United Methodist Church of Shelbyville, IL.



**No Use Of These Photos without the Expressed Permission
of the 1st United Methodist Church of Shelbyville, IL.**



**No Use Of These Photos without the Expressed Permission
of the 1st United Methodist Church of Shelbyville, IL.**



No Use Of These Photos without the Expressed
Permission of the 1st United Methodist Church of
Shelbyville, IL.



No Use Of These Photos without the Expressed
Permission of the 1st United Methodist Church of
Shelbyville, IL.



No Use Of These Photos without the Expressed
Permission of the 1st United Methodist Church of
Shelbyville, IL.

No Use Of These Photos without the Expressed Permission of the 1st United Methodist Church of Shelbyville, IL.





No Use Of These Photos without the Expressed Permission of the 1st United Methodist Church of Shelbyville, IL.

No Use Of These Photos without the Expressed Permission of the 1st United Methodist Church of Shelbyville, IL.



No Use Of These Photos without the Expressed Permission of the 1st United Methodist Church of Shelbyville, IL.



No Use Of These Photos without the Expressed Permission of the 1st United Methodist Church of Shelbyville, IL.

